

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Department of Environmental Quality**  
**Division of Waste Management - Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>COUNTY:</b> Edgecombe <b>PERMIT NO.:</b> CCB0079 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** 9/4/15    **Date of Last Inspection:** Initial Inspection

**FACILITY NAME AND ADDRESS:**

Fountain Industrial Park - Lots 9 & 10  
 4001 College Rd  
 Battleboro, NC 27809

**GPS COORDINATES:** N: 36.00100 W: -77.76248

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Oppie Jordan, (252) 442-6224, [OJordan@econdev.org](mailto:OJordan@econdev.org)

**FACILITY CONTACT ADDRESS:**

Edgecombe County Development Corporation  
 427 Falls Road  
 Rocky Mount, NC 27804

**PARTICIPANTS:**

Shawn McKee, NCDENR, Solid Waste Section  
 Pat Backus, NCDENR, Solid Waste Section  
 David Revoir, Appian Consulting Engineers  
 Donald Perry, City of Rocky Mount  
 Daniel Proctor, E.G. Smithson & Assoc.

**STATUS OF PERMIT:**

Not required - Coal Combustion By-products Structural Fill

**PURPOSE OF SITE VISIT:**

Onsite meeting regarding potential development of the site and inspection to observe current conditions

**STATUS OF PAST NOTED VIOLATIONS:**

None.

**OBSERVED VIOLATIONS**

None.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The site is approximately 30 acres in size and is a portion of a larger parcel. The site is the northern portion of the property currently identified as PIN 3862-61-0266 which totals 66.89 acres. The property is owned by Edgecombe County Development Corporation, PO Box 10, Tarboro NC 27886. A company is interested in purchasing the site and developing it as truck transfer and storage.



2. Coal combustion products (fly ash) was placed on the property prior to January 4, 1994; the effective date for 15A NCAC 13B .1700 – “Requirements for Beneficial Use of Coal Combustion By-Products”. According to a June 14, 1989 letter from ReUse Technology Inc. to the Solid Waste Section, this portion of the Fountain Industrial Park was Phase II and was to be developed using coal ash from Congentrix’s Rocky Mount Plant when it was projected to become operational in late 1990.
3. The quantity of ash onsite is unknown at this time. Based on information contained in the “Geotechnical Engineering Report”, August 14, 2015, conducted by Terracon Consultants, Inc., the depth of fly ash placement on the site varies from 3 feet to 12 feet. The report also indicates that the depth to groundwater at the time of the investigation at the site was approximately 18 feet.
4. The use of fly ash as structural fill on the property does not appear to have been recorded on the deed.
5. The current depth of soil cover is unknown. Much of the site was heavily vegetated at the time of the site visit. Portions of the driveways which were constructed when the site was used for temporary housing following Hurricane Floyd.
6. Control of dust during redevelopment will be necessary to control any offsite migration of fly ash.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

7. Areas not covered by asphalt or concrete during redevelopment should receive soil cover of at least 6 inches and have vegetation established sufficient to prevent erosion.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 919-707-8284

Environmental Senior Specialist  
***Regional Representative***

<b>Sent on:</b> September 25, 2015		Email: X		Hand delivery		US Mail		Certified No. [ ]
---------------------------------------	--	-------------	--	---------------	--	---------	--	-------------------

Copies: David Revoir, Appian Consulting Engineers, drevoir@appianengineers.com  
Ellen Lorscheider, Section Chief, Solid Waste Section  
Ed Mussler, Permitting Branch Head, Solid Waste Section  
Jason Watkins, Field Operations Branch Head, Solid Waste Section  
Dennis Shackelford, Western District Supervisor, Solid Waste Section  
Elizabeth Werner, Permitting Hydrogeologist, Solid Waste Section  
Pat Backus, Permitting Engineer, Solid Waste Section  
Jessica Montie, Compliance Officer, Solid Waste Section