

Scanned By	Date	DOC ID	Permit
Backus	02/08/2016	25597	2602-MSWLF-1981

20 January 2016

Sid Williamson
Solid Waste/Recycling
Environmental Compliance Branch
DPW Bldg 3-1137, Fort Bragg, NC 28310

RE: Longstreet Landfill Methane Vent Repairs

Dear Mr. Williamson:

At the request of Ft, Bragg DPW, the U.S. Army Corps of Engineers, Savannah District (USACE) was contracted to conduct methane vent repairs at the Longstreet Landfill. This letter summarizes the methane vent repair activities.

METHANE VENT REPAIR ACTIVITIES

During landfill maintenance operations two methane vents were damaged on top of Longstreet landfill. On January 7, 2015 USACE crews mobilized to the site to repair the damaged vents.

Prior to repair the vents were measured and inspected to make sure that no debris or soil was blocking the vent screen. Following inspection the vent surface completions were repaired to original working condition. The vent casings were brought up to approximately 4 feet above ground surface and the top casing was situated to prohibit water from entering the vent (candy cane configuration). Following the vent repairs the surrounding soil was graded by hand and grass seed and hay was placed for erosion protection.

Please let me know if you have any questions or concerns. I can be reached at (912) 652-5151 or by e-mail at Jason.T.Lennane@usace.army.mil

Sincerely



Jason T. Lennane, P.G.