

Hazardous Waste Section
File Room Document Transmittal Sheet

17

Your Name: Mark Wilkins
EPA ID: N C D 0 2 4 5 9 9 0 1 1
Facility Name: Former Ashland Greensboro
Document Group: Permit (P)
Document Type: Correspondence (C)
Description: Report - 2nd 2012 semiannual Post Closure Inspection
Date of Doc: 1/10/2013
Author of Doc: Ashland

File Room Use Only

NCD024599011

Date Recieved by File Room:

Month	Day	Year
01	22	13
01	24	13

Date Scanned:

Scanner's Initials: 



Antea USA of North Carolina, Inc.
8008 Corporate Center Drive, Suite 100
Charlotte, North Carolina 28226 USA
www.anteagroup.com

MEMORANDUM

To: Michael Dever, PG
Remediation Project Manager
Ashland Inc.
5200 Blazer Parkway, DS-4
Dublin, Ohio 43017

From: Patrick Storz

Date: January 10, 2013

Re: Semi-Annual RCRA Post-Closure Inspection
Former Ashland Distribution Company Facility
2802 Patterson Street,
Greensboro, North Carolina
Facility ID # NCD 024 599 011

Att: Photographic Log
Post-Closure Inspection Checklist

CC: Mark Wilkins – NCDENR, Jenny Patterson – NCDENR, Bradley Bailey – NCDENR,
Don Malone – ARCADIS, Ryan Gerber – ARCADIS

Purpose

Antea USA of North Carolina, Inc., (Antea USA of NC), on behalf of Ashland Inc. (Ashland), is providing this memo to serve as documentation of the RCRA post-closure inspection completed at the former Ashland facility located at 2802 Patterson Street, Greensboro, North Carolina.

Field Activities

On December 13, 2012, Antea USA of NC conducted an inspection of the concrete RCRA pad located to the rear of the on-site building. The following observations were made during the site visit:

- The facility is enclosed by a fence and the access gate located off Patterson Street was secured by a chain and padlock upon arrival. The cap was in good condition with no observable damage or cracks.
- No standing water was observed on the cap.
- No materials are currently stored on the cap.

Photographs of the pad and the post-closure inspection checklist are included as Attachments 1 and 2, respectively. The inspection checklist also documents conditions of the groundwater remediation system and monitoring well network. If you have any questions, please contact me at (919) 655-4919.

Sincerely,

ANTEA USA OF NC

A handwritten signature in black ink, appearing to read "Patrick Storz".

Patrick Storz
Project Manager






ATTACHMENT 1
PHOTOGRAPHIC LOG
FORMER ASHLAND INC. DISTRIBUTION FACILITY
2802 PATTERSON STREET
GREENSBORO, NORTH CAROLINA
FACILITY ID # NCD 024 599 011

Photo 1:
East view of RCRA
pad.



Photo 2:
West view of RCRA
pad.



ATTACHMENT 2
Post-Closure Inspection Checklist
Former Underground Hazardous Waste Tank
Ashland Chemical, Inc
Greensboro, North Carolina

Inspector: Jason Millington

Date: 12/13/2012

Signature: 

<u>Item</u>	<u>Condition</u>	<u>Maintenance Needs</u>	<u>Comments</u>
RCRA Concrete Pad	<u>Good</u>	<u>None</u>	
Remediation System	<u>Good</u>	<u>None</u>	
Recovery Wells	<u>Good</u>	<u>Remove fines (bottom)</u>	<u>RW-1, RW-3</u>
Monitoring Wells	<u>Good</u>	<u>Pad repair well plug →</u>	<u>MW-12/12D MW-29S</u>
Site Security	<u>Good</u>	<u>small hole in fence</u>	<u>NE corner of prop. by rail tracks</u>

Other Notes

- hole in fence repaired on 12/17/12
- well plug on MW-29S replaced with Fernco plug for clearance purposes

