

**Photograph 1:**

View front entrance to Subject Property from Wake Forest Road. Property is fenced off for safety and to deter trespassers. Partial view of the northeast portion of the property that is currently used as a commuter parking area.



**Photograph 2:**

View from driveway accessing property off of Wake Forest Road facing west.



**Photograph 3:**

View of former facility parking lot along Wake Forest Road on the southwestern portion of the property accessed from Wake Forest Rd driveway. This area is located outside of the secured fenced portion of the property.



**Photograph 4:**

View of former facility parking lot along Wake Forest Road on the northwestern portion of the property accessed from Wake Forest Rd driveway. This area is located outside of the secured fenced portion of the property.



**Photograph 5:**

View of the concrete pad and former building location facing southwest from the Wake Forest Rd driveway.



**Photograph 6:**

View of the concrete pad and former building location facing south from the former main entrance of the building along Wake Forest Rd.



**Photograph 7:**

View of the concrete pad and former building location facing southeast from the former main entrance of the building along Wake Forest Rd.



**Photograph 8:**

View of the concrete pad and former building location facing east from the former main entrance of the building along Wake Forest Rd. Recycled crushed concrete building material is shown stockpiled on the site. A portion of this crushed concrete building material was used as backfill during the soil blending in-situ remediation activities.



**Photograph 9:**

View of the concrete pad and former building location facing northeast from the former main entrance of the building along Wake Forest Rd.



