

PHOTOGRAPHIC RECORD



Photograph 1 - Subject Site - East Side



Photograph 2 - Subject Site - West Side



Photograph 3 - Subject Site - Southeast Side



Photograph 4 - North Side



Photograph 5 - Subject Site - Northwestern Loading Dock



Photograph 6 - Subject Site - 1st Floor Interior

PHOTOGRAPHIC RECORD



Photograph 7 - Subject Site - Typical Interior Hallway



Photograph 8 - Subject Site 1 of 2 Elevators




Photograph 9 - Subject Site - Typical Available Office Space



Photograph 10 - Subject Site - Tar and Gravel Roof



Photograph 11 - Subject Site - Rubber Membrane Roof



Photograph 12 - Drop Inlet (Loading Dock)

PHOTOGRAPHIC RECORD



Photograph 13 – Drop Inlet Eastern Side of Property



Photograph 14 – Northern Adjacent Property



Photograph 15 – Northern Adjacent Property (Old Salem Visitors Center)



Photograph 16 – Southern Adjacent Property (Delco)



Photograph 17 – East View Across Old Salem Road



Photograph 18 – West View Across Marshall Street, SW

PHOTOGRAPHIC RECORD



Photograph 19 - Drum - Biocide




Photograph 20 - Wall Mounted Transformer



Photograph 21 - Wall Mounted Transformer



Photograph 22 - Subject Site - Fluorescent Light



Photograph 23 - Steel Covered Process Drain



Photograph 24 - Concrete Filled Process Drain or Scale

PHOTOGRAPHIC RECORD



Photograph 25 - Process Drain



Photograph 26 - Process Drain



Photograph 27 - Sewer Manway



Photograph 28 - Roof Tarp



Photograph 29 - Suspect ACM Pipe Wrap



Photograph 30 - Suspect ACM Pipe Wrap