



**Photograph 1: Eastern wall or eastern warehouse,
facing south along access road for Eden Street**



Photograph 2: Vent pipe along eastern wall of eastern warehouse



Photograph 3: Location of UST - beneath access road for Eden Street near the southeastern corner of the site



Photograph 4: Southern portion of site



**Photograph 5: Rear of eastern warehouse.
Note water supply well pump house in foreground**



Photograph 6: Dumpster near southwestern corner of eastern warehouse



**Photograph 7: Western warehouse and gravel-lined parking area.
Note grassed area in background is location of buried asbestos containing materials**



Photograph 8: Location of buried asbestos containing materials



Photograph 9: Vacant space in western warehouse



Photograph 10: Floor drain in western warehouse



Photograph 11: Typical storage space in eastern warehouse



Photograph 12: Three 55-gallon oil drums located in paint recycling business' area



Photograph 13: Numerous containers in paint recycling business' area



Photograph 14: Spray paint storage in Peak Fitness' area



Photograph 15: Typical storage space in eastern warehouse



Photograph 16: Typical storage space in eastern warehouse