



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer	<input checked="" type="checkbox"/>	Compost		SLAS	<b>COUNTY:</b> Lenoir <b>PERMIT NO.:</b> 54-08T <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** February 9, 2012    **Date of Last Inspection:** October 13, 2011

**FACILITY NAME AND ADDRESS:**

Onslow Container Service  
P.O. Box 9  
Deep Run, NC 28525  
NCSR 1511/ Bland Howell Rd.

**GPS COORDINATES:** N: 35.17373    W: 77.69637

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Al Hill, Owner 252 527 5040 Fax 252 523 0651  
Email: [ahill@onslowcontainer.com](mailto:ahill@onslowcontainer.com)

**FACILITY CONTACT ADDRESS:**

Same as above

**PARTICIPANTS:**

Wes Hare, NCDENR Solid Waste Section

**STATUS OF PERMIT:**

Issued July 7, 2011; Expires December 19, 2016

**PURPOSE OF SITE VISIT:**

Partial Audit

**STATUS OF PAST NOTED VIOLATIONS:**

Not Applicable

**OBSERVED VIOLATIONS**

None

**ADDITIONAL COMMENTS**

1. The service area for this facility is Craven, Duplin, Lenoir, Pitt and Wayne Counties.
2. The wind blown was minimal and is being managed well.
3. The signage at the front gate is as required.
4. The tipping floor is washed with a hot water pressure washer. The facility is currently in the process of replacing the tipping floor.
5. Fire extinguishers are inside the transfer station and were reading a full charge.
6. Lead acid batteries, white goods, and tires are not accepted at this facility.
7. The waste is being transferred to Republic in Bertie County.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2


8. Leachate is currently being collected in a 2,000 gallon tank and pumped as needed. The leachate is hauled to the City of Kinston's WWTP for proper disposal.
9. All access roads are paved with no erosion problems.
10. The facility is very well managed.
11. Pictures taken during the visit are as follows:



Tipping floor is kept clean.



Owner is replacing the floor in sections.



Truck bay is kept clean.



Leachate tank.

Please contact me if you have any questions or concerns regarding this inspection report.

---

Phone: 910.796.7405

Wes Hare  
Environmental Senior Specialist  
**Regional Representative**



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>Sent on: 2/9/12</b>	<input checked="" type="checkbox"/>	Email	<input type="checkbox"/>	Hand delivery	<input type="checkbox"/>	US Mail	<input type="checkbox"/>	Certified No. [ ]
------------------------	-------------------------------------	-------	--------------------------	---------------	--------------------------	---------	--------------------------	-------------------

Copies: \*Dennis Shackelford, Eastern District Supervisor  
\*Shawn McKee, Compliance Officer