



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>										
Lined MSWLF		LCID		YW	<b>X</b>	Transfer	<b>X</b>	Compost	SLAS	<b>COUNTY:</b> Currituck <b>PERMIT NO.:</b> 2703T <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods	<b>X</b>	Incineration		T&P	FIRM	
CDLF		Tire T&P / Collection	<b>X</b>	Tire Monofill		Industrial Landfill		DEMO	SDTF	

**Date of Site Inspection: March 6, 2014**

**Date of Last Inspection: January 23, 2014**

**FACILITY NAME AND ADDRESS:**

Currituck County Transfer Station  
 216 Airport Rd.  
 Maple, North Carolina 27956

**GPS COORDINATES:** N: 36.39700 E: 76.00140

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Brenda McQueen	Stacey R. Bowen
Telephone: (o) 252 232 2504 (c) 252 599 0673	(c) 252 943 3702
Email address: <a href="mailto:Brenda.McQueen@CurrituckCountyNC.gov">Brenda.McQueen@CurrituckCountyNC.gov</a>	<a href="mailto:sbowen@bowencompany.us">sbowen@bowencompany.us</a>
Fax: 252 232 3298	

**FACILITY CONTACT ADDRESS:**

Brenda McQueen	Stacey R. Bowen
Currituck County Public Works	Bowen Company, Inc.
PO Box 38	P.O. Box 394
Currituck, NC 27929	Belhaven, NC 27810

**PARTICIPANTS:**

Ben Barnes NCDENR-Solid Waste  
 Brenda McQueen Currituck Co. Public Works Director

**STATUS OF PERMIT:**

Active, permit issued on December 12, 2008 and due for review on or about December 12, 2013. No later than July 12, 2013 the operator must submit a request for permit review to the Division.

**PURPOSE OF SITE VISIT:**

Comprehensive inspection

**STATUS OF PAST NOTED VIOLATIONS:**

NONE

**OBSERVED VIOLATIONS**

NONE

# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

Page 2 of 5

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

### ADDITIONAL COMMENTS

1. The permit, Ops Plan, and Contingency Plan were on site and available for review. The request for permit renewal was submitted to the Division on June 24, 2013.
2. The normal operating hours are 8am to 4:15 M-S from May 1 to September 30. The rest of the year Saturday's hours are 8am to 12pm
3. The service area is Currituck County and all communities within the county.
4. Waste from the facility is transported to East Carolina Regional Landfill permit # 08-03 in Bertie Co. NC.
5. Scrap tires, yard waste and white goods collection sites are located within the facility.
6. White goods need better management. **Freon containing white goods should be stacked neatly and marked for Freon removal.** Freon removal is being handled by Murky Waters Shawboro, NC.
7. Yard waste facilities shall follow the time and temperature requirements listed in 15A NCAC 13B .1406(10) for all yard trash feed stocks. The temperature requirements include the compost process being maintained at or above 55 degrees Celsius (131 degrees F) for 3 days and aerated to maintain elevated temperatures. Yard trash is defined within 130A-290(a)(45) as solid waste consisting solely of vegetative matter resulting from landscaping maintenance. Leaves from landscaping maintenance and grass clippings are considered yard trash.
8. Scrap tires are being stored in trailers. Waste Management is handling transportation of the tires.
9. Insulation has been recently removed from the ceiling of the building. The need for this was noted in the previous inspection report.
10. **There was much blown waste around the facility grounds. It could not be determined if this was from one day's operation or if the grounds had not been cleaned for several days. Blown litter must be removed daily.**
11. The floors walls and ceilings of the building were generally clean.
12. The ventilation fans needed repair the louvers were damaged.
13. Fire suppression is by three fire extinguishers all charged and a one inch hose bib.
14. According to the Ops Plan waste is to be screened as the waste is dumped on the tipping floor.
15. The tipping floor is to be cleaned at the end of each operating day. The Ops plan indicates that wash water will be swept towards the floor drains in the lower level of the facility. Leachate is held in holding tanks and pumped out as needed.
16. Signage is adequate.

Please contact me if you have any questions or concerns regarding this inspection report.

*Ben Barnes*

Phone: 252 236 4453 email: [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

*Ben Barnes*  
Environmental Senior Specialist  
**Regional Representative**

Sent on: March 19, 2014	X	Email		Hand delivery		US Mail	Certified No. [ ]
-------------------------	---	-------	--	---------------	--	---------	-------------------

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 5

Copies: Dennis Shackelford, Eastern District Supervisor  
Jessica Monte, Compliance Officer



Fencing around the dumping area of the facility needs repair. McQueen indicated that a repair order has been submitted.



The downspout for the gutter system has become dislodged and is allowing runoff from the roof to wash soil away the anchor from the fencing around the turn area.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 4 of 5



Other repairs needed at the front of the facility



Repairs are needed for the siding on the back wall.



Much waste material was scattered around the grounds. Insulation removed from the roof had been left piled outside of the building for several days.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 5 of 5



Much blown waste was observed outside of the building.



White goods area, also showing blown waste