03-01
Ashe Co LF
5/3/95
site visit



MW's not grouted - need replacing - no MW records

Leachate seeps noticed during past insp. on east side of LF (per B. Rockett)