RECORD OF COMMUNICATION

☑ PHONE CALL ☐ DISCUSSION ☐ FIELD TRIP ☐ CONFERENCE

☐ OTHER (SPECIFY)

(Record of item checked above)

TO:	FROM:	DATE
GRAY STEPHENS	LLOYD COOK WAYNE CO. (96-01)	3/9/90 TIME 2:15

SUBJECT

SURFACE WATER MONITORING, GROUND WATER (WELL LOCATIONS) MONITORING

SUMMARY OF COMMUNICATION

— HAVING TROUBLE FINDING STREAM SAMPLES BECAUSE OF BEAVER. DAMS?

= WILL TRY TO FIND SAMPLE BELOW DAM.

— ASKED IF COULD RELOCATE OBSTRUCTED MONITORING WELL, SINCE IT IS ALMOST IN THE WASTE FIELD, AND USE AS UPGRAD. WELL..?

= SUGGESTED MAY BE ABLE TO ONLY SLIGHTLY MOVE WELL SINCE IT WAS ACTUALY A DWN GRADIENT WELL. AND IT WOULD BE BETTER TO RELOCATE EXISTING WELL # ALONG THE ROAD, TO A POINT MORE UPGRADIENT, TOWARDS THE CORNER OF THE PROPERTY.

= HE WILL DISCUSS THIS WITH THE CONSULTING ENGINEER.

CONCLUSIONS, ACTION TAKEN OR REQUIRED

Cawner Johnson

Fac/Perm/Co ID# 96-01 | Date 1/8/13 | Doc ID# | DIN

INFORMATION COPIES

TO:

EPA Form 1300-6 (7-72)