60-13

8-16-00

ENVIRO-PRO
PROFESSIONAL CORPORATION

September 1, 2000

Be 6 14 10

-Data OK
-no field measurements.

Mr. Larry Griffin
North Mecklenburg Landfill
15300 Holbrooks Road
Huntersville, NC 28078

RE: Semi-annual Monitor Well Sampling Results
North Mecklenburg Landfill
Huntersville, NC
Project No. EP-1217

Dear Mr. Griffin:

Enviro-Pro, P.C. is pleased to submit this report which describes the field sampling activities and summarizes the semi-annual monitor well analytical results for the subject site.

Field Sampling Activities

On August 16, 2000, Enviro-Pro personnel collected groundwater samples from on-site perimeter monitor wells MW-1, MW-4, MW-5, MW-6, MW-10 and MW-11. The approximate locations of these wells are indicated on Figure 1.

The procedures for groundwater measurement and sampling were as follows:

1) Initially, the monitor well caps were removed to allow the groundwater levels to equilibrate to the ambient atmospheric pressure. Next, the depth to groundwater from a measuring point on top of the well casing was recorded. Water level measurements were obtained using an electronic water level meter. The water level probe was decontaminated between monitor wells with deionized water and isopropyl alcohol.

2) At least three well volumes were removed from each monitor well to purge stagnant water and to ensure that fresh formation water would be sampled. Purging was conducted using dedicated disposable Teflon bailers.

15101 Regena Lane • Charlotte, NC 28278 • (704) 583-0075 • FAX (704) 583-2673

3) Each well was then sampled utilizing laboratory prepared containers, labeled, and packed on ice in a portable cooler for shipment to Prism Laboratories, Inc., a North Carolina-certified laboratory located in Charlotte, North Carolina. Chain-of-custody documentation is included with the analytical reports in Appendix A.

4) Quality assurance/quality control (QA/QC) measures in the field included wearing disposable sample gloves during sampling activities and changing them between sample locations to protect the groundwater samples from cross-contamination. Analytical QA/QC included a trip blank analyzed for volatile organic compounds (EPA Method 8260).

The field information obtained is summarized on the Well Development, Purge, and Sample Record included as Appendix B. Groundwater levels decreased in four of the wells, from 0.33 foot in well MW-1 to 2.08 foot in well MW-10 since the previous sampling event on March 9, 2000. The average decrease in water levels for the four wells was slightly over one foot. The water levels in MW-6 and MW-11 increased 0.31 and 0.62 foot, respectively, over this same period of time.

Laboratory Test Results

In accordance with regulatory requirements, the six monitor well samples were analyzed for the eight RCRA metals and volatile organic compounds (VOCs) via EPA Method 8260 by Prism Laboratories. Laboratory data sheets are attached as Appendix A, with a summary of groundwater analytical results presented in Table 1.

Laboratory test results indicated that no metals or VOC compounds were present above their respective regulatory limits in any of the monitor well or QA/QC samples tested.

Enviro-Pro appreciates the opportunity to continue to provide our environmental services on your project. Please contact me at (704) 583-0075 if you have any questions concerning this report or when we can be of further service.

Sincerely,
ENVIRO-PRO, P.C.

Thomas H. Bolyard

Thomas H. Bolyard, P.G.
Senior Hydrogeologist

TABLE 1

SUMMARY OF GROUNDWATER ANALYTICAL RESULTS
North Mecklenburg Landfill
Huntersville, North Carolina
August 16, 2000 Sampling Event

	Sample I.D.							
Parameter	MW-1	MW-4	MW-5	MW-6	MW-10	MW-11	Trip Blank	NCAC 2L Standard
Arsenic	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.05
Barium	0.073	0.10	0.20	0.027	0.072	0.15	NT	2.0
Cadmium	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.005
Chromium	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.05
Lead	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.015
Mercury	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.0011
Selenium	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.05
Silver	BDL	BDL	BDL	BDL	BDL	BDL	NT	0.018
All 8260 Compounds	BDL	BDL	BDL	BDL	BDL	BDL	BDL	

Notes: BDL = Below Detection Limits
NT = Not Tested
All Metal Results Are Presented in Parts Per Million

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-1
Prism Sample ID: AB78718
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:10
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:26	MSP
BARIUM	0.073	mg/L	0.010	6010B	8/22/2000 20:26	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:26	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:26	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:26	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:26	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:26	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 17:43	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-1
Prism Sample ID: AB78718
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:10
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-1
Prism Sample ID: AB78718
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:10
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 12:43	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 12:43	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 12:43	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 12:43	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-4
Prism Sample ID: AB78719
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 16:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:31	MSP
BARIUM	0.10	mg/L	0.010	6010B	8/22/2000 20:31	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:31	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:31	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:31	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:31	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:31	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 17:55	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-4
Prism Sample ID: AB78719
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 16:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-4**
Prism Sample ID: **AB78719**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 16:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 13:23	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 13:23	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 13:23	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 13:23	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-5
Prism Sample ID: AB78720
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:30
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:35	MSP
BARIUM	0.20	mg/L	0.010	6010B	8/22/2000 20:35	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:35	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:35	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:35	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:35	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:35	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 18:00	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-5
Prism Sample ID: AB78720
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:30
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-5**
Prism Sample ID: **AB78720**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:30
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 17:35	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 17:35	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 17:35	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 17:35	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 - Toll Free Number: 1-800/529-6364 - Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-6**
Prism Sample ID: **AB78721**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:50
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:40	MSP
BARIUM	0.027	mg/L	0.010	6010B	8/22/2000 20:40	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:40	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:40	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:40	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:40	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:40	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 18:04	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-6
Prism Sample ID: AB78721
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:50
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-6
Prism Sample ID: AB78721
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:50
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 18:16	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 18:16	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:16	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 18:16	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-10
Prism Sample ID: AB78722
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:45	MSP
BARIUM	0.072	mg/L	0.010	6010B	8/22/2000 20:45	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:45	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:45	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:45	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:45	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:45	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 18:16	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-10**
Prism Sample ID: **AB78722**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-10
Prism Sample ID: AB78722
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:00
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 18:56	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 18:56	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 18:56	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 18:56	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 Toll Free Number: 1-800/529-6364 Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-11**
Prism Sample ID: **AB78723**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:40
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
METALS DIGESTION METHOD GW	Completed			3010	8/18/2000 09:45	PRF
ARSENIC	Not detected	mg/L	0.010	6010B	8/22/2000 20:50	MSP
BARIUM	0.15	mg/L	0.010	6010B	8/22/2000 20:50	MSP
CADMIUM	Not detected	mg/L	0.001	6010B	8/22/2000 20:50	MSP
CHROMIUM	Not detected	mg/L	0.005	6010B	8/22/2000 20:50	MSP
LEAD	Not detected	mg/L	0.005	6010B	8/22/2000 20:50	MSP
SELENIUM	Not detected	mg/L	0.010	6010B	8/22/2000 20:50	MSP
SILVER	Not detected	mg/L	0.005	6010B	8/22/2000 20:50	MSP

MERCURY, TOTAL	Less than	mg/L	0.0002	EPA 245.1	8/22/2000 18:21	PRF
MERCURY DIGESTION	Completed			EPA 245.1	8/21/2000 10:30	PRF
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **MW-11**
Prism Sample ID: **AB78723**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:40
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: MW-11
Prism Sample ID: AB78723
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000 15:40
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 19:37	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 19:37	MP
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 19:37	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 19:37	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: NMLF
Customer Sample ID: TRIP BLANK
Prism Sample ID: AB78724
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
BENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
BROMOBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
BROMOCHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
BROMODICHLOROMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
BROMOFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
BROMOMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
N-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
SEC-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TERT-BUTYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
CHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
CHLORODIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
CHLOROETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
CHLOROFORM	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
CHLOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
2-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
4-CHLOROTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2-DIBROMO-3-CHLOROPROPANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
1,2-DIBROMOETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
DIBROMOMETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,3-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,4-DICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
DICHLORODIFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
1,1-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2-DICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
CIS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TRANS-1,2-DICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,3-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **TRIP BLANK**
Prism Sample ID: **AB78724**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
2,2-DICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
ETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
HEXACHLOROBUTADIENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
ISOPROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
P-ISOPROPYLTOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
METHYLENE CHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
NAPHTHALENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
N-PROPYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
STYRENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1,1,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1,2,2-TETRACHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TETRACHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TOLUENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2,3-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2,4-TRICHLOROBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1,1-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,1,2-TRICHLOROETHANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TRICHLOROETHENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
TRICHLOROFLUOROMETHANE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
1,2,3-TRICHLOROPROPANE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,2,4-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
1,3,5-TRIMETHYLBENZENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
VINYL CHLORIDE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
TOTAL XYLENES	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
cis-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
trans-1,3-DICHLOROPROPENE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
ACETONE	Not detected	ug/L	50	SW846-8260	8/23/2000 20:17	MP
2-BUTANONE (MEK)	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
CARBON DISULFIDE	Not detected	ug/L	50	SW846-8260	8/23/2000 20:17	MP

449 Springbrook Road ▲ P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 - Toll Free Number: 1-800/529-6364 ▲ Fax: 704/525-0409

Lab Report

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

8/28/2000

Enviro-Pro, P.C.
Attn: Tom Bolyard
15101 Regena Lane
Charlotte, NC 28278

Customer Project ID: **NMLF**
Customer Sample ID: **TRIP BLANK**
Prism Sample ID: **AB78724**
Login Group: 2580G7
Sample Collection Date/Time: 8/16/2000
Lab Submittal Date/Time: 8/16/2000 16:45

The following analytical results have been obtained for the indicated sample which was submitted to this laboratory

TEST PARAMETER	TEST RESULT	UNITS	REPORTING LIMIT	METHOD REFERENCE	DATE/TIME STARTED	ANALYST
CARBON TETRACHLORIDE	Not detected	ug/L	5.0	SW846-8260	8/23/2000 20:17	MP
2-CHLOROETHYLVINYLETHER	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
2-HEXANONE	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP
4-METHYL-2-PENTANONE (MIBK)	Not detected	ug/L	10	SW846-8260	8/23/2000 20:17	MP

Sample Comments:

Angela D. Overcash, V.P. Laboratory Services

PRISM LABORATORIES, INC.

Full Service Analytical & Environmental Solutions

CHAIN OF CUSTODY RECORD

PAGE 1 OF 1 QUOTE #

449 Springbrook Road ▲ Charlotte, NC 28217
P.O. Box 240543 ▲ Charlotte, NC 28224-0543
Phone: 704/529-6364 ▲ Fax: 704/525-0409

LAB USE ONLY

	YES	NO	N/A
Samples INTACT upon arrival?	✓		
Received ON WET ICE? Temp 5°	✓		
PROPER PRESERVATIVES indicated?	✓		
Received WITHIN HOLDING TIMES?	✓		
CUSTODY SEALS INTACT?			✓
VOLATILES rec'd W/OUT HEADSPACE?	✓		
PROPER CONTAINERS used?	✓		

PRESS DOWN FIRMLY - 3 COPIES

Client: Enviro-Pro, P.C.
Physical Address: 15401 Regena Ln. Charlotte, NC 28278
Phone: 583-0075 Fax:
P.O.#/Billing Reference:
Project Name: NMLF

REPORT TO: Name: T. Bolyard
Address: Same
BILL TO: Name: Same
Address:
Requested Due Date: 2 wks

(SEE REVERSE SIDE FOR RUSH TURNAROUND FEES)

State Certification Requested: NC ✓ SC ___ Other ___ NA ___
Water Chlorinated: Yes ___ No ___ NA ✓
Sample Iced Upon Collection: Yes ✓ No ___

CLIENT SAMPLE DESCRIPTION	DATE COLLECTED	TIME COLLECTED MILITARY HOURS	MATRIX (SOIL, WATER OR SLUDGE)	SAMPLE CONTAINER *TYPE SEE BELOW	NO.	SIZE	PRESERVATIVES	8260	RCRA Metals					REMARKS	SUB LAB CERT. ID NO.	PRISM LAB ID NO.
MW-1	8-16-00	15:10	H_2O	VOA/P	2/1	40ml/500ml	HCL/HNO_3	✓	✓							78718
MW-4		16:00						✓	✓							78719
MW-5		15:30						✓	✓							78720
MW-6		15:50						✓	✓							78721
MW-10		15:00						✓	✓							78722
MW-11		15:40						✓	✓							78723
Trip Bl.				VOA	2	40ml	HCL	✓								78724

Sampler's Signature: T. Bolyard
Sampled By (Print Name): T. Bolyard
Affiliation: Enviro-Pro

Relinquished By: (Signature) T. Bolyard	Received By: (Signature)	Date 8/16/00	Military/Hours
Relinquished By: (Signature)	Received By: (Signature)	Date	
Relinquished By: (Signature)	Received For Prism Laboratories By: Kathryn a King	Date 8/16/00	1645
Method of Shipment		Log-In Group No. 258067	

Additional Comments

NPDES NC ___ SC ___ OTHER ___ UST: NC ___ SC ___ OTHER ___ GROUNDWATER: NC ___ SC ___ OTHER ___ DRINKING WATER: NC ___ SC ___ OTHER ___ SOLID WASTE: NC ___ SC ___ OTHER ___ OTHER: NC ___ SC ___ OTHER ___

*CONTAINER TYPE CODES: A = Amber C = Clear G = Glass P = Plastic; TL = Teflon-Lined Cap VOA = Volatile Organics Analysis (Zero Head Space)

SEE REVERSE FOR TERMS & CONDITIONS

WELL DEVELOPMENT, PURGE, AND SAMPLE RECORD

LIENT: North Mecklenburg Landfill
OCATION: 15300 Holbrooks Rd.
ROJECT NAME/DESCRIPTION: N. Meck. LF
ATE OF WATER LEVEL MEASUREMENTS: 8-16-00

DEVELOP:
PURGING: ✓
SAMPLING: ✓

PROJECT NO.: EP-1217
PROJ. MGR.: THB
CHECKED BY:
PREPARED BY: THB

Sample ID	A Well No.	B Sample Date	C Time (hrs)	D Well Depth (ft)	E MP Elevation (ft)	F Depth to Water (ft-bmp)	(E - F) = G Water Level Elevation (ft)	(D - F) = H Hgt. of Water Col. (ft)	I Volume of Water (gal)*	Vol. of Water Pgd. (gal)**	Temp. (°C)	Specific Cond. (umhos)	pH	Turbidity or Appearance
	MW-1	8-16-00	15:10	25		14.77		10.23	1.7	5.0				
	MW-4	"	16:00	42		34.32		7.68	1.3	4.0				
	MW-5	"	15:30	55		29.12		25.88	4.2	13				
	MW-6	"	15:50	67		59.50		7.50	1.3	4.0				
	MW-10	"	15:00	19		12.75		6.25	1.0	3.0				
	MW-11	"	15:40	80		68.28		11.72	1.9	6.0				

Comments:

*To calculate volume of water in the well multiply "H" by 0.163 for a 2" well, 0.652 for a 4" well, or 1.469 for a 6" well.

**To calculate purge volume, multiply "I" by the desired number of well volumes (e.g., 3 to 5).

(e.g., after each well volume).