



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	X	COUNTY: Wilson PERMIT NO.: SLAS-98-11 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF		

Date of Site Inspection: 1/4/2012 **Date of Last Inspection:**

FACILITY NAME AND ADDRESS:

*Allen Roberson
 Roberson Septic Service
 6049 US 301 N.
 Elm City, NC 27822*

GPS COORDINATES:

N: 35.69186

W: -77.79693

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Allen Roberson*
Telephone: *252-236-5725*
Email address: *allen@robersonsepticsevice.com*
Fax: *252-236-3813*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb, Michael Scott, Tony Gallagher, and Allen Roberson*

STATUS OF PERMIT: *Proposed*

EXPIRES: *6/25/2013*

PURPOSE OF SITE VISIT: *Initial*

STATUS OF PAST NOTED VIOLATIONS:

OBSERVED VIOLATIONS:

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Septage Land Application signage present near the proposed tank location. Signage needs to be moved back up the path prior to access to the first field.
2. Access road was in good shape.
3. Site evaluation performed. Markers will need to be installed where orange flags are placed.
6. No crop had been planted.
9. Setbacks were measured off. There is a 500 ft setback to the well at an old abandoned house as you enter the site. We will need documentration of the abandoned well near the detention tank location.
11. Site was evaluated for the suitability of land application of septage. Areas suitable were mapped with a Trimble GPS unit. Nutrient Management Plan will need to be admended to include a crop for Field 2. Field 1 will not be permitted due to its' small size (1.3 acres).

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb

Regional Representative

Phone: (919) 707-8283.

Sent on: 8-6-12		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	---	---------	--	-------------------