

5705Permit2002 - Batch No. _____

/Macon (i. 57-05

2002

A

57052002

SWC 57-05

B & B Concrete Prods.

B&B CONCRETE PRODUCTS, INC.

1629 Georgia Highway

Franklin NC 28734

Ph. 828 524 6483

Fax 828 524 5194



May 17, 2002

Mr. Ted Lyons
Division of Solid Waste Management
401 Oberlin Road-Suite 150
Raleigh NC 27605

Dear Mr. Lyons:

The results of the man made inerts test as of May 17, 2002 are as follows:

5 gallon bucket – 17.5 lbs – 2.5 lbs for bucket = 15 lbs.

No man made inerts found.

Also, Dr. Rubin did a fecal coliform analysis and found (lower than 4 per gram
(whatever that means))

Sincerely,

B&B CONCRETE PRODUCTS, INC.

Nelson Bates

Nelson W. Bates, President

NWB/wv

Cc: Jim Patterson
NC Solid Waste Section
852 Merrimon Avenue
Asheville NC 28804

B&B CONCRETE PRODUCTS, INC.

1629 Georgia Highway

Franklin NC 28734

Ph. 828 524 6483

Fax 828 524 5194

May 17, 2002

Mr. Ted Lyons
Division of Solid Waste Management
401 Oberlin Road - Suite 150
Raleigh NC 27605

Dear Mr. Lyons:

We are listing below information on composting project.

| | | |
|------------------|---|--|
| June 31, 2001 | 24 yds wood waste 12 yds rest. grease | 136 degree average temp. Pile turned 5 times |
| July 20, 2001 | 24 yds wood waste 12 yds rest. grease | 141 degrees average temp. Pile turned 6 times |
| August 30, 2001 | 24 yds. wood waste 12 yds. rest grease | 134 degrees average temp Pile turned 7 times |
| November 2, 2001 | 30 yds. wood waste 12 yds rest grease | 144 degrees average temp Pile turned 8 times |
| December 3, 2001 | 30 yds. wood waste 12 yds rest waste | 136 degrees average temp Pile turned 6 times |
| Feb. 5, 2002 | 30 yds. wood waste 12 yds. rest grease | 129 degrees average temp Pile turned 6 times |
| April 28, 2002 | 30 yds. wood waste 14 yds. rest grease | 135 degrees average temp Pile turned 6 times |

Sincerely,

B&B CONCRETE PRODUCTS, INC.

Nelson Bates

Nelson W. Bates, President

Copy: Jim Patterson
852 Merrimon Avenue
Asheville NC 28804