



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	COUNTY: Nash PERMIT NO.: CCB0062 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P	FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: May 19, 2014

Date of Last Inspection: 12/27/2009

FACILITY NAME AND ADDRESS:

Turn Key Contractors
 North Side Business Park
 End of Business Park Drive
 Rocky Mount, North Carolina

GPS COORDINATES: N: 36.00902 W: 77.7786

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Bobbie Davis
 Telephone: 252 977 6680 X31
 Email address: rdavis1352@aol.com

FACILITY CONTACT ADDRESS:

Wright Development Corporation
 P.O. Box 7515
 Rocky Mount, North Carolina 27804

PARTICIPANTS:

Ellen Lorscheider, NCDENR-SWS Special Waste Branch Head
 Ben Barnes, NCDENR-SWS Environmental Senior Specialist

STATUS OF PERMIT:

CCB fill site, no permit required

PURPOSE OF SITE VISIT:

Inspection of closed CCB fill site

STATUS OF PAST NOTED VIOLATIONS:

NONE

OBSERVED VIOLATIONS

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS:

1. Robbie Davis is the owner of Wright Development Corp.
2. The CCB was originally used to build a berm to provide a visual barrier between residences located on Bishop Rd. and industries located at North Side Business Park.
3. The CCB generator was Cogentrix of Rocky Mount, P.O. Box 370 Battleboro, North Carolina 27809
4. There is a Dominion Power easement located between the home sites on Bishop Rd. and the berm. Mr. Davis indicated in a conversation with me on January 7, 2010 that the CCB was removed from the site many years ago. It was discovered that the property lines of the home sites on Bishop Rd went through the area of the power line to the property line for North Side Business Park rather than stopping on the other side. This resulted in ash being deposited within 25 feet of the property lines between the home sites located on Bishop Rd. and North Side Business Park. The ash was removed and replaced with soil according to Mr. Davis. A review of the Nash Co. GIS website supported this assertion and indicated that the property lines from the Bishop Rd home sites did join the property lines with North Side Business Park.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 252 236 4453 email: ben.barnes@ncdenr.gov

Ben Barnes
Environmental Senior Specialist
Regional Representative

Sent on: July 18, 2014		Email		Hand delivery	X	US Mail		Certified No. []
------------------------	--	-------	--	---------------	---	---------	--	-------------------

Copies: Jason Watkins, Field Operations Branch Head
Ellen Lorscheider, Special Waste Branch Head
Dennis Shackelford, Eastern District Supervisor
Jessica Montie, Compliance Officer