



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Harnett PERMIT NO.: SLAS 43-03 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

Date of Site Inspection: 10/24/2014

Date of Last Inspection: 3/26/2014

FACILITY NAME AND ADDRESS:

Gerald Temple Septic Tank Service
 1636 Temple Road
 Bunnlevel, NC 28323

GPS COORDINATES: N: 35.31837 E: -78.86139

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Gerald Temple
 Telephone: (910) 893-4953
 Email address: N/A
 Fax: (910) 893-3184

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Active- permit expires April 18, 2017

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

- N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Took soil samples at this time, received check for NCDA.
2. The required signs are posted and the access road is adequate.
3. The cropstand is adequate and the approved setbacks are being met.
4. No land application has occurred in a very long time (no site logs to review), but site is not “officially inactive” per operators’ request. For land application to occur, additional field markers will be required and the two fields will need to be GPS’d.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------