



GUILFORD COUNTY
DEPARTMENT OF EMERGENCY SERVICES

May 1, 1992

Exxon Company USA
P.O. Box 4386
Houston, TX 77210

Subject: Inadequate UST Closure Report for Exxon RAS # 43998,
4701 W. Market St., Greensboro, NC

Dear Mr. Summey:

Your tank closure report was received March 30, 1992, but fails to meet our standards for completing 40 CFR 280.72. Also refer to "Guidelines for Remediation of Soil Contaminated by Petroleum" and the enclosed outline. Before your report can be accepted, it must include the following information:

- I. Area Map (see enclosure, section I.A.)
- II. Base Map (see enclosure, section I. B.)
- III. Sampling Points and Procedures (see enclosure, section I.C.)
- IV. Quality Control Measures (see enclosure, section I.D.)
- V. Sample Results (see enclosure, section I.E.)
- VI. Manifest Documentation (see enclosure, section I.F.)
- VII. Form GW/UST-2.

Please note that your deficiencies have been highlighted in the attachment. Your revised report must be received within 20 days from letterhead date. If you have any questions, please feel free to contact me at the letterhead address or (919) 884-7565.

Sincerely,

Kelly Craver Gage
Toxic and Health Hazard
Specialist

enclosure
cc: WSRO