

Division of Waste Management

Michael F. Easley, Governor  
William G. Ross Jr., Secretary  
Dexter R. Matthews, Interim Director



**DIVISION OF WASTE MANAGEMENT  
UST SECTION**

September 11, 2001

**Draper Corporation**

Attn: Ms. Sherry Cook  
951 S. Pine Street  
Spartanburg, SC 29302

**Subject: Draper Corporation**

5644 Hornaday Road, Greensboro, Guilford County  
Incident #10089, Low Risk Classification

Dear Ms. Cook:


Per your request, this office has reviewed the file for the incident site. After reviewing the file, we have made following comments:

- Based on the information provided in two separate comprehensive site assessment reports (CSA), there are two unrelated soil/groundwater contamination incidents on the property. One is associated with former 30,000-gallon UST and the other is related to mainly solvent-type contaminants of unknown sources.
- MW-6 was installed about 35 feet down-gradient from the UST. The well needs resampling and risk-based assessment needs to be performed. We need the information for considering whether a no-further-action (NFA) letter can be issued for UST incident.
- Although monitoring wells have been installed to delineate the extent of solvent-type contaminants, their sources have not been determined. It is interesting that these contaminants are mainly found in the deep wells. This observation indicates that the sources are not in the areas around the wells. They may be located up-gradient on the property. Your consultant indicated the sources could be from Ciba-Geigy property. But there is no proof at this time. According to the information provided in the CSA, the groundwater flows from east to west, which indicates the sources may be on Draper's property.
- Because the solvent-type contaminants are not related to UST, the risk-based rules for UST will not apply to this case. Therefore, the cleanup levels for the contaminants are the North Carolina State groundwater standards specified in the NCAC 15A 2L.

Winston-Salem Regional Office, 585 Waughtown Street, Winston-Salem, North Carolina 27107-2241  
Phone: 336-771-4600 \ FAX: 336-771-4632 \ Internet: [www.enr.state.nc.us](http://www.enr.state.nc.us)

Draper Corporation is required to proceed the assessment and remediation at the site. If you may have any questions, please feel free to contact Gene Mao at (336) 641-3771.

Sincerely,

A handwritten signature in black ink, reading "Cindy H. Rintoul". The signature is written in a cursive style with a large, looping initial "C".

Cindy H. Rintoul, PG  
Regional Supervisor