

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Jeff Menzel

Facility ID Number: NCS000002309

Facility Name: SHUFORD LUMBER

Document Group: Inspection/Investigation (I) **Document Type:** I - Complaint Investigation (CMP)

Description for File (for CARA): No violations noted

Date of Document: 04/08/2016

Author(s) of Document: Jeff Menzel

Inspector ID #: NC014

Suborganization: Western Region

Comments for RCRAInfo: Complaint No violations noted

County (if not on report): McDOWELL

**On-Site Complaint Investigation
NCDEQ- DWM-Hazardous Waste Section**

Facility Name: SHUFORD LUMBER
Address: 1946 US HIGHWAY 70 WEST MARION, NC 28752
EPA ID Number: NCS000002309
Inspection Date: April 8, 2016
Facility Contact: TROY SHUFORD

Complaint Info:

CALLER IS REPORTING THAT THERE IS A WASTE OIL TANK THAT HAS LEAKED. APPROXIMATELY 100 GALLONS OF USED MOTOR OIL INTO A CONTAINMENT PIT. THE CONTAINMENT PIT HAS A CRACK IN THE BERM WHICH HAS ALLOWED SOME OF THE PRODUCT TO ESCAPE ONTO THE GROUND.

Date Received: Complaint received from EPA on 04/08/2016
EPA Incident Report NRC#1144761

On-Site Visit: 04/08/2016

Findings:

HWS staff investigated the complaint on 4/08/2016 and found there to be two 500 gallon containers of used oil on the property surrounded by a secondary containment wall. Within the secondary containment there was approximately 100 gallons of spilled used oil. Mr. Troy Shuford (owner) produced a manifest which showed that 310 gallons of used oil had been picked up by Liquidgator Recycling earlier in the day. Mr. Shuford indicated that he and the driver had a disagreement over the price of the transportation of the used oil. Mr. Shuford could not explain how 100 gallons of used oil was spilled into the secondary containment. No fresh spilled oil was observed outside of containment. Dan Murphy, NCDEQ UST section, also arrived on site and confirmed that there was no oil leaking from the secondary containment. Mr. Shuford agreed to pump the material in the secondary containment back into the 500 gallon containers. NCDEQ staff advised Mr. Shuford that better housekeeping practices in the area around the used oil tank would be prudent. A follow up visit 4/13/2016 has confirmed that Mr. Shuford has conducted clean-up in and around the secondary containment unit.

No further action is required at this time.

Inspector:



Date: 04/08/2016