



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Table with columns for Unit Type (Lined MSWLF, Closed MSWLF, CDLF, LCID, HHW, Tire T&P/Collection, YW, White goods, Tire Monofill, X, Transfer, Incin, Industrial Landfill, Compost, T&P, DEMO, SLAS, FIRM, SDTF) and County/Permit/File Type information.

Date of Site Inspection: 07/07/2016

Date of Last Inspection: 04/22/2014

FACILITY NAME AND ADDRESS:

Hensons' Inc.
105 Ridge Rd
Tryon, NC 28782

GPS COORDINATES: N: 35.198412 ° W: 82.226351°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Trey Fincher
Telephone: 828-859-5836
Email address: hensons@hensonsinc.net

FACILITY CONTACT ADDRESS:

PO Box 1060
Tryon, NC 28782

PARTICIPANTS:

Randy Flynn, Hensons' Inc
Lee Hill, NCDEQ – Solid Waste Section

STATUS OF PERMIT:

Active
Notification expires May 31, 2017

PURPOSE OF SITE VISIT:

Comprehensive Inspection

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- The facility is secured by a gate at the entrance and proper signage was observed.
- Access roads throughout the facility are constructed of asphalt and gravel and were in good condition.
- No unapproved material was observed at the time of inspection.
- The unground stockpile consisted on land clearing debris, limbs, branches and untreated wood.
- The facility appeared to have less than 6000 cubic of yards of material at the time of the inspection.
- Surface water appeared to be diverted from the storage areas at the time of inspection.
- Adequate distances between windrows and stockpiles were being maintained for firefighting access.
- Buffer requirements appeared to be met at the time of inspection.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 828-296-4700

Lee Hill
Environmental Senior Specialist
Regional Representative

Sent on: July 11, 2016 to Randy Flynn by:	X	Email		Hand delivery		US Mail		Certified No. []
--	---	-------	--	---------------	--	---------	--	-------------------

Copies: Deb Aja, Western District Supervisor - Solid Waste Section
 Jessica Montie, Compliance Officer – Solid Waste Section