


\*188IHSSF2206\*



DocumentID NONCD0002867

Site Name ATKINSON ST CONTAMINATION

DocumentType Correspondence (C)

RptSegment 1

DocDate 5/19/2010

DocRcvd 5/19/2010

Box SF2206

AccessLevel PUBLIC

Division WASTE MANAGEMENT

Section SUPERFUND

Program IHS (IHS)

DocCat FACILITY



North Carolina Department of Environment and Natural Resources  
Division of Waste Management

Beverly Eaves Perdue  
Governor

Dexter R. Matthews  
Director

Dee Freeman  
Secretary

*Copy*

May 19, 2010

Mr. Gordon Haught  
109 Atkinson Street  
Hamlet, NC 28345

Re: Atkinson Street Contamination  
Hamlet, NC  
NONCD0002867


Dear Mr. Haught:

As you know, to date the Inactive Hazardous Sites Branch (Branch) has been unable to identify the source of the contamination detected in your well. Within the next few weeks, the Branch will be assigning this Site to its contractor to conduct a more thorough investigation of the area. This investigation is being conducted in an attempt to identify the source and location of the contamination. This work will include the collection of both soil and groundwater samples from various properties in the area. As part of this investigation, we may also request your permission to collect soil samples and install monitoring well(s) on your property.

If a source of the contamination can be identified, the Branch will then require those responsible to clean up the contamination and provide you with an alternate drinking water source. If no responsible party can be identified or the responsible party is not financially viable, this Site will be considered as an orphan site and the Branch will evaluate all options to provide you with an alternate drinking water source. Please be aware that the installation of a new drinking water well on your property may not resolve this issue unless the source of the groundwater contamination can be identified and the vertical and horizontal extent of the contaminant plume defined so that a clean area of your property, suitable for a well, can be identified.

If you have any questions or comments, please feel free to give me a call at 919-508-8485. Thank you once again for your cooperation.

Sincerely,



John W. Walch  
Eastern Unit Supervisor  
Inactive Hazardous Sites Branch  
Superfund Section

cc: Penny Myers, 6508 Berridge Drive, Wilmington, NC 28412

M<sub>3</sub>.

Lorretta? Jernigan - 910-582-4824