



FACILITY COMPLIANCE AUDIT REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	X	YW	Transfer	Compost	SLAS	COUNTY: Durham PERMIT NO.: 32-D FILE TYPE: COMPLIANCE
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM	
CDFL	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF	

Date of Audit: February 17, 2010

Date of Last Audit: December 29, 2010

FACILITY NAME AND ADDRESS:

Currin Landfill
 Coley Road
 Durham County, NC

GPS COORDINATES: **N: 35.95090** **E: -78.74380**

FACILITY CONTACT NAME AND PHONE NUMBER:

Glenn Currin, 919-876-1877
 Allen Currin, 919-614-2374

FACILITY CONTACT ADDRESS:

Currin Brothers, Inc.
 1610 Wolfpack Lane
 Raleigh, NC 27603

AUDIT PARTICIPANTS:

Allen Currin, Owner/Operator
 Glenn Currin, Owner/Operator
 Chris Marriott, NCDENR-Solid Waste Section

STATUS OF PERMIT:

Original Issue: January 25, 1989
 Permit Amendment: September 7, 1993
 Permit Amendment: November 3, 2010
Permit Expires: November 3, 2015

PURPOSE OF AUDIT:

Partial Audit--follow-up at request of owner

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS:

None

FACILITY COMPLIANCE AUDIT REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

AREAS OF CONCERN AND COMMENTS:

- 1) This inspection was completed at the request of Allen Currin to view the corrections to concerns mentioned in the report from the December 29, 2010 inspection. Allen Currin called me on February 8, 2011 to inform me that work had been completed and to request this meeting.
- 2) The repairs to the cave in documented during the December 29, 2010 audit were viewed. The area has been filled in with dirt, seeded and covered with straw (pictured below).



- 3) The perimeter of the top of the fill was walked with Allen & Glenn Currin. Grass cover over the landfill is well established. Upkeep issues were discussed such as, depressions, water drainage, vegetation and access to the facility.
- 4) The dead tree observed during the December 2010 inspection was shown to Allen and Glenn. Allen Currin said that he would take care of the dead tree removal the following week.

Please contact me if you have any questions or concerns regarding this audit report.

Phone: 336-771-5090

Chris Marriott
Environmental Senior Specialist
Regional Representative

Delivered on : <u>March 1, 2011</u> by		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. <input type="checkbox"/>
--	--	---------------	-------------------------------------	---------	--	--

cc: Jason Watkins, Central District Supervisor
Donald Herndon, Compliance Officer