



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:										
Lined MSWLF		LCID	X	YW		Transfer		Compost	SLAS	COUNTY: Durham PERMIT NO.: 32-D FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

Date of Site Inspection: August 17, 2011 **Date of Last Inspection:** February 17, 2011

FACILITY NAME AND ADDRESS:

Currin Brothers, Inc. LCID Landfill (No. 1)
 Coley Road
 Durham, NC 27703

GPS COORDINATES: N: 35.95247 E: 78.74354

FACILITY CONTACT NAME AND PHONE NUMBER:

Glenn Currin, Co-Owner
 c. 919-880-6624
 Allen Currin, Co-Owner
 c. 919-614-2374
 Office (Donna Parrish - Secretary): 919-876-1138

FACILITY CONTACT ADDRESS:

Currin Brothers, Inc.
 PO Box 547
 Fuquay-Varina, NC 27526

PARTICIPANTS

John Patrone, NCDENR – Solid Waste Section (SWS)

STATUS OF PERMIT:

Permit To Construct (PTC)/Permit To Operate (PTO) issued November 3, 2010
 PTO/PTC expiration date November 3, 2015

PURPOSE OF SITE VISIT:

Comprehensive Audit

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 4

ADDITIONAL COMMENTS


On August 17, 2011, John Patrone conducted a comprehensive audit of the Currin Brothers, Inc. LCID Landfill (No. 1) on Coley Road in Durham, Durham County.

1. A copy of the facility permit recorded with the Durham County Register of Deeds, dated December 20, 2010 (Bk: 6630, Pg: 416 – 428) has been received by the SWS.
2. The land clearing and inert debris (LCID) landfill has not accepted LCID material since the late 1990s.
3. The facility is not in operation. An active permit is maintained on the assumption of future use. The LCID landfill is located on the right ~ ½ mile south of the Currin Brothers, Inc. LCID Landfill No. 2 (32-I), access via yellow metal gate visible from road.
4. The LCID landfill contains soil cover and vegetative material.
5. The facility service area includes Durham, Wake, Orange, Granville, and Chatham Counties.
6. The facility is permitted to receive land clearing waste, unpainted and untreated natural wood, inert debris, and (used) asphalt.
7. The LCID landfill is permitted for a total gross capacity of 1,118,000 yd³.
8. Permanent disposal unit boundary markers shall be installed and maintained.
9. Ensure that the landfill cap is routinely mowed and woody vegetation removed.
10. The facility has an all-weather access road leading to the front/edge of the fill area. The landfill cap does not allow vehicle access. Ready access to the landfill cap and around the fill area perimeter should be established and maintained such that routine inspection can be conducted.
11. The facility is secured by a locked gate. The entrance/gate is also used by a local power authority to access high voltage transmission lines.
12. Ensure the facility has proper signage.
13. Ensure that the waste material dumped at the facility entrance/gate (to include the scrap tire inside the facility, adjacent to the gate) is picked-up and brought to an approved solid waste disposal facility.
14. Ensure that the metal garbage can filled with water (inside the facility, adjacent to the gate) is dumped-out/does not cause a nuisance condition.
15. The facility is permitted for a land clearing debris treatment and processing (T&P) operation.
16. The T&P operation did not appear to be in use. No indication of a grinding operation was observed.
17. The T&P operation is permitted to receive land clearing waste, unpainted and untreated natural wood, and wooden pallets.
18. The T&P operation is required to be located at a separate area from the active LCID landfill and fire lanes must be maintained throughout material stockpiles.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 4

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 336-771-5095 Fax: 336-771-4631

John Patrone
Environmental Senior Specialist
Regional Representative

Sent on: <u>August 25, 2011</u>		Email		Hand delivery		US Mail	X	Certified No. []
---------------------------------	--	-------	--	---------------	--	---------	---	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor
Shawn McKee, Compliance Officer

Digital Photographs taken August 17, 2011
by John Patrone, DWM – SWS

Facility access road/gate



Facility access road to front/edge of fill area



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 4 of 4

Left front of fill area



Dumped material at facility gate



Right front corner of fill area



Tire and metal garbage can (filled with water) inside facility, adjacent to gate

