



**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE: (check all that apply to this audit with same Permit number)</b>											
Lined MSWLF	<input type="checkbox"/>	LCID	<input type="checkbox"/>	YW	<input type="checkbox"/>	Transfer	<input type="checkbox"/>	Compost	<input type="checkbox"/>	SLAS	COUNTY: Forsyth PERMIT NO.: 34-18-TP FILE TYPE: COMPLIANCE
Closed MSWLF	<input type="checkbox"/>	HHW	<input type="checkbox"/>	White goods	<input type="checkbox"/>	Incineration	<input type="checkbox"/>	T&P	<input checked="" type="checkbox"/>	FIRM	
CDLF	<input type="checkbox"/>	Tire T&P / Collection	<input type="checkbox"/>	Tire Monofill	<input type="checkbox"/>	Industrial Landfill	<input type="checkbox"/>	DEMO	<input type="checkbox"/>	SDTF	

Date of Audit: 9-26-07

Date of Last Audit: 7-18-07

**FACILITY NAME AND ADDRESS:**

H.G. Myers/ M. L. Myers Land Clearing and  
 Inert Debris Treatment and Processing Facility  
 7775 Shallowford Road  
 Lewisville, NC

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Herbert G. Myers  
 (336) 766-6887

**FACILITY CONTACT ADDRESS (IF DIFFERENT):**

820 Ellington Drive  
 Winston-Salem, NC 27104

**AUDIT PARTICIPANTS:**

Jason Watkins, DWM-Solid Waste

**STATUS OF PERMIT:**

Active permit expires on June 10, 2009

**PURPOSE OF AUDIT:**

Comprehensive Audit

<p><b><u>NOTICE OF VIOLATION(S) (citation and explanation):</u></b>          NONE</p> <p>You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$5,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. If the violation(s) noted here continue, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.</p>
---

**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**STATUS OF PAST NOTED VIOLATIONS (List all noted last audit):**

**1. 15A NCAC 13B .0302(1) states that "Operational plans shall be approved and followed as specified for the facility".**

The facility operations plan states that "mulch will be processed and ground in the areas indicated on the operations plan. Mulch will be stockpiled in windrows in the areas and in the general arrangement as also illustrated in the plan".

*This facility is in violation of 15A NCAC 13B .0303(1) in that the approved operations plan is not being followed. The newer material is currently not being managed in windrows but in one large pile after processing. There are older windrows on site.*

**2. Permit Condition #5 states that "any heat generation (composting) in any of the piles of material at the facility will considered a permit violation".**

*This facility is in violation of Permit Condition #5 in that random temperature checks in the large pile on July 18, 2007 showed temperatures well above the bottom range for composting, which is around 110 degrees Fahrenheit. Temperatures were checked in 4 locations with the lowest reading near 100 degrees and the highest near 140 degrees. None of the older windrows showed temperature readings above 100 degrees.*

**In order to gain compliance, the following must be implemented by September 15, 2007:**

1. All processed material must be placed in windrows no larger than 10 ft in height and 20 ft wide at the base as noted in your operations plan.
2. Implement a temperature monitoring program to ensure that no readings over 110 degrees are occurring.

*Some of the material onsite has been shifted into new windrows. The facility has not implemented a temperature monitoring plan at this time.*

**AREAS OF CONCERN AND COMMENTS:**

1. Ensure that all buffers for material including the 100 ft buffer from Shallowford Road are being maintained. Unprocessed material was within 100ft of the road.
2. All signage in place and all boundary areas are properly marked.
3. There was a large amount of soil on-site to be screened for topsoil.
4. This facility needs to obtain a windrow thermometer so that temperature checks can occur on a regular basis. Attached is an example of an appropriate thermometer.
5. I spoke to Mr. Myers via telephone on September 26<sup>th</sup> and told him to continue to shift material into windrows.

Please contact me if you have any questions or concerns regarding this audit report.

  
 Regional Representative

(signature) Phone: 336-771-5092

**Distribution: original signed copy to facility -- signed copy to compliance officer -- e-mail or copy to super**

Delivered on : <u>9-27-07</u> by		hand delivery	X	US Mail		Certified No.
----------------------------------	--	---------------	---	---------	--	---------------

Cc: Deb Aja, Western Regional Supervisor  
 Mark Poindexter, Field Operations Branch Head  
 Mike Scott, Composting/Land Application Branch Head