

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Ernest Lawrence

Facility ID Number: NCR000150466

Facility Name: EQ Mobile Recycling Services, Inc.

Document Group: Inspection/ Investigation (I) **Document Type:** I – Compliance Evaluation Inspection (CEI)

Description for File (for CARA): -No violations

Date of Document: 12/30/2015

Author(s) of Document: Ernest Lawrence

Inspector ID #: NC043

Suborganization: Western Region

Comments for RCRAInfo: No violations

County (if not on report): Surry

For Violations:

Enforcement Date: [Click here to enter a date.](#)

Docket Number:

Enforcement Type:

How many violations were there?

For IANOV or CO: The facility is

Outcome Measures for CSE for IANOV or CO:

Waste Involved	Volume	Exposure Media (a, gw, sw, s)	Distance to Residences	Number of People involved	Distance to On-site wells	Distance to Off-site wells

Violation #1:

Date Determined: [Click here to enter a date.](#)

Scheduled Return to Compliance: [Click here to enter a date.](#)

Actual Return to Compliance: [Click here to enter a date.](#)

Regulation Description:

Comment:

For CSE, Corrections to Violations were:

Violation #2:

Date Determined: [Click here to enter a date.](#)

Scheduled Return to Compliance: [Click here to enter a date.](#)

Actual Return to Compliance: [Click here to enter a date.](#)

Regulation Description:

Comment:

For CSE, Corrections to Violations were:



PAT MCCRORY
Governor

DONALD R. VAN DER VAART
Secretary

RCRA INSPECTION REPORT

Facility Address

EQ Mobile Recycling Services, Inc.
540 West Independence Blvd
Mount Airy, NC 27030

Facility Contact – Gary Willard, Operations Manager (336-719-0058) steve.coe@eqonline.com

EPA ID Number – NCR000150466

Inspector (s) – Ernest Lawrence

Date of Inspection – December 30, 2015

Last Inspection Date – March 14, 2014

Status – SQG. The facility does not generate over 220 pounds in most months, but is an episodic SQG.

Inspection Type – CEI

Present at Inspection – Gary Willard, Ernest Lawrence

Facility Description

EQ Mobile Recycling Services, Inc. operates mobile distillation units for the on-site reclamation of solvents at various manufacturing facilities. The company serves the Southeast but mostly works in North Carolina, Georgia, and Virginia.

The facility has one building that includes an office and a truck service shop. The distillation units are mounted inside trailers.

Hazardous waste that is generated during the distillation process is left at the customer's facility. The customer is responsible for the disposal of still bottoms generated at their site.

The Mt. Airy facility generates hazardous waste only when the trailer units require cleaning. This does not occur on a regular basis.

The facility operates a 10-day transfer station. This consists of one semi trailer. No waste was in the trailer at the time of inspection.



State of North Carolina | Environmental Quality
1601 Mail Service Center | Raleigh, North Carolina 27699-1601
919 - 707 - 8600

Facility Description

Distance to closest residence	estimated 1/2 mile
Distance to closest off-site well	>1 mile
Water supply	City water
Sewage	City Sewer
Operating shifts	1
Number of employees	2 on site
Size of facility	estimated 2 acres

Wastes Generated

D001, F003, F035 – Waste flammable liquid (acetone, MEK)
D001, F003 – Waste acetone

Manifests

Filled Out Correctly - Yes

Signed Copies – Yes

LDR Notification Attached - Yes

Transporters - EQ Industrial Services – MIK435642742

TSDF's- EQ Detroit – MID980991566

Storage Area

There was one 55-gallon container of hazardous waste in the storage shed.

Containers labeled “Hazardous Waste”? – Yes

Containers dated when accumulation began? – Yes.

Containers compatible with waste? – Yes

Containers closed? – Yes

Managing incompatible waste? – Yes

Containers in good condition and not leaking? – Yes

Adequate aisle space – Yes

A telephone or two-way radio available at the scene of operation to summon emergency assistance? – Yes

Inspection Records

Weekly inspections of the hazardous waste storage area were being made and recorded.

Emergency arrangements made with fire, police, hospital, and emergency responders? – Yes.

Satellite Accumulation Areas

There were no satellite accumulation areas.

Emergency coordinator on premises or on call at all times? – Yes

Contingency Plan – Information posted next to the telephone

Name and phone number of emergency coordinator? – Yes.

Location of fire extinguishers, spill control equipment, and fire alarm? –Yes.

Number to the fire department, unless there is a direct alarm? – Yes.

Emergency Preparedness

The facility is equipped with fire extinguishers and spill control equipment. The fire extinguishers are serviced annually. A PA system is used to announce the need to evacuate the building in the event of an emergency.

Training

The generator has ensured that all employees that are involved with the handling of hazardous waste are thoroughly familiar with proper waste handling and emergency procedures? –RCRA training was included with OSHA training.

Used Oil

There was one 500-gallon container of used oil inside the service building and three 55-gallon containers of used oil in the storage shed. The tank and containers were labeled “Used Oil” and no spills were observed.

Site Deficiencies

None



12/30/2015

Copy sent to facility

RCRA Inspector

Date

Facility Contact