

According to (G.S. 130A-309.09D(b)) completed forms must be returned by August 1, 2011 and a copy of this report must be sent to the County Manager of each county from which waste was received. If you have questions or require assistance in completing this report, contact your Regional Environmental Senior Specialist.

Facility Name: Fort Bragg C&D Landfill Recycling Area

Permit: 2608-CDLF-1998 ID: 9497

Facility Website (URL):

Physical Address	Mailing Address
Street 1: BLDG # O-3454, Lamont Road	Street 1: BLDG #3-1137 Butner Road, Directorate of Public Works
Street 2:	Street 2:
City: Fort Bragg County: Cumberland	City: Fort Bragg
State: North Carolina Zip: 28310	State: North Carolina Zip: 28310
Primary Facility Contact Person	Billing Contact Person
Name: Sid Williamson	Name: Sid Williamson
Phone: (910) 977-2502 Fax: (910) 396-4188	Phone: (910) 977-2502 Fax: (910) 396-4188
Email: sidney.williamson@us.army.mil	Email: sidney.williamson@us.army.mil

1. Tipping Fee: \$0.00 per Ton (Attach a schedule of tipping fees if appropriate.)

2. Please attach results of monthly temperature monitoring for the period of July 1, 2010 thru June 30, 2011.

3. For Type II, III, and IV facilities, attach results of tests (Waste Analysis with metals, foreign matter and pathogens) as required in Table 3 of Rule 15A NCAC 13B .1408 for the period of July 1, 2010 thru June 30, 2011. **Current Rules state that "Compost shall be analyzed at intervals of every 20,000 tons of compost produced or every six months."**

4. What type and quantity of waste was composted by your facility?

Materials COMPOSTED	Check X if Received	Tons RECEIVED	Tons COMPOSTED	Unusable Tons DISPOSED
Yard Waste	<input checked="" type="checkbox"/>	547.25	547.25	
Clean Wood	<input type="checkbox"/>			
Sawdust	<input type="checkbox"/>			
Wooden Pallets	<input type="checkbox"/>			
Food Waste	<input type="checkbox"/>			
Animal Waste	<input type="checkbox"/>			
Sludge and Biosolids	<input type="checkbox"/>			
Grease Trap Waste	<input type="checkbox"/>			
Animal Mortalities	<input type="checkbox"/>			
Sheetrock	<input type="checkbox"/>			
Commingled (Describe)	<input type="checkbox"/>			
Other (Describe)	<input type="checkbox"/>			
Other (Describe)	<input type="checkbox"/>			
Other (Describe)	<input type="checkbox"/>			
TOTAL		547.25	547.25	

**SOLID WASTE MANAGEMENT FACILITY
FIRE OCCURRENCE NOTIFICATION**
NC DENR Division of Waste Management
Solid Waste Section



Notify the Section verbally within 24 hours and submit written notification within 15 days of the occurrence.
(If additional space is needed, use back of this form)

NAME OF FACILITY: Recycling Area C+D LF PERMIT # 2608
 DATE AND TIME OF FIRE: April 16 2011 @ 08:00 AM / PM (circle one)
 HOW WAS THE FIRE REPORTED AND BY WHOM: Dan Messier Landfill Manager reported fire in the stockpiled yard waste
 LIST ACTIONS TAKEN: Landfill personnel applied water on yard waste and moved pile apart to get to hot spots. Fire Dept Fort Bragg was notified of fire for guidance and assistance.
 WHAT WAS THE CAUSE OF THE FIRE: Possible lightning strike due to high intensity heat.

DESCRIBE AREA, TYPE, AND AMOUNT OF WASTE INVOLVED: Recycling Area for yard waste. yard waste was 40'x50'x12' High
 WHAT COULD HAVE BEEN DONE TO PREVENT THIS FIRE: Divide the big pile in smaller piles.

CURRENT STATUS OF FIRE: Fire is out. Yard waste is cooked. Yard waste was put in windrow
 DESCRIBE PLAN OF ACTIONS TO PREVENT FUTURE INCIDENTS: Smaller piles of yard waste

NAME: A.W. Williams TITLE: Solid Waste Manager DATE: 4-21-11

THIS SECTION TO BE COMPLETED BY SOLID WASTE SECTION REGIONAL STAFF
DATE RECEIVED _____

List any factors not listed that might have contributed to the fire or that might prevent occurrence of future fires:

FOLLOW-UP REQUIRED:						
<input type="checkbox"/> NO	<input type="checkbox"/> PHONE CALL	<input type="checkbox"/> SUBMITTAL	<input type="checkbox"/> MEETING	<input type="checkbox"/> RETURN VISIT	BY: _____	(DATE)
ACTIONS TAKEN OR REQUIRED:						

Revised 6/29/01

Moved Yard Waste Area to
back corner (North West) of
Recycling Area. Yard Waste
will be Stockpiled.

MW
6-7-10

For Record - Land Fill Manager
performed random temperature checks
of Yard Waste Stockpiled and
Temperature never achieved the
above 131° for compliance - Too much
pine straw due to clean sweep.

On April 16 2011 Yard Waste
Stockpile caught fire due to
lightning strike on other methodes.

Report to State Sent

MW
4-21-11