

**Subject: Monitoring Data**

**Date:** Fri, 07 Dec 2001 14:32:19 -0500

**From:** Larry Rose <Larry.Rose@ncmail.net>

**To:** Bob.wilson@pgnmail.com

*Carmen Johnson*  
Scanned by *[Signature]* Date *9/26/12 [Signature]*  
*92-10*

Bob,

As requested by phone, please verify that the October 18, 2001 groundwater monitoring data for the Shearon Harris Nuclear Power Plant landfill is correct. It appears as if the detection limits for the metals are wrong. With the exception for mercury, all are reported as mg/L and the concentrations of those metals detected are unusually high - much higher than their respective NCAC 2L groundwater standard. Is it possible the detection limits should be ug/L? If they are correct, they exceed the Solid Waste Section's required reporting limits.

Thanks for your help in resolving the matter.

Larry Rose  
Solid Waste Section  
Environmental Compliance  
(919) 733-0692, ext. 257