



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost		SLAS		<b>COUNTY:</b> Wilson <b>PERMIT NO.:</b> N0403 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** January 22, 2013    **Date of Last Inspection:** November 3, 2011

**FACILITY NAME AND ADDRESS:**

L&L Landfill  
 4468 London Church Rd.  
 Wilson, North Carolina

**GPS COORDINATES:** N: 35.79740    E: 77.90734

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name:            Johnnie Langley  
 Telephone:    252 304 6149 Johnnie Langley, 252 245 0098 Ronnie Langley  
 Email address: [langldsc@gmail.com](mailto:langldsc@gmail.com) Ronnie Langley  
 Fax:              252 281 1007

**FACILITY CONTACT ADDRESS:**

Johnnie Langley 3009 Anderson Rd. Wilson, North Carolina 27893	Langley's Landscaping & Lawn Care, website: <a href="http://langleyslandscaping.com">langleyslandscaping.com</a> 3010 Heard Rd Wilson, North Carolina 27896
--	---

**PARTICIPANTS:**

Ben Barnes NCDENR, Solid Waste Section  
 Johnnie Langley, L&L Landscaping  
 Ronnie Langley, Langley's Landscaping & Lawn Care

**STATUS OF PERMIT:**

Notified site, no permit required

**PURPOSE OF SITE VISIT:**

Follow up audit to determine compliance with NOV dated January 26, 2010

**STATUS OF PAST NOTED VIOLATIONS:**

NONE

**OBSERVED VIOLATIONS**

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

- 1) The disposal area is approaching two acres in size. **The boundary of the landfill footprint needs to be staked to prevent the disposal area from exceeding the 2 acre size limit.**
- 2) The slopes need to be graded to 3:1 or no greater than 4:1 and stabilized with seed or mulch.
- 3) The cover is generally good.
- 4) The access road was well maintained.
- 5) There is a cable across the entrance that was open at the time of the audit. **The gate should be closed to prevent illegal dumping.**
- 6) The area of impounded water below the eastern slope should either be filled or drained.
- 7) Only waste defined as land clearing and inert debris waste can be disposed in the landfill. **The nonconforming waste on the site needs to be removed and transported to a facility approved to receive this type of waste within 30 days of receiving this inspection form. Receipts from the approved facility must be provided to me at Ben Barnes, P.O. Box 8998 Rocky Mount, North Carolina 27804.**

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 252 459 4502 email [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

*Ben Barnes*  
 Environmental Senior Specialist  
**Regional Representative**

Sent on January 29, 2013 By:	X	Email		Hand delivery		US Mail	Certified No. [ ]
------------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor  
 Jessica Montie, Compliance Officer



Nonconforming waste on the surface of the landfill

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3



landfill

Impounded water on the eastern slope of the



Southern slope of the landfill



Fresh waste on the surface