



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		COUNTY: CATAWBA PERMIT NO.: 18-H FILE TYPE: COMPLIANCE
Closed DEMO	X	HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: May 20, 2014

Dates of Last Inspection: February 8, 2011

FACILITY NAME AND ADDRESS:

Blackburn Demolition Landfill
 4017 Rocky Ford Road
 Newton, NC 28658

GPS COORDINATES: N: 35.60782 W: -81.30588

FACILITY CONTACT NAME AND PHONE NUMBER:

Rodney Hamby, Landfill Superintendent
 (704) 462-1348
 rhamby@catawbacountync.gov

FACILITY CONTACT ADDRESS:

Post Office Box 389
 Newton, North Carolina 28658

PARTICIPANTS:

Rodney Hamby, Landfill Superintendent
 Deborah Aja, NCDENR Solid Waste Section

STATUS OF PERMIT:

Catawba County was issued a Letter of Closure for the Blackburn Demolition Landfill on September 29, 2005.

PURPOSE OF SITE VISIT:

Partial Inspection.

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

No violations observed.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

1. A gate was provided at the entrance to the landfill to prevent unauthorized access.
2. Edge of waste markers were in place.
3. Vegetation (grasses) was established on the cap. The landfill was scheduled for mowing.
4. Brush was growing on the northeastern slope of the landfill at slope drain outlets. Any brush and woody vegetation must be removed so that the cap and structures can be properly maintained.
5. Access roads were of all-weather construction and maintained in good condition.
6. Minor settlement was observed on the landfill cap.
7. No standing water was observed on the cap.
8. Semi-annual groundwater monitoring is conducted with sampling events for the Blackburn Resource Recovery Facility, Permit 1803.

Please contact me if you have any questions or concerns regarding this inspection report.



Deborah Aja
Environmental Senior Specialist
Regional Representative
deborah.aja@ncdenr.gov

Phone: 828-296-4702
Asheville Regional Office
2090 US Hwy 70
Swannanoa, NC 28778

Sent on May 30, 2014, to Rodney Hamby by:	<input checked="" type="checkbox"/>	Email	<input type="checkbox"/>	US Mail	<input type="checkbox"/>	Certified No. <input type="checkbox"/>
---	-------------------------------------	-------	--------------------------	---------	--------------------------	--

EC: Jason Watkins, Western District Supervisor - SWS
Sarah Rice, Compliance Officer - SWS