



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		COUNTY: Cumberland PERMIT NO.: 2602-MSWLF-1981 FILE TYPE: COMPLIANCE
Closed MSWLF	X	HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: October 29, 2013

Date of Last Inspection: September 11, 2013

FACILITY NAME AND ADDRESS:

Fort Bragg Closed MSWLF
 Longstreet Road, Fort Bragg

GPS COORDINATES: N: 35.1438 E: -79.07399

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Sid Williamson, Solid Waste Manager
 Telephone: 910-396-3372
 Email address: Sidney.d.williamson.civ@mail.mil
 Fax: 910-396-4188

FACILITY CONTACT ADDRESS:

Department of the Army
 Public Works Business Center
 IMSE-BRG-PW
 HQ, US Army Garrison, Fort Bragg
 Installation Management Agency Command
 Fort Bragg, North Carolina 28310

PARTICIPANTS:

Drew Hammonds, NCDENR
 Sid Williamson, Fort Bragg Solid Waste Manager

STATUS OF PERMIT:

MSWLF Closed May 2001

PURPOSE OF SITE VISIT:

Inspection

STATUS OF PAST NOTED VIOLATIONS: NA

OBSERVED VIOLATIONS

1. None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

Follow up inspection was conducted of the closed MSWLF.

1. The mowing of tall vegetation at the facility had been completed at the time of this inspection.
2. It is recommended that staff routinely mow the site in order to check the integrity of the landfill cap for issues such as settling and ponding of water, erosion, seeps or any other issues that cannot be observed due to high, thick vegetation.
3. Bragg personnel want to fill in the surface drainage ditches. It is recommend that you remove the rip rap stone from the ditches and fill the ditches with suitable soil in accordance with the closure plan and requirements as it relates to the cap system. Alternative methods of filling these areas should be discussed with the permitting branch engineer.
4. Measures should be installed to prevent onsite erosion from the fill activity and to assist in establishing vegetative cover on this area.
5. I recommend that the landfill have routine inspections to identify and address any problems that may occur as part of the post-closure care and maintenance identified in the post-closure criteria.

Please contact me if you have any questions or concerns regarding this inspection report.



Environmental Senior Specialist
Regional Representative

Phone: 910-433-3350

Sent on: December 16, 2013	X	Email		Hand delivery		US Mail		Certified No. []
-----------------------------------	---	-------	--	---------------	--	---------	--	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor
Jessica Montie, Solid Waste Section Compliance Officer
Audrey Oxendine, Fort Bragg Compliance Branch Chief
Sid Williamson, Fort Bragg Solid Waste Manager