



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer	<input checked="" type="checkbox"/>	Compost		SLAS	<b>COUNTY:</b> Forsyth <b>PERMIT NO.:</b> 34-16T <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** May 7, 2014

**Date of Last Inspection:** July 31, 2013

**FACILITY NAME AND ADDRESS:**

Overdale Road Transfer Station  
 5000 Overdale Road  
 Winston-Salem, North Carolina 27101

**GPS COORDINATES:** **N:** 36.03323    **W:** 80.23202

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Mark Bacon, General Manager  
 Telephone: (336) 724-0842 (o) or (336) 714-4300 (m)  
 Email address: [baconm@republicservices.com](mailto:baconm@republicservices.com)  
 Fax: (336) 724-0412

**FACILITY CONTACT ADDRESS:**

Mark Bacon, General Manager  
 Republic Services of North Carolina, LLC  
 2875 Lowery Street  
 Winston-Salem, North Carolina 27107

**PARTICIPANTS:**

Mark Tabaczynski, Division Manager, Republic Services of North Carolina, LLC  
 Charles Gerstell, NCDENR-Solid Waste Section

**STATUS OF PERMIT:**

A Permit to Operate the Overdale Transfer Facility was issued to Republic Services of North Carolina, LLC (Owner & Operator) on September 17, 2012. This permit shall expire on September 17, 2017.

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

**ADDITIONAL COMMENTS**

1. The facility is owned by Republic Services of North Carolina, LLC.
2. The transfer station operation and hauling is contracted to K.R. Drenth Trucking, Inc.
3. The facility is permitted to receive municipal solid waste that is generated within Forsyth, Alamance, Alexander, Alleghany, Cabarrus, Caswell, Chatham, Davidson, Davie, Guilford, Iredell, Randolph, Rockingham, Rowan, Stokes, Surry, Wilkes, and Yadkin Counties, North Carolina.
4. Waste from the facility is transported to Uwharrie Regional Landfill (Permit #: 62-04) for final disposal
5. The facility currently accepts approximately 363 tons of municipal solid waste each operating day.
6. The permit and operations plan were current and available for review upon request.
7. Waste screening reports were reviewed. Facility staff performed an average of one waste screening each operating day as outlined in the approved operations plan. Majority of screenings were performed during the same period of the day, usually in the late afternoon.
8. Transfer Station Operations Specialists:
  - Sandra G. Lucas (expires 7/15/15)
  - Franklin May (expires 4/14/12)
  - Ronnie McIntyre (expires 10/20/14)
  - Timothy L. Moore (expires 9/13/16)
  - Jacquelyn N. Posey (expires 6/3/14)
  - Joseph E. Prestandrea (Took course on March 25<sup>th</sup> – 26<sup>th</sup>. Waiting of certificate.)
  - Larry L. Sansbury (expires 12/14/14)
  - Daryl Stratton (expires 2/27/15)
  - Sylvester E. Scales (expires 6/3/14)
  - Mark Tabaczynski (expires 1/1/15)
9. The facility had proper signage.
10. A gate was provided at the entrance to the facility to prevent unauthorized access when the facility is not in operation.
11. No unacceptable waste streams were observed.
12. The damaged portion of the tipping floor with exposed rebar observed during previous inspections has been repaired. Thank you for your attention to this matter.
13. Majority of facility walls were free of a heavy buildup of residue at the time of inspection. However, heavy residue buildup was observed on the east wall adjacent to the transfer trailer loading area and on the east and south walls at the southwest corner. Please ensure that these areas receive attention during the next cleaning event.
14. Please ensure that all waste deposited on the floor of the transfer trailer loading bay and on top of the structural beams along the wall of the loading bay are removed and properly disposed at the end of the working day.
15. Fire extinguishers were available in case of fires at the facility. All observed were found to have a full charge.
16. Windblown waste was well controlled at the time of inspection.
17. Bait boxes were installed along the perimeter of the facility for vector control.
18. Continue efforts to remove the buildup of small pieces of waste consisting primarily of paper and glass on the exterior side of the wall adjacent to the trailer loading area. This waste must be picked up and returned to the transfer station. It appeared that this material was deposited on the ground through a hole in the wall. A piece of sheet metal placed over the hole in the past has partially separated from the wall allowing waste to fall through the repaired section.
  - Mr. Tabaczynski explained during the inspection that repairs to the exterior wall adjacent to the trailer loading area have been scheduled for the weekend of May 17<sup>th</sup>.
19. During the inspection, a K.R. Drenth tractor truck was being washed down via water hose on the paved area in front of entrance to the tipping floor. No water was observed leaving the tipping floor. Please ensure that such activities are performed in a manner that prevents any water from washing residue from the tipping floor away from leachate containment.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

*Charles T. Gerstell*

Phone: (704) 235-2144

\_\_\_\_\_  
Charles T. Gerstell  
Environmental Senior Specialist  
***Regional Representative***

Sent on: <u>5/14/14</u>	<input checked="" type="checkbox"/>	Email		Hand delivery		US Mail		Certified No. [ ]
-------------------------	-------------------------------------	-------	--	---------------	--	---------	--	-------------------

Copies: Jason Watkins, Western District Supervisor  
Sarah M. Rice, Compliance Officer  
Mark Tabaczynski, District Manager, Republic Services of North Carolina, LLC