



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>										
Lined MSWLF		LCID	<b>X</b>	YW		Transfer		Compost	SLAS	<b>COUNTY: Chatham</b> <b>PERMIT NO.: N0568</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P	FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF	

**Date of Site Inspection:** February 4, 2014    **Date of Last Inspection:** July 26, 2011

**FACILITY NAME AND ADDRESS:**

Ricky Beal Grading & Septic Tank Service LLC LCID Landfill  
Walter Lambert Road  
Goldston, NC 27252

**GPS COORDINATES:** N: 35.60134 E: -79.30762

**FACILITY CONTACT NAME AND PHONE NUMBER:**

[Joseph] Ricky Beal  
w. 919-898-4346  
c. 919-542-8087  
[beal.ricky@yahoo.com](mailto:beal.ricky@yahoo.com)

**FACILITY CONTACT ADDRESS:**

Ricky Beal, Manager  
Ricky Beal Grading & Septic Tank Service LLC  
PO Box 314  
Goldston, NC 27252

**OTHER**

Home address: 1469 N. Main Street, Goldston, NC 27252

**PARTICIPANTS**

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)  
Ricky Beal, Manager - Ricky Beal Grading & Septic Tank Service LLC

**STATUS OF PERMIT:**

Land Clearing and Inert Debris Landfill Notification recorded with the Chatham County Register of Deeds June 8, 2001 and re-recorded on June 18, 2001 (addition of property deed book and page numbers)  
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

**STATUS OF PAST NOTED VIOLATIONS**

None

**OBSERVED VIOLATIONS**

None

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

On February 4, 2014, John Patrone met with Ricky Beal to conduct a comprehensive inspection of the Ricky Beal Grading & Septic Tank Service LLC LCID Landfill on Walter Lambert Road in Goldston, Chatham County.

1. The land clearing and inert debris (LCID) landfill is not open to the general public.
2. The LCID landfill appeared to be < 2 acres.
3. The current fill area appeared to be ~ 100 feet in length. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
4. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
5. Side slopes should be graded and covered with soil such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
6. Ensure LCID material is covered with soil by March 2014.
7. Mr. Beal stated that the LCID landfill is > 50 feet from a small pond (adjacent to the fill area).
8. Per 15A NCAC 13B .0564(9)(a), "The facility shall meet the following buffer requirements: 50 feet from the waste boundary to all surface waters of the state as defined in G.S. 143-212.
9. Per 15A NCAC 13B .0564(9)(b), "The facility shall meet the following buffer requirements: 100 feet from the disposal area to property lines, residential dwellings, commercial or public buildings, and wells."
10. There was no indication of erosion or runoff.
11. Access roads are of all-weather construction.
12. The facility is secured by a steel cable and padlock.
13. Per 15A NCAC 13B .0566(16), "A sign shall be posted at the facility entrance showing the contact name and [phone] number in case of emergency."
14. Logs are stored on the property to be given-away for firewood.
15. Inert debris (rock, brick, and cement block associated with demolition) is stored on site to be sold as fill material.
16. A copy of the Land Clearing and Inert Debris Landfill Notification recorded June 18, 2001 is included with this inspection report.
17. Mr. Beal was given a copy of the rules pertaining to notified LCID landfills during the inspection.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 336-771-5095 Fax: 336-771-4631

John Patrone  
 Environmental Senior Specialist  
*Regional Representative*

Sent on: <u>February 7, 2014</u>	X	Email		Hand delivery		US Mail	Certified No. <u>  </u>
----------------------------------	---	-------	--	---------------	--	---------	-------------------------

Electronic Copies: Jason Watkins, Western District Supervisor  
 Sarah Rice, Compliance Officer

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Digital pictures taken on February 4, 2014  
by John Patrone, DWM – SWS

LCID landfill entrance



Left side of fill area



Right side of fill area



Stored material for reuse: firewood, inert debris, and soil

