FROM: LANDON DAVIDSON - MRO TO: FAY SWEAT - PARKER LINCOLN

POLLUTION INCIDENT/U.S.T. LEAK REPORTING FORM

not in inventory

Department of Environment, Health, Natural Resources
Division of Environmental Management
GROUNDWATER SECTION

NEW SITE

Confirm. GW Contamination (Y/N) ____
Major Soil Contamination (Y/N) ____
Minor Soil Contaminatin (Y/N) ____

Incident # 16028

Date Incident Occurred or Leak Detected 6/29/96

INCIDENT DESCRIPTION

Incident Location/Name: REEVES BROTHERS, INC. OSAGE ~~PLANT~~ PH - Sewer line

Address: ALABAMA AVE.

City/Town: BESSEMER CITY | County: GASTON | Region: MRO

Briefly Describe Incident

ENVIROMENT INVEST. DUE TO PROPERTY TRANSACTION FOUND PCE, TCE, CARBON DISULFIDE, CIS - 1,2 DCE IN TEMPORARY MONITOR WELL. ADDITIONAL COMPOUNDS INCLUDE BTEX COMPOUNDS. PCE, TCE, CHLOROFORM AND BENZENE EXCEED THE 2L STANDARD. POTENTIAL SOURCES INCLUDE UST BUT IS PROBABLY RELATED TO FAULTY STORM SEWER LINE. KNOWN DUMP SOURCES UPGRADIENT OF SEWER - SEWER OUTFALL HAS SIMILAR COMPOUNDS AND DUMPS TO SURFACE.

POTENTIAL SOURCE OWNER-OPERATOR

Potential Source Owner-Operator: UNKNOWN AT THIS TIME | Telephone:

Company: | Street Address:

City: | County: | State: | Zip Code:

RECEIVED/EHNR
DEM. GROUND WATER SEC.
96 JUL 17 AM 11:31

OWNERSHIP
0. N/A 1. Municipal 2. Military 3. Unknown (4.) Private 5. Federal 6. County 7. State

OPERATION TYPE
0. N/A 1. Public Service 2. Agricultrural 3. Residential 4. Educational/Relig. (5.) Industrial 6. Commercial 7. Mining

POLLUTANTS INVOLVED

MATERIALS INVOLVED	AMOUNT LOST	AMOUNT RECOVERED
PCE, TCE, TOLUENE, BTEX, CIS 1,2 DCE	UNK	— 0 —
CARBON DISULFIDE	—	—

SOURCE OF POLLUTION

PRIMARY SOURCE OF POLLUTION (Select one)
1. Intentional dump
2. Pit, pond, lagoon
3. Leak-underground
4. Spray irrigation
5. Land application
6. Animal feedlot
7. Source unknown
8. Septic tank
(9.) Sewer line
10. Stockpile
11. Landfill
12. Spill-surface
13. Well
14. Above-ground Storage Tank
15. Nonpoint source

PRIMARY POLLUTANT TYPE (Select one)
1. Pesticide/herbicide
2. Radioactive waste
3. Gasoline/diesel
4. Heating oil
5. Other petroleum prod.
6. Sewage/septage
7. Fertilizers
8. Sludge
9. Solid waste leachate
10. Metals
11. Other inorganics
(12.) Other organics

LOCATION
(1.) Facility
2. Railroad
3. Waterway
4. Pipeline
5. Dumpsite
6. Highway
7. Residence
8. Other

SETTING
1. Residential
(2.) Industrial
3. Urban
4. Rural

Site Priority Ranking: B

D.E.M. Regional Contact: G. LANDON DAVIDSON | Signature: [signature] | Date: 7/16/96

GW-61 Revised 2/95

IMPACT ON DRINKING WATER SUPPLIES

WELLS AFFECTED 1. YES 2. NO UNK

NUMBER OF WELLS AFFECTED _____ KNOWN WSWs IN AREA BUT STATUS UNKNOWN

Well(s) Contaminated: (Users Name)

1.

2.

3.

4.

5.

Circle Appropriate Responses

Lab Samples Taken By: 1. DEM 2. DHS 3. Responsible Party 4. Other 5. None

Samples Taken Include: 1. Groundwater 2. Soil

LOCATION OF INCIDENT

7 1/2 Min. Quad Name Q715

Lat. : Deg : Min : Sec : 35/17/00

5 Min. Quad Number

Long. : Deg : Min : Sec : 81/17/00

Draw Sketch of Area or Attach Additional Maps



SCALE: 1:24000

1 1/2 0 1 mile

1000 0 1000 2000 3000 4000 5000 6000 7000 ft.

N

Source:
USGS, Bessemer City, NC
Quadrangle Map, 1973

Figure 1
SITE LOCATION MAP

AWARE ENVIRONMENTAL INC