Site Assessment Report

*File Name: Piedmont Triad Airport Authority-Gulf *Date 11-12-90

*Company/Property Owner: Piedmont Triad Airport Authority

*Address/Location: 421 / Regional Rd.

*Purpose: Sampling ✓ Compliance ✓

Source ID ____ Monitoring ✓

*Action Taken: Conference ✓ Sample ✓

Survey ✓ Photo ____

*Samples Collected: Well ____ Stream ____

Air ____ Soil ✓

*Evidence of: Spill ____ Liquid Discharge ____

Drums ____ Air Discharge ____

Solid Waste ____ Chemicals ____

U.S.T. ✓

*Summary: 11-12-90; USTs removed at 421 / regional Rd pump, 650; Piedmont Env. removed 4-3000 gal USTs, & will remove ± 1-1K & ± 2-550 gal USTs probably 11-13-90; HNU Readings ranged from ± 3 to 85; No H2O supply in area.

*Referral: Yes ____ No ____ Date Pending analytical results

Agency DEHNR Contact Tom Jolley

Further Action Needed: Monitor analytical results

*Staff Member: Terry B. Ole

*Date to Unit Manager: 11-12-90

*Unit Manager: J Marlow

*Date Returned: 11/15/90

*Remarks: ____



11-12-90

- US 421 at Ramp to Regional Rd.

- Removal by Piedmont Env.

HNU Readings Ranged
3 — 35
B Sample (A Sample