



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer		Compost	<input checked="" type="checkbox"/>	SLAS	<b>COUNTY:</b> Wilson <b>PERMIT NO.:</b> SWCD 98-01 DEMO <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** January 10, 2014

**Date of Last Inspection:** Initial inspection

**FACILITY NAME AND ADDRESS:**

D&D Septic Tank Service  
 7155 Pelt Rd.  
 Stantonsburg, North Carolina  
 Hwy 58S Wilson, T/R NC 111, T/R Pelt Rd. approximately 2 1/2 miles on right.

**GPS COORDINATES:** N: 35.59776 E: 77.87581

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: David Newsome-Owner D&D Septic Tank Service  
 Telephone: 919 242 3751 office cell 252 206 6802  
 Email address: No email  
 Fax: 919 242 4268

**FACILITY CONTACT ADDRESS:**

Mr. David Newsome  
 D&D Septic LLC  
 441 Buck Newsome Rd.  
 Fremont, North Carolina 27830

**PARTICIPANTS:**

Ben Barnes NCDENR Solid Waste Section  
 Tony Gallagher NCDENR Solid Waste Section  
 Donna Wilson NCDENR Solid Waste Section  
 David Newsome D&D Septic Tank Service  
 Daniel Newsome D&D Septic Tank Service  
 Donald Perry Consultant 252 230 7937 email: [dmperryeng55@gmail.com](mailto:dmperryeng55@gmail.com)

**STATUS OF PERMIT:**

Solid Waste Pilot Demonstration Project, the initial approval was granted by the Division on February 5, 2008. An extension was granted on August 19, 2009 and expired on February 5, 2010. D&D has applied for a permit from the Division.

**PURPOSE OF SITE VISIT:**

Pre permitting site visit

**STATUS OF PAST NOTED VIOLATIONS:**

NONE

**OBSERVED VIOLATIONS**

NONE

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

1. The site is a type 3 compost facility
2. The Property owner is Newsome Brothers Farms LLC, 477 Buck Newsome Rd., Fremont, NC 27830. The site owner is David L. Newsome, 441 Buck Newsome Rd., Fremont, NC 27830.
3. Yard waste, dewatered domestic septage, grease trap pumping, clean wood, pre and post consumer food waste, food processing waste, land clearing debris, poultry litter, tobacco dust, and produce waste are the primary feed stock.
4. The primary compost method is windrowing. Aeration will be by turning,
5. The compost material will be land applied on the Newsome Brother's Farms land.
6. The facility appears to be generally well run.

Please contact me if you have any questions or concerns regarding this inspection report.

*Ben Barnes*

Phone: 252 236 4453 email: [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

*Ben Barnes*  
 Environmental Senior Specialist  
**Regional Representative**

Sent on: January 23, 2014		Email		Hand delivery	<b>X</b>	US Mail	Certified No. [ ]
---------------------------	--	-------	--	---------------	----------	---------	-------------------

Copies: Tony Gallagher, Composting and Land Application Land Branch  
 Dennis Shackelford, Eastern District Supervisor  
 Jessica Montie, Compliance Officer



Windrows

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3



Grading between some of the windrows needs to be improved so that runoff in couple of the windrows needs to be better managed.



Grading between some of the windrows needs to be improved so that runoff in couple of the windrows needs to be better managed.