



September 16, 2008

Mr. Ethan Brown
Solid Waste Section
Division of Waste Management
North Carolina Department of Environment and Natural Resources
Mail Service Center 1646
Raleigh, NC 27699-1646

**RE: ANDERSON CREEK LANDFILL - HARNETT COUNTY, SWS PERMIT 43-03
GROUNDWATER MONITORING AT THE C & D SITE, APRIL 2008**

Dear Mr. Brown:

Please find the attached summary table (Table 1) of results from the April 2008 sampling and analysis at Anderson Creek C & D Landfill, Harnett County. Copies of the site plan, analytical results, and chain of custody forms are also enclosed.

To comply with the requirements of the Solid Waste Section Memorandums dated October 27, 2006, February 23, 2007, and October 16, 2007, the new Solid Waste Section Limits (SWSL) and Method Detection Limits (MDLs) have been incorporated. Only values exceeding the SWSL are presented as detections, except when an estimated value (MDL < result < SWSL) exceeds a 2L North Carolina Groundwater Standards (NCGS) or a 13B Groundwater Protection Standard. The table is intended to fulfill the requirements of the notification table per the new Environmental Monitoring Reporting Form, which is also attached.

During the April 2008 sampling event, arsenic, chromium, and lead were detected in MW-6; barium was detected in MW-2, MW-5, and CDMW-5; and benzene was detected in MW-5 at a concentration exceeding NCGS.

Should you have any questions or comments, please contact us at telephone (910) 897-7070 or by e-mail at tyrus@ctclayton.com.

Sincerely,

A handwritten signature in black ink, appearing to read "C. Tyrus Clayton, Jr.", is written over a horizontal line.

C. Tyrus Clayton, Jr., PE

cc. Jerry Blanchard - Harnett County
C.T. Clayton, Sr., PE
C.J. Poran, PE – ENSOL

/attachments

**P.O. Box 578
46 W. Washington St.
Coats, NC 27521**
Phone: 910-897-7070
Fax: 910-897-6767

Offices located in Coats and New Bern, North Carolina
www.ctclayton.com