

Henderson, Ginny

From: Henderson, Ginny
Sent: Thursday, May 19, 2011 10:56 AM
To: 'Kent Harrell'
Subject: RE: Paraxylene in the vicinity of the River Road Force Main repair

Kent,

There is still paraxylene above the state standards in the groundwater at the Port. Currently, Sunoco is monitoring the contamination and sends in a monitoring report periodically. John Lenfestey with the Port was correct that precautions will need to be taken if you will come into contact with groundwater and any water that may be removed will have to be disposed of properly. Was there anything specific that you wanted to know about the site? Just let me know if you have any additional questions.

Ginny Henderson
Hydrogeologist
North Carolina Dept. of Environment & Natural Resources
Div. of Waste Mgt. - Superfund Section - Inactive Hazardous Sites Branch
Wilmington Regional Office
127 Cardinal Drive Extension
Wilmington, NC 28405
Ph: (910) 796-7215 Fax: (910) 350-2004
ginny.henderson@ncdenr.gov

E-mail correspondence to and from this address may be subject to the North Carolina Public Records Law and may be disclosed to third parties.

From: Kent Harrell [<mailto:Kent.Harrell@cfpua.org>]
Sent: Thursday, May 19, 2011 10:17 AM
To: Henderson, Ginny; 'sue.robbs@ncdenr.gov'
Cc: Frank Styers; Jim Tayson
Subject: FW: Paraxylene in the vicinity of the River Road Force Main repair

Ginny and Sue,
Debbie Mayo gave me your names for a question we have.

Attached please find reports on a P-Xylene Spill that occurred several years ago at the State Ports on River Road. What is the status of the project? Feel free to give me a call to discuss.

Thank you,

Kent Harrell, PE
Senior Project Engineer
Cape Fear Public Utility Authority
235 Government Center Drive
Wilmington, NC 28403
910-332-6674 office
910-470-6643 cell