



 COPY

North Carolina Department of Environment and Natural Resources

Beverly Eaves Perdue, Governor

Division of Waste Management
UST Section

Dee Freeman, Secretary
Dexter R. Matthews, Director

March 17, 2011

Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603
Attention: Terry Church

Re: Notice of No Further Action
15A NCAC 2L .0407(d)
Risk-based Assessment and Corrective Action
for Petroleum Underground Storage Tanks

The Perfect Image
3rd Avenue Drive & 11th Street Drive, Hickory
Catawba County
Incident Number: 12634
Risk Classification: Low

Dear Mr. Church:

The Notice of Residual Petroleum received by the UST Section, Mooresville Regional Office on March 15, 2011 has been reviewed. The review indicates that soil contamination exceeds the residential maximum soil contaminant concentrations (MSCCs) established in Title 15A NCAC 2L .0411 and groundwater contamination meets the cleanup requirements for a low-risk site but exceeds the groundwater quality standards established in Title 15A NCAC 2L .0202.

The UST Section determines that no further action is warranted for this incident. This determination shall apply unless the UST Section later finds that the discharge or release poses an unacceptable risk or a potentially unacceptable risk to human health or the environment. Pursuant to Title 15A NCAC 2L .0407(a) you have a continuing obligation to notify the Department of any changes that might affect the risk or land use classifications that have been assigned.

Be advised that as groundwater contamination exceeds the groundwater quality standards established in Title 15A NCAC 2L .0202, groundwater within the area of contamination or within the area where groundwater contamination is expected to migrate is not suitable for use as a water supply. Be advised that as soil contamination exceeds the residential MSCCs, the property containing the contamination is suitable only for industrial/ commercial use or restricted residential use (The term "residential is inclusive of, but not limited to, private houses, apartment complexes, schools, nursing homes, parks, recreation areas and day care centers), as stipulated in the Notice of Residual Petroleum (attached).

As groundwater contamination exceeds the groundwater quality standards established in Title 15A NCAC 2L .0202 and soil contamination exceeds the residential MSCCs, pursuant to NCGS 143B-279.9 and 143B-279.11, you must file the approved Notice of Residual Petroleum (attached) with the Register of Deeds in the county in which the release is located and submit a certified copy to the UST

Section within 30 days of receipt of this letter. This No Further Action determination will not become valid until the UST Section receives a certified copy of the Notice of Residual Petroleum which is filed with the Register of Deeds.

As groundwater contamination exceeds the groundwater quality standards established in Title 15A NCAC 2L .0202 and soil contamination exceeds the lower of the soil-to-groundwater or residential MSCCs, public notice in accordance with 15A NCAC 2L .0409(b) also is required. Thus, within 30 days of receipt of this letter, a copy of the letter must be provided by certified mail, or by posting in a prominent place, if certified mail is impractical, to the local health director, the chief administrative officer of each political jurisdiction in which the contamination occurs, all property owners and occupants within or contiguous to the area containing contamination, and all property owners and occupants within or contiguous to the area where the contamination is expected to migrate. Within 60 days of receiving this no further action letter, this office must be provided with proof of receipt of the copy of the letter or of refusal by the addressee to accept delivery of the copy of the letter or with a description of the manner in which the letter was posted. This No Further Action determination will not become valid until public notice requirements are completed. Interested parties may examine the Soil Cleanup Report/ Site Closure Request by contacting this regional office and may submit comments on the site to the regional office at the address or telephone number listed below.

This No Further Action determination applies only to the subject incident; for any other incidents at the subject site, the responsible party must continue to address contamination as required.

If you have any questions regarding this notice, please contact me at the address or telephone number listed below.

Sincerely,



Brad C. Newton, P.G.
Hydrogeologist
Mooresville Regional Office

Attachments: Notice of Residual Petroleum
cc: Steve Austin – P.O. Box 297
Hickory, NC 28603 (w/ original NRP)
Catawba County Health Department

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 **(828) 296-4500**

Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 **(910) 433-3300**

Mooresville (MOR) – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 **(704) 663-1699**

Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 **(919) 791-4200**

Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 **(252) 946-6481**

Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 **(910) 796-7215**

Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 **(336) 771-5000**

Guilford County Environmental Health, 400 West Market Street, Suite 300, Greensboro, NC 27401, **(336) 641-3771**

Steve A. Austin
Attorney at Law

110 Third Street, N.W.
Post Office Box 297
Hickory, North Carolina 28603

Telephone (828) 322-1695
FAX (828) 322-4378

RECEIVED
NCDENR
Division of Waste Management

MAR 15 2011

UST Section
Mooresville Regional Office

March 10, 2011

Brad Newton, P.G., Hydrogeologist
North Carolina Department of Environment and
Natural Resources
Div Waste Management, UST Section
610 East Center Avenue
Mooresville, NC 28115

RE: The Perfect Image, Hickory, NC Catawba County
Incident # 12634

Dear Mr. Newton:

Find enclosed the executed Notice of Residual Petroleum regarding the above referenced case. I would request that the notice be reviewed by the Mooresville Regional office, and if found to be satisfactory, signed by the Regional Supervisor. Upon execution by the Regional Supervisor, please return to my office for recordation in Catawba County.

Thank you for your assistance in this matter.

Sincerely yours,



Steve A Austin

SAA/nam

Enclosure



North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

February 8, 2008

Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603
Attention: Terry Church

Re: Notice of Regulatory Requirements
NCGS 143B-279.9 and 143B-279.11
Notice of Residual Petroleum

The Perfect Image
3rd Avenue Drive & 11th Street Drive, Hickory
Catawba County
Incident Number: 12634
Risk Classification: Low

Dear Mr. Church:

North Carolina General Statute (NCGS) 143B279.9 and 143B-279.11 require a Notice of Residual Petroleum (Notice) to be filed with the Register of Deeds in Catawba County, where the release is located, when a release from an underground storage tank has not been remediated to below "unrestricted use standards". The Notice is required either prior to conveyance of a contaminated property or prior to receiving a Notice of No Further Action. "Unrestricted use standards" for groundwater are the groundwater quality standards and interim standards contained in Title 15A NCAC 2L .0202, and "unrestricted use standards" for soil are the residential maximum soil contaminant concentrations (MSCCs) established in Title 15A NCAC 2L .0411.

The Notice must be prepared in accordance with the attached instructions and format. It must contain a legal description of the property containing the source of contamination and legal descriptions of any other properties which you own (or control) which are contaminated by the release. The Notice must also include appropriate land use restrictions for these properties. In addition, the Notice must identify all other properties (adjacent, adjoining, downgradient, etc.) on which contamination is known to exist at the time the Notice is prepared.

The Notice must be sent to this regional office of the UST Section within 30 days of the date of this letter for approval and notarization. The approved and notarized Notice must then be filed by you with the Register of Deeds, and a certified copy of the filed Notice must be submitted to this office within 30 days of its return to you.

Effective October 1, 2004, the Department requires that all work following the submittal of the Limited Site Assessment Report (Title 15A NCAC 2L .0405) be preapproved if State Trust Fund reimbursement is anticipated. To comply with this requirement, a completed Preapproval/Claim Authorization Form, encompassing the required remedial activities, must be received in this office within

14 days of the date of this letter. Upon completion of the preapproved activities, you should submit your claim promptly. Reimbursement funds are budgeted based on completed preapprovals, but lengthy delays in reimbursement can occur if claims are not submitted immediately following work completion.

Failure to comply with this letter is a violation of North Carolina law and may result in the assessment of civil penalties and/or the use of other enforcement mechanisms available to the state. If you have any questions regarding this letter, please contact Mr. Brad Newton at the address or telephone number listed below.

Sincerely,



Brad C. Newton, P.G.
Hydrogeologist II
Mooresville Regional Office

Attachment: Instructions for Preparing Notice of Residual Petroleum

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500
Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 (910) 433-3300
Mooresville (MOR) – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 (704) 663-1699
Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 (919) 791-4200
Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 (252) 946-6481
Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 (910) 796-7215
Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 (336) 771-5000
Guilford County Environmental Health, 1203 Maple Street, Greensboro, NC 27405, (336) 641-3771

Newton, Brad

From: Newton, Brad
Sent: Thursday, March 10, 2011 7:17 AM
To: 'saustinatty@earthlink.net'
Subject: the perfect image nrp

Mr. Austin,

I have received the Notice of Residual Petroleum for the subject site. It appears to be correct, however, it needs to be signed and notarized by Mr. Church prior to submittal of this office. Please contact me if you have any questions.

Brad Newton - Brad.Newton@ncdenr.gov
Hydrogeologist II
North Carolina Dept. of Environment & Natural Resources
Division of Waste Management
610 E. Center Ave., Suite 301
Mooresville, NC 28115
Ph: 704.663.1699 Fax: 704.663.6040

E-mail correspondence to and from this address may be subject to the
North Carolina Public Records Law and may be disclosed to third parties.

Steve A. Austin
Attorney at Law

110 Third Street, N.W.
Post Office Box 297
Hickory, North Carolina 28603

Telephone (828) 322-1695
FAX (828) 322-4378

RECEIVED
NCDENR
Division of Waste Management

MAK 08 2011

UST Section
Mooreville Regional Office

March 7, 2011

Brad Newton, P.G., Hydrogeologist
North Carolina Department of Environment and
Natural Resources
Div Waste Management, UST Section
610 East Center Avenue
Mooreville, NC 28115

RE: The Perfect Image, Hickory, NC Catawba County
Incident # 12634

Dear Mr. Newton:

Find enclosed the executed Notice of Residual Petroleum regarding the above referenced case. I would request that the notice be reviewed by the Mooreville Regional office, and if found to be satisfactory, signed by the Regional Supervisor. Upon execution by the Regional Supervisor, please return to my office for recordation in Catawba County.

Thank you for your assistance in this matter.

Sincerely yours,



Steve A Austin

SAA/nam

Enclosure

Prepared by: Steve A Austin, Attorney
Return to: Steve A Austin, Attorney

NOTICE OF RESIDUAL PETROLEUM

The Perfect Image, Catawba County, North Carolina
(Site Name)

The property that is the subject of this Notice (hereinafter referred to as the "Site") contains residual petroleum and is an Underground Storage Tank (UST) incident under North Carolina's Statutes and Regulations, which consist of N.C.G.S. 143-215.94 and regulations adopted thereunder. This Notice is part of a remedial action for the Site that has been approved by the Secretary (or his/her delegate) of the North Carolina Department of Environment and Natural Resources (or its successor in function), as authorized by N.C.G.S. Section 143B-279.9 and 143B-279.11. The North Carolina Department of Environment and Natural Resources shall hereinafter be referred to as "DENR".

NOTICE

Petroleum product was released and/or discharged at the Site. **Petroleum constituents remain on the site, but are not a danger to public health and the environment, provided that the restrictions described herein, and any other measures required by DENR pursuant to N.C.G.S. Sections 143B-279.9 and 143B-279.11, are strictly complied with.** This "Notice of Residual Petroleum" is composed of a description of the property and the land use restrictions on the Site. The Notice has been approved and notarized by DENR pursuant to N.C.G.S. Sections 143B-279.9 and 143B-279.11 and shall be recorded at the Catawba County Register of Deeds' office.

Source Property

Terry L. Church and wife, Dana P. Church of 1781 12th Street Drive, NW, Hickory, North Carolina is the owner in fee simple of all or a portion of the Site, which is located in the County of Catawba, State of North Carolina, and is known and legally described as:

BEGINNING at a stake in the southwest intersection of 3rd Avenue Drive, NW (Old Lenoir Road) and 11th Street, NW, in the City of Hickory, and running thence in a southeastern direction along the west margin of 3rd Avenue Drive, NW, 237 feet to a point; thence in a northwesterly direction 89 feet to a point in the east margin of 11th Street, NW; thence with the East margin of said 11th Street, NW in a northern direction with a distance of 214 feet to the point of Beginning.

Being all of Lot 1 in Block 3 as shown on Catawba County Tax Map 49H.

For reference to chain of title see Book 1630 at Page 112 and Book 1636 at Page 32 of the Catawba County Registry.

For protection of public health and the environment, the following land use restrictions required by N.C.G.S. Section 143B-279.9(b) shall apply to all of the above-described real property. These restrictions shall continue in effect as long as residual petroleum remains on the site in excess of unrestricted use standards and cannot be amended or cancelled unless and until the Catawba County Register of Deeds receives and records the written concurrence of the Secretary (or his/her delegate) of DENR (or its successor in function).

PERPETUAL LAND UNSE RESTRICTIONS


Soil: The Site shall be used for industrial/commercial use only. Industrial/commercial use means a use where exposure to soil contamination is limited in time and does not involve exposure to children or other sensitive populations such as the elderly or sick. The real property shall not be developed or utilized for residential purposes including but not limited to: primary or secondary residences (permanent or temporary), schools, daycare centers, nursing homes, playgrounds, parks, recreation areas and/or picnic areas.

Groundwater: Groundwater from the site is prohibited from use as a water supply. Water supply wells of any kind shall not be installed or operated on the site.

ENFORCEMENT

The above land use restrictions shall be enforced by any owner, operator, or other party responsible for the Site. The above land use restrictions may also be enforced by DENR through any of the remedies provided by law or by means of a civil action, and may also be enforced by any unit of local government having jurisdiction over any part of the Site. Any attempt to cancel this Notice without the approval of DENR (or its successor in function) shall be subject to enforcement by DENR to the full extent of the law. Failure by any party required or authorized to enforce any of the above restrictions shall in no event be deemed a waiver of the right to do so thereafter as to the same violation or as to one occurring prior or subsequent thereto.

IN WITNESS WHEREOF, Terry L. Church as an owner of the Site has caused this Notice to be executed pursuant to N.C.G.S. Sections 143B-279.9 and 143B-279.11, this 3rd day of March, 2011.



Terry L. Church

Site Owner

**NORTH CAROLINA
CATAWBA COUNTY**

I, Nelda A. Miller, a Notary Public for the County and State above hereby certify that **TERRY L. CHURCH** personally appeared before me this day and acknowledged that he signed the foregoing document for the purposes stated therein.

This the ____ day of March, 2011.

Notary Public
Notary Public: Nelda A. Miller

My Commission Expires: _____

Approved for the purposes of N.C.G.S. 143 B-279.11

Ronald H. Taraban, Ph.D.
Regional Supervisor

Mooreville Regional Office
UST Section
Division of Waste Management
Department of Environment and Natural Resources

**NORTH CAROLINA
_____ COUNTY**

I, _____, a Notary Public for the County and State above hereby certify that **RONALD H. TARABAN** personally appeared before me this day and acknowledged that he signed the foregoing document.

This the ____ day of _____, 2011.

Notary Public
Notary Public: Sherian R. Black

My Commission Expires: _____

DIVISION OF WASTE MANAGEMENT

Date: 12/6/07

MEMORANDUM

To: Bruce Parris
Inactive Hazardous Waste Section, DWM

From: Brad Newton
UST Section, DWM

Subject: Non-UST contaminants

UST Site: The Perfect Image
1907 3rd Avenue
Hickory, NC
UST Incident No. 12634

Contaminants Identified:

Soil samples collected during Limited Site Assessment activities reported the presence of Dibromomethane and Methyl Ethyl Ketone in the soils at this site. Please note that the subject site was once utilized as a automobile body shop and it may still be in utilized as that. These two compounds are consistent with chemicals typically in use at such a facility.



North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

December 6, 2007

Terry L. Church, Registered Agent
Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603

Re: Limited Site Assessment Report
The Perfect Image
3rd Avenue Drive & 11th Street Drive, Hickory
Catawba County
Incident Number: 12634
Risk Classification: Unknown

Dear Mr. Church:

On November 28, 2007, the Underground Storage Tank (UST) Section of the Division of Waste Management (the Division), Mooresville Regional Office, received the Limited Site Assessment (LSA) Report for the above-referenced site. Upon review of this information, the Division has determined that the report is incomplete. In order to complete the LSA Report, you must address the following issue:

- Documentation that the Water Supply Well Information Survey was sent to all property owners within 500' of the source area was not included in the LSA Report.

Please report to the Mooresville Regional Office the actions taken to bring the site into compliance within **30** days of the date of this notice.

Because a release or discharge has been confirmed, a Licensed Geologist or a Professional Engineer, certified by the State of North Carolina, is required to prepare and certify all reports submitted to the Department in accordance with Title 15A NCAC 2L .0103(e) and 2L .0111(b).

Please note that before you sell, transfer, or request a "No Further Action" determination for a property that has not been remediated to below "unrestricted use" standards, you must file a Notice of Residual Petroleum ("Notice") with the Register of Deeds in the county where the property is located (NCGS 143B-279.9 and 143B-279.11).

If you have any questions regarding trust fund eligibility or reimbursement from the Commercial or Noncommercial Leaking Petroleum Underground Storage Tank Cleanup Funds, please contact the UST Section Trust Fund Branch at (919) 733-8486. If you have any questions regarding the actions that must be taken or the rules mentioned in this letter, please contact Mr. Brad Newton at (704) 235-2174, or at the address below.

Sincerely,



Brad C. Newton, P.G.
Hydrogeologist II
 Mooresville Regional Office

cc: Ron Haynes - Blue Ridge Engineering, PLLC
Catawba County Health Department

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500

Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 (910) 486-1541

Mooresville (MOR) – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 (704) 663-1699

Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 (919) 791-4200

Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 (252) 946-6481

Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 (910) 796-7215

Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 (336) 771-4600

Guilford County Environmental Health, 1203 Maple Street, Greensboro, NC 27405, (336) 641-3771



COPY

North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

October 31, 2007

CM # 7006 2760 0001 8497 3420

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Terry L. Church, Registered Agent
Church's Body Shop
P.O. Box 1528
Hickory, North Carolina 28603

Re: Recommendation for Enforcement Action
The Perfect Image
3rd Avenue Drive & 11th Street Drive
Hickory, NC
Catawba County
Risk: Unknown
Incident # 12634

Dear Mr. Church:

This letter is to notify you that this office is considering recommending enforcement action to the Director of the Division of Waste Management. The recommendation for enforcement concerns the violation(s) cited in the Notice of Violation (NOV) dated August 20, 2007 that was previously sent to you. Specifically:

Failure to submit a complete Limited Site Assessment Report as required by 15A NCAC 2L .0405.

If there is an explanation for the violation cited, or if you believe there are other factors that should be considered, please submit your response to me in writing **within 10 days of receipt** of this notice. Your explanation will be reviewed, and if enforcement action is still deemed appropriate, your explanation will be forwarded to the Director with the enforcement package for his consideration.

If you have any questions concerning this matter, please contact Mr. Brad Newton at 704-235-2174.

Sincerely,

Regional Supervisor
Mooresville Regional Office

US POSTAL SERVICE™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)
 For delivery information visit our website at www.usps.com

OFFICIAL USE


Postage \$	
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	5.21
Total	

Sent To: TERRY L CHURCH-REG AGENT
 CHURCH'S BODY SHOP
 P O BOX 1528
 HICKORY NC 28603
 bcn/nore 11/01/07 ust

Postmark Here: MOORESVILLE NC 28115

PS Form 3800, August 2006 See Reverse for Instructions

UNITED STATES POSTAL SERVICE



02 NOV 2007 PM 2

• Sender: Please print your name, address, and ZIP+4 in this box •

NCDENR - UST SECTION
 MOORESVILLE REGIONAL OFFICE
 610 EAST CENTER AVE, STE 301
 MOORESVILLE NC 28115



Certified Mail Provides:

- 1 A mailing receipt
- 1 A unique identifier for your mailpiece
- 1 A record of delivery kept by the Postal Service for two years

Important Reminders:

- 1 Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®.
- 1 Certified Mail is not available for any class of international mail.
- 1 NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- 1 For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- 1 For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- 1 If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.

PS Form 3800, August 2006 (Reverse) PSN 7530-02-000-9047

SENDER: COMPLETE THIS SECTION

- 1 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- 1 Print your name and address on the reverse so that we can return the card to you.
- 1 Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

TERRY L CHURCH-REG AGENT
 CHURCH'S BODY SHOP
 P O BOX 1528
 HICKORY NC 28603
 bcn/nore 11/01/07 ust



2. Article Number
(Transfer from service label)

7006 2760 0001 8497 3420

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

September 21, 2007

RECEIVED
NCDENR

SEP 25 2007

Brad Newton, P.G., Hydrogeologist.
North Carolina Department of Environment and
Natural Resources
Div Waste Management, UST Section
610 East Center Avenue
 Mooresville, NC 28115

Division of Waste Management
UST Section
 Mooresville Regional Office

Subject: Actions report
The Perfect Image, Hickory, NC, Catawba County
Incident # 12634

Dear Mr. Newton:

We have taken the following actions in response to your letter of August 20, 2007 based on information from Ron Haynes:


Contractors installed a monitoring well in the location of the former pump island soil sample. Blue Ridge Engineering (BRE) collected a sample from the well for analysis

The updated receptor survey submitted on July 31, 2007 did not rely solely on the 1994 survey. The material inserted from the 1994 Site Characterization Report was for the purpose of documenting the boring for construction of the original monitoring well. The LSA report will include a current receptor survey.

BRE and the contractors conducted borings and/or took soil samples for analysis at both the existing well and the new monitoring well

We are awaiting the laboratory reports from Blue Ridge Labs and expect they will be received this week. BRE will finish the LSA report as soon as the lab reports and other items are in hand. Thank you for your continuing consideration as we proceed on this project.

Sincerely,



Terry Church

Cc: W. Ronald Haynes, P.E., Blue Ridge Engineering
John Sigmon, Environmental Abatements



North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

August 20, 2007

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

CM # 7007 0710 0005 2882 4982

Terry L. Church, Registered Agent
Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603

Re: Notice of Violation of
15A NCAC 2L.0405
Risk-based Assessment and Corrective Action
for Petroleum Underground Storage Tanks

The Perfect Image
3rd Avenue Drive & 11th Street Drive, Hickory
Catawba County
Incident Number: 12634
Risk Classification: Unknown

Dear Mr. Church:

On August 6, 2007, the Underground Storage Tank (UST) Section of the Division of Waste Management (the Division), Mooresville Regional Office, received the Limited Site Assessment (LSA) Report for the above-referenced site. Upon review of this information, the Division has determined that the report is incomplete. In order to complete the LSA Report, you must address the following issue:

- A source area monitoring well must be installed in the location of the soil sample collected at the pump island during UST Closure activities;
- A receptor survey must be completed in accordance with the latest edition of the UST Section's guidelines for assessment and corrective action (the guidelines). Please note that referring to a previously conducted receptor survey is not acceptable;
- Soil samples must be collected from the source area monitoring wells in accordance with the guidelines.

Please report to the Mooresville Regional Office the actions taken to bring the site into compliance within **30 days** of the date of receipt of this notice to avoid recommendation of civil penalties for continuing violations.

Penalties may be assessed for the violation described within this Notice of Violation. Your prompt attention to the items described herein is required. Failure to comply with the State's rules, in the manner and time specified, may result in the assessment of additional civil penalties and/or the use of

other enforcement mechanisms available to the State. Each day that a violation continues may be considered a separate violation.

Because a release or discharge has been confirmed, a Licensed Geologist or a Professional Engineer, certified by the State of North Carolina, is required to prepare and certify all reports submitted to the Department in accordance with Title 15A NCAC 2L .0103(e) and 2L .0111(b).

Please note that before you sell, transfer, or request a "No Further Action" determination for a property that has not been remediated to below "unrestricted use" standards, you must file a Notice of Residual Petroleum ("Notice") with the Register of Deeds in the county where the property is located (NCGS 143B-279.9 and 143B-279.11).

If you have any questions regarding trust fund eligibility or reimbursement from the Commercial or Noncommercial Leaking Petroleum Underground Storage Tank Cleanup Funds, please contact the UST Section Trust Fund Branch at (919) 733-8486. If you have any questions regarding the actions that must be taken or the rules mentioned in this letter, please contact Mr. Brad Newton at (704) 235-2174, or at the address below.

Sincerely,



Regional Supervisor
Mooresville Regional Office

Enclosures: Title 15A NCAC 2L .0405

cc: Ron Haynes - Blue Ridge Engineering, PLLC
Catawba County Health Department

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500

Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 (910) 486-1541

Mooresville (MOR) – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 (704) 663-1699

Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 (919) 791-4200

Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 (252) 946-6481

Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 (910) 796-7215

Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 (336) 771-4600

Guilford County Environmental Health, 1203 Maple Street, Greensboro, NC 27405, (336) 641-3771

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information, visit our website at www.usps.com®

OFFICIAL USPS



Postage	\$	
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		5.21

Total F
 Sent To
 TERRY L CHURCH-REG AGENT
 CHURCH'S BODY SHOP INC
 P O BOX 1528
 HICKORY NC 28603
 bcn/hov 08/20/07 ust

Street, A
 or PO Bc
 City, State

PS Form 3800, August 2006 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:
 TERRY L CHURCH-REG AGENT
 CHURCH'S BODY SHOP INC
 P O BOX 1528
 HICKORY NC 28603
 bcn/hov 08/20/07 ust

COMPLETE THIS SECTION

A. Signature
 Daniel L
 B. Received by (Printed Name)

D. Is delivery address different from item 1? If YES, enter delivery address below.
 AND
 23
 2007

3. Service Type
 Certified Mail
 Registered
 Insured Mail
 Express Mail
 Return Receipt for Merchand.
 C.O.D.
 4. Restricted Delivery? (Extra Fee) Yes

2. Article Number (Transfer from service tag) 7007 0720 0005 2882 4982
 PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1540

MAIL SERVICE

First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

Sender: Please print your name, address, and ZIP+4 in this box •

NC DENR - WEST SECTION
MOORESVILLE REGIONAL OFFICE
610 EAST CENTER AVE, SUITE 301
MOORESVILLE NC 28115
AUG 24 2007

Division of Waste Management
USF Section
Mooreville Regional Office

Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®.
- Certified Mail is *not* available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain a Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.

PS Form 3800, August 2006 (Reverse) PSN 7530-02-000-9047



BLUE RIDGE ENGINEERING PLLC

529 Main Street
N. Wilkesboro, NC 28659

Phone: (336) 838-2500
Fax: (336) 838-4179

July 31, 2007

RECEIVED
NCDENR

AUG 06 2007

Brad Newton, P.G., Hydrogeologist.
North Carolina Department of Environment and
Natural Resources
Div Waste Management, UST Section
610 East Center Avenue
Mooresville, NC 28115

Division of Waste Management
UST Section
Mooresville Regional Office

Subject: Results of groundwater sampling analysis
The Perfect Image, Hickory, NC, Catawba County
Incident # 12634

Dear Mr. Newton:

Please find attached one copy of a Limited Site Assessment report that includes the following:

Table B4 summarizing results for the groundwater samples – 1994 and 2007 sample events

Three page Risk Assessment Question and Answer format

Drawings(4) Location Map, Area Map, Site Map and Monitoring Well GW Data

Copies of laboratory reports – 2007 sampling and analysis – For samples taken March 28, 2007,

I am sending this information as part of the ongoing site investigation. Please call me at 336/838-2500 with any questions or further requirements.

Sincerely,

W. Ronald Haynes

W. Ronald Haynes, P.E.

Cc: Terry Church

**UST SECTION
CORRECTIVE ACTION BRANCH
ENFORCEMENT CASE COVER MEMO, CHECKLIST, AND ASSESSMENT FACTORS**



RP INFORMATION:

Church's Body Shop, Inc.
 RP Name
 P.O. Box 1528
 Address
 Hickory NC 28603
 City State Zip Code

SITE / FACILITY INFORMATION:

The Perfect Image
 Site / Facility Name
 3rd Avenue & 11th Street Drive
 Address
 Hickory NC 28603
 City State Zip Code
 0-034061
 Facility ID# Incident #

REGISTERED AGENT INFORMATION:

Terry L. Church
 Registered Agent Name
 P.O. Box 1528
 Address
 Hickory NC 28603
 City State Zip Code

SITE RISK / JUSTIFICATION:

Unknown
 Site Risk / Justification

SIPS DATABASE:

- Facility screen printout
- Tank screen printout (PF12)

SECRETARY OF STATE DATABASE:

- Corporation / registered agent screen printout
- Document filing screen printout

NOTICES:

- NORRs
- NOVs
- 10-day letters
- Certified mail receipts
- Sheriff's services

RP RESPONSE:

- No responses received
- RP responses enclosed

OTHER DOCUMENTS:

- PIRF (UST Form 61)
- F&D template (from FTP site)
- Diskette

OTHER INFORMATION:

- UST notification forms
- Tax records
- Lease agreements
- Deeds
- Date connected to municipal water: _____
- Date converted to electricity/natural gas: _____
- Affidavits / Other supporting documents

RP HISTORY:

- Penalty history from Central Office
- Copies of NOVs used in history

VIOLATION(s):

15A NCAC 2L
 .0405 2/12/07 6/11/07
 Violation Begin Date End Date

Violation Begin Date End Date

CENTRAL OFFICE USE ONLY:

\$
 Amount Saved

\$
 Amount Saved

\$
 TOTAL AMOUNT SAVED

INVESTIGATIVE COSTS:

Administrative costs:				\$ 100.00
Supervisor:	2	hrs @	\$ 26.92 / hr	\$ 53.84
Manager: (site visits, sampling, Notices, and enforcement preparation)	2	hrs @	\$ 25.88 / hr	\$ 51.76
Certified mail:	1	mi @	\$ 4.64 / ea	\$ 4.64
Certified mail:	1	pcs @	\$ 5.21 / ea	\$ 5.21
TOTAL INVESTIGATIVE COSTS				\$ 215.45

GRAVITY OF VIOLATION (e.g., impacted water supply wells; wells within 1,500 feet of source area):

No water supply wells are known to be within 1,500 feet of the source area.


AGGRAVATING FACTORS (e.g., degree of recalcitrance):

MITIGATING FACTORS (e.g., degree of cooperation):

The responsible party's consultant has faxed laboratory analytical results that reportedly are from the on-site monitoring well. However, the Mooresville Regional Office has contacted the responsible party several times requesting a date that the report would be submitted, and to date have not received an answer.

Submitted by:

Mooresville
Regional Office


Incident Manager

6/11/07
Date

Supervisor

Date

STATE OF NORTH CAROLINA

NORTH CAROLINA
ENVIRONMENTAL MANAGEMENT COMMISSION
FILE NO.:

COUNTY OF CATAWBA

IN THE MATTER OF:)	
CHURCH'S BODY SHOP, INC.)	FINDINGS AND DECISION AND
)	ASSESSMENT OF CIVIL PENALTIES
FOR VIOLATION OF:)	
15A NCAC 2L .0405)	
)	
)	

Acting pursuant to North Carolina General Statutes (NCGS) 143-215.6A and 143-215.94W and by authority delegated to me under NCGS 143B-10, I, Robert K. Davies, Underground Storage Tank (UST) Corrective Action Branch Head, Division of Waste Management (DWM), make the following:

I. FINDINGS OF FACT:

- A. Church's Body Shop is a corporation organized and existing under the laws of the State of North Carolina.
- B. Pursuant to NCGS 143-215.94(9) or 15A North Carolina Administrative Code (NCAC) 2N .0203 of the Environmental Management Commission (EMC), Church's Body Shop is the owner of seven petroleum UST systems formerly located at The Perfect Image, 3rd Avenue Drive & 11th Street Drive, Hickory, Catawba County, North Carolina (hereafter "the site"). The subject UST systems were permanently closed on July 11-12, 1994.
- C. Pursuant to 15A NCAC 2L .0405 [formerly 2L .0115(c)(4)], a responsible party shall within 120 days of the discovery of a discharge or release, submit a Limited Site Assessment (LSA) report containing the information needed by DWM to classify the level of risk to human health and the environment.

- D. On July 22, 1994, DWM received notification of a release or discharge from the subject UST systems.
- E. On October 4, 2006, DWM sent Church's Body Shop, Inc. a Notice of Regulatory Requirements (NORR) stating that a LSA report must be submitted in accordance with 15A NCAC 2L .0405.
- F. On February 9, 2007, DWM sent Church's Body Shop, Inc. a Notice of Violation (NOV) stating that a LSA report must be submitted in accordance with 15A NCAC 2L .0405. The NOV was sent by certified mail and received on February 12, 2007.
- G. On May 23, 2007, DWM sent Church's Body Shop, Inc. a Notice of Recommendation for Enforcement Action. The Notice was sent by certified mail and received on May 25, 2007.
- H. As of June 7, 2007, DWM had not received the LSA Report required by 15A NCAC 2L .0405 and as specifically communicated in the NOV dated February 9, 2007.
- I. History: None.
- J. Staff costs and expenses associated with detecting the violations, defining their nature, and bringing the enforcement action total \$215.45.

Based upon the above Findings of Fact, I make the following:

II. CONCLUSIONS OF LAW:

- A. Church's Body Shop, Inc. is a "person" within the meaning of NCGS 143-215.6A and 143-215.94W pursuant to NCGS 143-212(4).
- B. UST rules at 15A NCAC 2N and 2L have been adopted by the EMC pursuant to NCGS 143-215.3, 143-215.94T, 143-215.94V, 143B-282(a)(2)(h), and 143-214.1.
- C. NCGS 143-215.6A and 143-215.94W allow the Secretary of the Department of Environment and Natural Resources to assess a civil penalty of not more than \$10,000.00 per day against any person who violates a rule of the Commission implementing, among others, Part 1, Article 21, Chapter 143, of NCGS (including NCGS 143-214.1 and 143-215.3) or Part 2B, Article 21A, Chapter 143, of NCGS (including NCGS 143-94T and 143-94V).
- D. Church's Body Shop has been in violation of 15A NCAC 2L .0405 from February 12, 2007 through at least June 11, 2007 by failing to submit a LSA report, in accordance with the procedures and requirements of the cited rule.
- E. NCGS 143.215.3(a)(9) provides that the reasonable costs of any investigation, inspection, or monitoring survey may be assessed against a person who violates any regulations adopted by the EMC.

Based upon the above Findings of Fact and Conclusions of Law, I make the following:

III. DECISION

Pursuant to NCGS 143-215.6A and 143-215.94W, in determining the amount of the penalty, I have taken into account the Findings of Fact and Conclusions of Law and have specifically considered each and every factor listed in NCGS 143B-282.1(b).

Accordingly, Church's Body Shop, Inc. shall be, and hereby is, assessed a civil penalty of:

\$ _____ for violation of 15A NCAC 2L .0405 from February 12, 2007 through at least June 11, 2007 by failing to submit a LSA Report, in accordance with the procedures and requirements of the cited rule.

\$ 215.45 Investigation costs which are authorized by NCGS 143-215.3(a)(9).

\$ _____ TOTAL AMOUNT DUE

IV. NOTICE

I reserve the right to assess civil penalties and investigative costs for any continuing violations occurring after the assessment period indicated above. Each day of a continuing violation may be considered a separate violation subject to a maximum \$10,000.00 per day penalty. Civil penalties and investigative costs may be assessed for any other rules and statutes for which penalties have not yet been assessed.

V. TRANSMITTAL

This CIVIL PENALTY ASSESSMENT is directed to be transmitted to Church's Body Shop, Inc. in accordance with NCGS 143-215.6A(d) and 143-215.94W(d).

Date

Robert K. Davies, UST Corrective Action Branch Head
Division of Waste Management


May 30, 2007

NCDENR Mooresville District Office
Attn. Brad
610 E. Ctr. Ave Suite301
Mooresville, NC.28115

Brad


Just wanted to fax a copy of initial report from first sampling of existing monitoring well for your information until Ron Haynes P.E. Completes the LSA.

Respectfully



John Sigmon
Environmental Abatements

828-850-4709



Client : Environmental Abatements
 PO Box 221
 Newton, NC 28658
Attention: John Sigmon
Date Received: 28-Mar-07
Report Date: 16-Apr-07
Sample Date: 28-Mar-07
BRL #: BRL-2007-0286
Lab Sample ID: LSID-2007-01819
Client Sample ID: Perfect Image

1 Church's Body Shop

Parameter	Result	MLQ	Unit	Method	Analysis Time	Analysis Date	Analyst
Bromodichloromethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Bromoform	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Bromomethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Carbon Tetrachloride	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Chloroethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Chloroethylvinyl Ether, 2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Chloroform	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Chloromethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dibromochloromethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichlorodifluoromethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloroethane, 1,1-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloroethane, 1,2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloroethene, 1,1-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloroethene, trans-1,2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloropropane, 1,2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloropropene, cis-1,3-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Dichloropropene, trans-1,3-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Ethylene Dibromide (EDB)	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM

Reported By:

K.S. Matheson
 K.S. Matheson, S.J. Johnson

* Concentrations are below Minimum Quantification Limit except where noted.

NC Laboratory Certificate No. 275



Client : Environmental Abatements
 PO Box 221
 Newton, NC 28658
Attention: John Sigmon
Date Received: 28-Mar-07
Report Date: 16-Apr-07
Sample Date: 28-Mar-07
BRL #: BRL-2007-0286
Lab Sample ID: LSID-2007-01819
Client Sample ID: Perfect Image

Parameter	Result	ML	Unit	Method	Analysis Time	Analysis Date	Analyst
Methylene Chloride	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Tetrachloroethane, 1,1,2,2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Tetrachloroethene	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Trichloroethane, 1,1,1-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Trichloroethane, 1,1,2-	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Trichloroethene	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Trichlorofluoromethane	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM
Vinyl Chloride	*	0.5	ug/l	EPA-601 Exp.	7:47	3/29/2007	KSM

Reported By:


 K.S. Matheson, S.J. Johnson

* Concentrations are below Minimum Quantification Limit except where noted.
 NC Laboratory Certificate No. 275



Client : Environmental Abatements
 PO Box 221
 Newton, NC 28658
Attention: John Sigmon
Date Received: 28-Mar-07
Report Date: 16-Apr-07
Sample Date: 28-Mar-07
BRL #: BRL-2007-0286
Lab Sample ID: LSID-2007-01820
Client Sample ID: Perfect Image

Parameter	Result	ML	Unit	Method	Analysis Time	Analysis Date	Analyst
Benzene	5.1	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Chlorobenzene	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Dichlorobenzene, 1,2-	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Dichlorobenzene, 1,3-	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Dichlorobenzene, 1,4-	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Ethyl Benzene	14.1	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
IPE	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
MTBE	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Naphthalene	*	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Toluene	2.2	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Xylene, o-	5.4	0.5	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM
Xylenes, m & p-	36.5	1	ug/l	EPA-602 Exp	8:31	3/29/2007	KSM

Reported By:

K.S. Matheson, S.J. Johnson

* Concentrations are below Minimum Quantification Limit except where noted.

NC Laboratory Certificate No. 275



Client : Environmental Abatements
 PO Box 221
 Newton, NC 28658
Attention: John Sigmon
Date Received: 28-Mar-07
Report Date: 16-Apr-07
Sample Date: 28-Mar-07
BRL #: BRL-2007-0286
Lab Sample ID: LSID-2007-01821
Client Sample ID: Perfect Image


Parameter	Result	MQL	Unit	Method	Analysis Time	Analysis Date	Analyst
VPH C5-C8 Aliphatics	*	0.074	mg/l	MADEP-VPH	5:44	4/7/2007	KSM
VPH C9-C10 Aromatics	0.312	0.072	mg/l	MADEP-VPH	5:44	4/7/2007	KSM
VPH C9-C12 Aliphatics	*	0.068	mg/l	MADEP-VPH	5:44	4/7/2007	KSM

Reported By: _____

K.S. Matheson, S.J. Johnson
 K.S. Matheson, S.J. Johnson

* Concentrations are below Minimum Quantification Limit except where noted.

NC Laboratory Certificate No. 275



Client : Environmental Abatements
 PO Box 221
 Newton, NC 28658
Attention: John Sigmon
Date Received: 28-Mar-07
Report Date: 16-Apr-07
Sample Date:
BRL #: BRL-2007-0286
Lab Sample ID: LSID-2007-01822
Client Sample ID: Trip Blank

Parameter	Result	ML	Unit	Method	Analysis Time	Analysis Date	Analyst
VPH C5-C8 Aliphatics	*	0.074	mg/l	MADEP-VPH	3:31	4/7/2007	KSM
VPH C9-C10 Aromatics	*	0.072	mg/l	MADEP-VPH	3:31	4/7/2007	KSM
VPH C9-C12 Aliphatics	*	0.068	mg/l	MADEP-VPH	3:31	4/7/2007	KSM

Reported By:

K.S. Matheson, S.J. Johnson

* Concentrations are below Minimum Quantification Limit except where noted.

NC Laboratory Certificate No. 275

BLUE RIDGE LABS

VPH (Aliphatics/Aromatics) REPORTING FORM

CLIENT: Environmental Abateaments
PROJECT:

NC LAB CERTIFICATION # 275
SITE LOCATION:

SAMPLE INFORMATION AND ANALYTICAL RESULTS

Sample ID	1822	1821	
Sample Matrix	Water	Water	
Collection	NA	NA	
Option (Soil)*			
Date Collected	3/28/07	3/28/07	
Date Received	3/28/07	3/28/07	
Date Extracted	4/6/07	4/6/07	
Date Analyzed	4/7/07	4/7/07	
Dry Weight	NA	NA	
Dilution Factor	1.0	1.0	
C5-C8 Aliphatics**	< 0.074 mg/l	< 0.074 mg/l	
C9-C12 Aliphatics**	< 0.068 mg/l	< 0.068 mg/l	
C9-C10 Aromatics**	< 0.072 mg/l	0.312 mg/l	
Surrogate %	80.5	79.8	
Recovery-PID			
Surrogate %	81.2	79.9	
Recovery-FID			

*Option 1 = Established fill line on vial Option 2 = Sampling Device (indicate brand) Option 3 = Field weight of soil

**Range results should exclude any surrogates, internal standards, or Target PAH analytes

*** Estimated value, beyond linear range ^a No trip blank submitted ^b Observed in method or trip blank

% Recovery-Fortified Blank (Spike)-PID	C5-C8 Aliphatic	C9-C12 Aliphatic	C9-C10 Aromatic
	NA	NA	97.4 %
Relative % Difference-PID Dup			
	NA	NA	0.9 %
Percent Recovery-Fortified Blank (Spike)-FID			
	99.7 %	96.9 %	NA
Relative % Difference-FID Dup			
	0.4 %	0.7 %	NA

BLUE RIDGE LABS VPH REPORTING FORM

Initial Calibration Date: 12/20/06

Sample Identification: 1822, 1821

Calibration Ranges and Limits

RANGE	MDL	ML	RL
C5-C8 Aliphatics	0.0231 mg/l	0.0735 mg/l	0.074 mg/l
C9-C12 Aliphatics	0.0214 mg/l	0.0679 mg/l	0.068 mg/l
C9-C10 Aromatics	0.0227 mg/l	0.0721 mg/l	0.072 mg/l

Note: Please include appropriate units

Method of Quantitation: Curve or Average Response Factor

Calibration Concentration Levels

RANGE	LEVELS	% RSD OR CCC
C5-C8 Aliphatics	0.050 mg/l	CCC=0.9981
	0.200 mg/l	
	0.400 mg/l	
	0.600 mg/l	
	0.800 mg/l	
C9-C12 Aliphatics	0.050 mg/l	CCC=0.9981
	0.200 mg/l	
	0.400 mg/l	
	0.600 mg/l	
	0.800 mg/l	
C9-C10 Aromatics	0.050 mg/l	CCC=0.9980
	0.200 mg/l	
	0.400 mg/l	
	0.600 mg/l	
	0.800 mg/l	

Note: Please include appropriate units

Calibration Check Date: 4/6/07

Calibration Check

RANGE	LEVEL	RPD
C5-C8 Aliphatics	0.399 mg/l	0.1 %
C9-C12 Aliphatics	0.397 mg/l	0.4 %
C9-C10 Aromatics	0.390 mg/l	1.2 %

MDL = Method Detection Limit
ML = Minimum Limit
RL = Reportable Limit

RPD = Relative Percent Difference
%RSD = Percent Relative Standard Deviation
CCC = Correlation Coefficient of Curve



 **COPY**

North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

May 23, 2007

CERTIFIED MAIL CM # 7006 2760 0001 8494 1931
RETURN RECEIPT REQUESTED

Terry L. Church, Registered Agent
Church's Body Shop
P.O. Box 1528
Hickory, North Carolina 28603

Re: Recommendation for Enforcement Action
The Perfect Image
3rd Avenue Drive & 11th Street Drive
Hickory, NC
Catawba County
Risk: Unknown
Incident # 12634

Dear Mr. Church:

This letter is to notify you that this office is considering recommending enforcement action to the Director of the Division of Waste Management. The recommendation for enforcement concerns the violation(s) cited in the Notice of Violation (NOV) dated February 9, 2007 that was previously sent to you. Specifically:

Failure to submit a Limited Site Assessment Report as required by 15A NCAC 2L .0405.

If there is an explanation for the violation cited, or if you believe there are other factors that should be considered, please submit your response to me in writing **within 10 days of receipt** of this notice. Your explanation will be reviewed, and if enforcement action is still deemed appropriate, your explanation will be forwarded to the Director with the enforcement package for his consideration.

If you have any questions concerning this matter, please contact Mr. Brad Newton at 704-235-2174.

Sincerely,



Steven E. Bograd, P.G.
Regional Supervisor

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 **(828) 296-4500**

Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 **(910) 433-3300**

Mooreville (MOR) – 610 East Center Avenue, Suite 301, Mooreville, NC 28115 **(704) 663-1699**

Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 **(919) 791-4200**

Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 **(252) 946-6481**

Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 **(910) 796-7215**

Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 **(336) 771-5000**

Guilford County Environmental Health, 1203 Maple Street, Greensboro, NC 27405, **(336) 641-3771**

**U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT**
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE



Postage \$ _____
Certified Fee _____
Return Receipt Fee (Endorsement Required) _____
Restricted Delivery Fee (Endorsement Required) _____

Total Po: TERRY L CHURCH-REGISTERED AGT
CHURCH'S BODY SHOP
POST OFFICE BOX 1528
HICKORY NC 28603
bcn/nore 05/23/07 **us1**

PS Form 3800, August 2006 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

TERRY L CHURCH-REGISTERED AGT
CHURCH'S BODY SHOP
POST OFFICE BOX 1528
HICKORY NC 28603
bcn/nore 05/23/07 **us1**

COMPLETE THIS SECTION ON DELIVERY

A. Signature *Charles Beck* Agent Addressee
B. Received by (Printed Name) *Charles Beck* C. Date of Delivery _____
D. Is delivery address different from item 1? Yes No
If YES, enter delivery address below:

3. Service type Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.
4. Restricted Delivery? (Extra Fee) Yes

2. Article Number (Transfer from service label)

7006 2760 0001 8494 1931

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

UNITED STATES POSTAL SERVICE




First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

RECEIVED

• Sender: Please print your name, address, and ZIP code in this box •

MAY 29 2007

Division of Waste Management
NCDENR - UST SECTION
MOORESVILLE REGIONAL OFFICE UST Section
610 EAST CENTER AVE, SUITE 301
MOORESVILLE NC 28115



Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®. Certified Mail is not available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.
PS Form 3800, August 2006 (Reverse) PSN 7530-02-000-9047



North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

February 9, 2007

CERTIFIED MAIL CM # 7006 2760 0001 8493 1109
RETURN RECEIPT REQUESTED

Terry L. Church, Registered Agent
Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603

Re: Notice of Violation of
 15A NCAC 2L.0405
 Risk-based Assessment and Corrective Action
 for Petroleum Underground Storage Tanks

The Perfect Image
3rd Avenue Drive & 11th Street Drive, Hickory
Catawba County
Incident number: 12634
Risk Classification: Unknown

Dear Mr. Church:

Information received by this office on July 22, 1994 confirms a release or discharge from a petroleum underground storage tank (UST) system at the above-referenced location. Records indicate that you are the owner or operator of this UST system. You have failed to comply with the assessment and reporting requirements of Title 15A NCAC 2L .0405 within the timeframes specified in the attached rules.

Please report to the Mooresville Regional Office the actions taken to bring the site into compliance within **30** days from the date of this notice to avoid recommendation of civil penalties for continuing violations.


Penalties may be assessed for the violation described within this Notice of Violation. Your prompt attention to the items described herein is required. Failure to comply with the State's rules, in the manner and time specified, may result in the assessment of additional civil penalties and/or the use of other enforcement mechanisms available to the State. Each day that a violation continues may be considered a separate violation.

Because a release or discharge has been confirmed, a Licensed Geologist or a Professional Engineer, certified by the State of North Carolina, is required to prepare and certify all reports submitted to the Department in accordance with Title 15A NCAC 2L .0103(e) and 2L .0111(b).

Please note that before you sell, transfer, or request a "No Further Action" determination for a property that has not been remediated to below "unrestricted use" standards, you must file a Notice of Residual Petroleum ("Notice") with the Register of Deeds in the county where the property is located (NCGS 143B-279.9 and 143B-279.11).

If you have any questions regarding trust fund eligibility or reimbursement from the Commercial or Noncommercial Leaking Petroleum Underground Storage Tank Cleanup Funds, please contact the UST Section Trust Fund Branch at (919) 733-8486. If you have any questions regarding the actions that must be taken or the rules mentioned in this letter, please contact Mr. Brad Newton at the address or telephone number listed below.

Sincerely,



Steven E. Bograd, P.G.
Regional Supervisor
Mooresville Regional Office

Enclosures: Title 15A NCAC 2L .0405

cc: Catawba County Health Department

UST Regional Offices

- Asheville (ARO)** – 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500
- Fayetteville (FAY)** – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 (910) 433-3300
- Mooresville (MOR)** – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 (704) 663-1699
- Raleigh (RRO)** – 1628 Mail Service Center, Raleigh, NC 27699 (919) 791-4200
- Washington (WAS)** – 943 Washington Square Mall, Washington, NC 27889 (252) 946-6481
- Wilmington (WIL)** – 127 Cardinal Drive Extension, Wilmington, NC 28405 (910) 796-7215
- Winston-Salem (WS)** – 585 Waughtown Street, Winston-Salem, NC 27107 (336) 771-5000
- Guilford County Environmental Health**, 1203 Maple Street, Greensboro, NC 27405, (336) 641-3771

SENDER: COMPLETE THIS SECTION


- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

TERRY L CHURCH-REGISTERED AGT
 CHURCH'S BODY SHOP INC
 P O BOX 1528
 HICKORY NC 28603
 bcn/nov 02/09/07 ust

COMPLETE THIS SECTION ON DELIVERY

A. Signature *David Beck* Agent Addressee
 B. Received by (Printed Name) *David Beck* Date of Delivery



D. Is delivery address different from item 1? Yes No
 If YES, enter delivery address below:

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.
 4. Restricted Delivery? (Extra Fee) Yes

2. Article Number **7006 2760 0001 8493 1109**
 (Transfer from service)
 PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1540

7006 2760 0001 8493 1109

**U.S. Postal Service™
 CERTIFIED MAIL™ RECEIPT
 (Domestic Mail Only: No Insurance Coverage Provided)**

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	4.64
Total	

Postmark Here

TERRY L CHURCH-REGISTERED AGT
 CHURCH'S BODY SHOP INC
 P O BOX 1528
 HICKORY NC 28603
 bcn/nov 02/09/07 ust

PS Form 3800, August 2006 See Reverse for Instructions

12 FEB 2007 11:17

First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10


• Sender: Please print your name, address, and ZIP+4 in this box •

NC DENR - UST SECTION
MOORESVILLE REGIONAL OFFICE
610 EAST CENTER AVENUE, SUITE
301
MOORESVILLE NC 28115

RECEIVED

FEB 14 2007

NC DEPT. OF ENVIRONMENT
AND NATURAL RESOURCES
MOORESVILLE REGIONAL OFFICE



Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®.
- Certified Mail is not available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.



North Carolina Department of Environment and Natural Resources

Michael F. Easley, Governor
William G. Ross Jr., Secretary

Division of Waste Management
Underground Storage Tank Section

Dexter R. Matthews, Director

October 4, 2006

Church's Body Shop, Inc.
P.O. Box 1528
Hickory, North Carolina 28603
Attention: Terry Church

Re: Notice of Regulatory Requirements
15A NCAC 2L .0404 and 2L .0405
Risk-based Assessment and Corrective
Action for Petroleum Underground Storage
Tanks

The Perfect Image
3rd Avenue Drive & 11th Street Drive,

Hickory

Catawba County
Incident Number: 12634
Risk Classification: Pending

Dear Mr. Church:

Information received by this office on July 22, 1994 confirms a release or discharge from a petroleum underground storage tank (UST) system at the above-referenced location. Records indicate that you are the owner or operator of this UST system. Therefore, as a responsible party, you must comply with the initial response and abatement action requirements of Title 15A NCAC 2L .0404 and, if applicable, the assessment and reporting requirements of Title 15A NCAC 2L .0405, within the timeframes specified in the attached rules.

Because a release or discharge has been confirmed, a Licensed Geologist or a Professional Engineer, certified by the State of North Carolina, is required to prepare and certify all reports submitted to the Department in accordance with Title 15A NCAC 2L .0103(e) and 2L .0111(b).

Please note that before you sell, transfer, or request a "No Further Action" determination for a property that has not been remediated to below "unrestricted use" standards, you must file a Notice of Residual Petroleum ("Notice") with the Register of Deeds in the county where the property is located (NCGS 143B-279.9 and 143B-279.11).

Failure to comply with the State's rules in the manner and time specified may result in the assessment of civil penalties and/or the use of other enforcement mechanisms.

If you have any questions regarding trust fund eligibility or reimbursement from the Commercial or Noncommercial Leaking Petroleum Underground Storage Tank Cleanup Funds, please contact the UST Section Trust Fund Branch at (919) 733-8486. If you have any questions regarding the actions that must be taken or the rules mentioned in this letter, please contact me at the address or telephone number listed below.

Sincerely,



Brad C. Newton, P.G.
Hydrogeologist II
Mooresville Regional Office

Enclosures: Title 15A NCAC 2L .0404 and 2L .0405

cc: Catawba County Health Department

UST Regional Offices

Asheville (ARO) – 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500

Fayetteville (FAY) – 225 Green Street, Suite 714, Systel Building, Fayetteville, NC 28301 (910) 433-3300

Mooresville (MOR) – 610 East Center Avenue, Suite 301, Mooresville, NC 28115 (704) 663-1699

Raleigh (RRO) – 1628 Mail Service Center, Raleigh, NC 27699 (919) 791-4200

Washington (WAS) – 943 Washington Square Mall, Washington, NC 27889 (252) 946-6481

Wilmington (WIL) – 127 Cardinal Drive Extension, Wilmington, NC 28405 (910) 796-7215

Winston-Salem (WS) – 585 Waughtown Street, Winston-Salem, NC 27107 (336) 771-5000

Guilford County Environmental Health, 1203 Maple Street, Greensboro, NC 27405, (336) 641-3771

DIVISION OF WASTE MANAGEMENT
UST SECTION
MOORESVILLE REGIONAL OFFICE

FILE REVIEW NOTES

Site: The Perfect Image

Reviewed by: BCW

Location: 3rd Ave Dr. & 11th St. Dr.
Hickory, NC

Date Reviewed: 4/11/01

Incident #: 12634

USTs removed July 1995. TPH as high as
504 ppm detected.

No WSWs reported within 1500'

Several Petroleum constituents detected
above MACs, but below GCLs

Needs LSA

State of North Carolina
Department of Environment,
Health and Natural Resources
Mooreville Regional Office

James B. Hunt, Jr., Governor
Jonathan B. Howes, Secretary



DIVISION OF WATER QUALITY

July 18, 1996

Dear Underground Storage Tank Owner/Operator:

The General Assembly of North Carolina introduced legislation during the 1995 Short Session to address the continued solvency of the Leaking Petroleum Underground Storage Tank Cleanup Funds. The Underground Storage Tank (UST) Senate Bill 1317 (SB 1317) was ratified on June 21, 1996. SB 1317 requires the Department of Environment, Health, and Natural Resources (Department) to rank all UST-related contamination incidents according to the Department's revised Site Priority Ranking System which classifies sites as: A, B (highest priority), C, D or E (lower priority). Further, SB 1317 requires the Department to notify the UST owner, operator and/or other responsible party (RP), as applicable, of the ranking of their site. Please find below a statement notifying you of the priority ranking the Department has assigned to your site.

Your site has been assigned a priority ranking score of:

TERRY CHURCH
Site: THE PERFECT IMAGE (CHURCH'S BODY)
Incident #: 12634 County: CW
Rank: 070E

SB 1317 temporarily suspends the requirement to cleanup a discharge or release from a petroleum UST for lower priority sites (i.e., those ranked C, D or E). This legislation is effective July 21, 1996. Therefore, costs for site assessment or corrective actions at C, D or E sites which are incurred after July 21, 1996, will not be reimbursed from either the Commercial or

1

919 North Main Street,
Mooreville, North Carolina 28115
Voice 704-663-1699



FAX 704-663-6040
An Equal Opportunity/Affirmative Action Employer
50% recycled/10% post-consumer paper

State of North Carolina
Department of Environment,
Health and Natural Resources
Mooresville Regional Office

James B. Hunt, Jr., Governor
Jonathan B. Howes, Secretary
Linda Diane Long, Regional Manager



DIVISION OF ENVIRONMENTAL MANAGEMENT

December 14, 1994

Church's Body Shop, Inc.
Post Office Box 1528
Hickory, North Carolina 28603-1528
Attention: Terry Church

RE: Acknowledgement of Receipt
Site Characterization Report
3rd Avenue Drive, Hickory
Catawba County, N.C.

Dear Mr. Church:

We received your report on October 11, 1994. Please be advised that the submittal of this information does not relieve you of the responsibility for continued investigation and cleanup at this site. In order to avoid delays due to Mooresville Regional Office staff review time, you should proceed without further review by the Mooresville staff. Prior to initiation of remediation at the subject site, you should contact the Mooresville Office. In the meantime, the report will remain on file in this Office in the Groundwater Section's files.

Thank you for your cooperation and should you have any questions, please contact me at (704) 663-1699, ext. 240.

Sincerely,

A handwritten signature in black ink, appearing to read "Paul R. Dahlen".

Paul R. Dahlen, P.G.
Hydrogeological Technician

PRD/sc

POLLUTION INCIDENT/U.S.T. LEAK REPORTING FORM

Department of Environment, Health, Natural Resources
 Division of Environmental Management
 GROUNDWATER SECTION

Revised

Confirm. GW Contamination (Y/N) Y
 Major Soil Contamination (Y/N) _____
 Minor Soil Contamination (Y/N) _____

Incident # 12634
 Date Incident Occurred or Leak Detected 7/4/95

INCIDENT DESCRIPTION

Incident Location/Name Church's Body Shop, Inc (The Perfect Image)
 Address 3rd Ave Dr. + 11th St. Drive
 City/Town Hickory County Catawba Region MRO
 Briefly Describe Incident Release from UST's discovered during closure
BTEX = 2517 ppb Benzene = 143 ppb

POTENTIAL SOURCE OWNER-OPERATOR

Potential Source Owner-Operator Terry Church Telephone 704 396-2185
 Company Church's Body Shop Street Address P.O. Box 1528
 City Hickory County Catawba State NC Zip Code 28603-1528

OWNERSHIP
 0. N/A 1. Municipal 2. Military 3. Unknown 4. Private 5. Federal 6. County 7. State
 OPERATION TYPE
 0. N/A 1. Public Service 2. Agricultural 3. Residential 4. Educational/Relig. 5. Industrial 6. Commercial 7. Mining

POLLUTANTS INVOLVED

MATERIALS INVOLVED	AMOUNT LOST	AMOUNT RECOVERED
<u>Gasoline</u>	<u>?</u>	<u>?</u>

SOURCE OF POLLUTION

PRIMARY SOURCE OF POLLUTION (Select one)	PRIMARY POLLUTANT TYPE (Select one)	LOCATION	SETTING
1. Intentional dump	1. Pesticide/herbicide	1. <u>Facility</u>	1. Residential
2. Pit, pond, lagoon	2. Radioactive waste	2. Railroad	2. Industrial
3. <u>Leak-underground</u>	3. <u>Gasoline/diesel</u>	3. Waterway	3. <u>Urban</u>
4. Spray irrigation	4. Heating oil	4. Pipeline	4. Rural
5. Land application	5. Other petroleum prod.	5. Dumpsite	
6. Animal feedlot	6. Sewage/septage	6. Highway	
7. Source unknown	7. Fertilizers	7. Residence	
8. Septic tank	8. Sludge	8. Other	
9. Sewer line	9. Solid waste leachate		
10. Stockpile	10. Metals		
11. Landfill	11. Other inorganics		
12. Spill-surface	12. Other organics		

Site Priority Ranking _____

D.E.M. Regional Contact Paul Dahler Signature [Signature] Date 8/10/95

IMPACT ON DRINKING WATER SUPPLIES

WELLS AFFECTED

1. YES

2. NO

NUMBER OF WELLS AFFECTED _____

Well(s) Contaminated: (Users Name)

1.

2.

3.

4.

5.

Circle Appropriate Responses

Lab Samples Taken By:

1. DEM

2. DHS

3. Responsible Party

4. Other

5. None

Samples Taken Include:

1. Groundwater

2. Soil

LOCATION OF INCIDENT

7 1/2 Min. Quad Name

Hickory, NC

Lat. : Deg : Min : Sec :

35° 44' 25" N

5 Min. Quad Number

L726

Long. : Deg : Min : Sec :

81° 21' 34" W

Draw Sketch of Area or Attach Additional Maps

See Attached

ATTN: Faye Sweet

POLLUTION INCIDENT/U.S.T. LEAK REPORTING FORM

Department of Environment, Health, Natural Resources
Division of Environmental Management
GROUNDWATER SECTION

Confirm. GW Contamination (Y/N) _____
Major Soil Contamination (Y/N) _____
Minor Soil Contamination (Y/N) _____

Incident # 12634
Date Incident Occurred
or Leak Detected 7/11/94

INCIDENT DESCRIPTION

Incident Location/Name The Perfect Image
Address 3rd Ave Drive, NW
City/Town HICKORY County CATAWBA Region MKO
Briefly Describe Incident
SOIL CONTAMINATION discovered during
TANK REMOVAL

POTENTIAL SOURCE OWNER-OPERATOR

Potential Source Owner-Operator MR. Terry Church Telephone (704) 396-2185
Company _____ Street Address P.O. Box 1528
City HICKORY County CATAWBA State N.C. Zip Code 28603

OWNERSHIP
0. N/A 1. Municipal 2. Military 3. Unknown 4. Private 5. Federal 6. County 7. State
OPERATION TYPE
0. N/A 1. Public Service 2. Agricultural 3. Residential 4. Educational/Relig. 5. Industrial 6. Commercial 7. Mining

POLLUTANTS INVOLVED

MATERIALS INVOLVED	AMOUNT LOST	AMOUNT RECOVERED
<u>GASOLINE</u>	<u>UNKNOWN</u>	<u>-</u>

SOURCE OF POLLUTION

PRIMARY SOURCE OF POLLUTION (Select one)	PRIMARY POLLUTANT TYPE (Select one)	LOCATION	SETTING
1. Intentional dump	1. Pesticide/herbicide	<input checked="" type="radio"/> 1. Facility	1. Residential
2. Pit, pond, lagoon	2. Radioactive waste	2. Railroad	2. Industrial
<input checked="" type="radio"/> 3. Leak-underground	<input checked="" type="radio"/> 3. Gasoline/diesel	3. Waterway	<input checked="" type="radio"/> 3. Urban
4. Spray irrigation	4. Heating oil	4. Pipeline	4. Rural
5. Land application	5. Other petroleum prod.	5. Dumpsite	
6. Animal feedlot	6. Sewage/septage	6. Highway	
7. Source unknown	7. Fertilizers	7. Residence	
8. Septic tank	8. Sludge	8. Other	
9. Sewer line	9. Solid waste leachate		
10. Stockpile	10. Metals		
11. Landfill	11. Other inorganics		
12. Spill-surface	12. Other organics		

D.E.M. Regional Contact ROBERT KLEBS Signature [Signature] Date 8/27/94

Incident Name: Church's Body Shop Region/County: MPO / Catawba

Groundwater Incident File # _____ Ranking Performed by: _____

Date: _____

**NORTH CAROLINA
GROUNDWATER CONTAMINATION INCIDENT MANAGEMENT
SITE PRIORITY RANKING SYSTEM
(To be completed by Regional Office)**

	<u>Points Awarded</u>
I. IMMINENT HAZARD ASSESSMENT	
A. Explosion - free product in confined areas or vapor phase product detected at or above 20% of the lower explosive limit or at health concern levels; award 50 points total	_____ _____
B. Fire - free product subject to ignition in exposed areas such as surface water impoundments, streams, excavations, etc.; award 50 points total	_____ _____
II. EXPOSURE ASSESSMENT	
A. Contaminated Drinking Water Supplies	
1. Private, domestic water supply well containing substances in concentrations exceeding 15A NCAC 2L groundwater quality standards; award 10 points per well	_____ _____
2. Public or institutional water supply well containing substances in concentrations exceeding 15A NCAC 2L groundwater quality standards; award 20 points per well	_____ _____
3. Exceedances of Class WS-1 surface water quality standards as a result of groundwater discharge; award 20 points per surface water body impacted	_____ _____
4. If a water supply well identified in items II. A. 1 and II. A. 2 cannot be replaced by an existing public water supply source requiring hook-up only; award additional 10 points per irreplaceable well	_____ _____
B. Threat to Uncontaminated Drinking Water Supplies	
1. Private, domestic water supply well located within 1500 feet down gradient of contaminant source; award 10 points per well	_____ _____
2. Public or institutional water supply well located within 1500 feet downgradient of contaminant source; award 15 points per well	_____ _____
3. Raw surface water intake for public water supply located within 1/2 mile downgradient of contaminant source; award 5 points per water supply system	_____ _____
4. If any well identified in items II. B. 1 and II. B. 2 or an intake in item II. B. 3. are located within 250 feet of contaminant source; award additional 20 points total (not per well or intake)	_____ _____
C. Vapor Phase Exposure	
1. Product vapors detected in inhabitable building(s) below 20% of the lower explosive limit or health concern levels; award 30 points total	_____ _____

Points Awarded

2. Product vapors detected in other confined areas (uninhabitable buildings, sewer lines, utility vaults, etc.) below 20% of the lower explosive limit; award 10 points total

—

III. SOURCE ASSESSMENT

- A. Uncontrolled or Unabated Primary Source (including dumpsites, stockpiles, lagoons, land applications, septic tanks, landfills, underground and above ground storage tanks, etc.)

1. Suspected or confirmed source remains in active use and continues to receive raw product, wastewater or solid waste; award 30 points per source
2. Active use of suspected or confirmed source has been discontinued or source was caused by a one-time release of product or waste, however, source continues to release product or contaminants into the environment; award 10 points per source

—

10

IV. ENVIRONMENTAL VULNERABILITY ASSESSMENT

- A. Vertical Contaminant Migration - Literature or well logs indicate that no confining layer is present above bedrock or within twenty feet of land surface; award 10 points total

10

- B. Horizontal Contaminant Migration - Data or observations indicate that no discharge points or aquifer discontinuities exist between the source and the nearest downgradient drinking water supply; award 10 points total

10

- C. Existing Groundwater Quality - The worst case monitor or supply well contains contaminant levels:

1. At less than 10 times the 2L groundwater standards; award 5 points
2. Between 10 and 100 times the 2L groundwater standards; award 20 points
3. Greater than 100 times the 2L groundwater standards; award 40 points

40

V. REGIONAL OFFICE RESPONSE (LETTER RANK)

Priority A - (Site meets any one of the criteria)

1. Water supply well(s) contaminated and no alternate water supplies available.
2. Vapors present in confined areas at explosive or health concern levels.
3. Treated surface water supply in violation of the safe drinking standards.

Priority B - (Any One)

1. Water supply well(s) contaminated, but alternate water supplies available.

2. Water supply well(s) within 1500 feet of site, but not contaminated and no alternate water supplies available.
3. Vapors present in confined areas but not at explosive or health concern levels.

Priority C - (Both)

1. No water supply well(s) contaminated.
2. Water supply well(s) greater than 1500 feet from site, no alternate water supply available.

Priority D - (Both)

1. No water supply well(s) contaminated.
2. Water supply well(s) within 1500 feet of site but alternate water supplies available.

Priority E - (Both)

1. No water supply well(s) contaminated or within 1500 feet of site.
2. Area served by alternate water supply.

TOTAL POINTS AWARDED

70/E #/Letter

Rbk

State of North Carolina
Department of Environment,
Health and Natural Resources
Mooresville Regional Office



James B. Hunt, Jr., Governor
Jonathan B. Howes, Secretary
Vivian H. Burke, Regional Manager

DIVISION OF ENVIRONMENTAL MANAGEMENT

August 8, 1994

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Church's Body Shop, Inc.
Post Office Box 1528
Hickory, North Carolina 28603
Attention: Terry Church

SUBJECT: Notice of Regulatory Requirements
15A NCAC 2N Criteria and Standards
Applicable to Underground Storage Tanks

The Perfect Image
Old Lenoir Road, Hickory
Catawba County, N.C.

Dear Mr. Church:

The Division of Environmental Management administers the State's rules for underground storage tanks (USTs) and the required corrective action for petroleum releases adopted pursuant to Chapter 143 of the North Carolina General Statutes. The State's rules for USTs are located in Title 15A, Subchapter 2N of the North Carolina Administrative Code (NCAC). This letter is a standard notification and is intended to advise you of the legal requirements pertaining to a release under North Carolina law.

The tank closure report received by this Office on July 22, 1994 confirms a release from the UST system located at the subject site. Specifically, the report identifies soil contamination around two gasoline USTs. The total petroleum hydrocarbon level was reported to be as high as 504 parts per million.

As the owner of the subject UST system you are required to comply with the release response and corrective action requirements of 15A NCAC 2N. A copy of this section of the rules (.0700) is attached for your reference. Specifically you shall comply with the requirements listed below:

15A NCAC 2N .0703 Initial Abatement Measures and Site Check

The report, which was due within 20 days after release confirmation, should be completed as required in paragraph (b) of this section summarizing the applicable initial abatement steps and any resulting information or data. The report should be received within 20 days of receipt of this letter. If free product is discovered, begin free product removal within 14 days in accordance with 15A NCAC 2N .0705.

15A NCAC 2N .0704 Initial Site Characterization

The report, which was due within 45 days of release confirmation, should be completed as required in paragraph (b) of this section and submitted within 45 days of receipt of this letter. In particular, the report should include information on surrounding populations, water quality, use and approximate locations of supply wells potentially affected by the release.

15A NCAC 2N .0705 Free Product Removal

If the investigation required under 15A NCAC 2N .0703 indicates the presence of free product, submit a free product removal report as required in this section. The report, which was due within 45 days of confirming the release, should be submitted within 45 days of receipt of this letter.

15A NCAC 2N .0706 Investigation for Soil and Groundwater Cleanup

The tank closure report indicates the presence of soil contamination. As a result, you must submit the report for the site investigation for cleanup as required under this section. The report should explain your investigation for determining the vertical and horizontal extent of soil contamination in the area containing the former gasoline USTs. The report must also include an additional soil sample taken from below the 550-gallon waste oil UST. The additional sample should be submitted for analysis by EPA Method 8021 in accordance with the attached guidelines. You should also complete a Site Sensitivity Evaluation in accordance with the "Groundwater Section Guidelines for the Investigation and Remediation of Soils and Groundwater" (June, 1993). The report and evaluation are due in this Office within 45 days of receipt of this letter.

Church's Body Shop, Inc.
August 8, 1994
Page Three


Submittal of the tank closure report does not relieve you of the responsibility for continued investigation and cleanup at this site. In order to avoid delays due to Mooresville Regional Office staff review time, you should proceed without further notice or review by Mooresville staff. Prior to initiation of remediation at the subject site, you should contact the Mooresville Office.

Underground storage tank owners and operators are held jointly and severally liable for a release from an UST system. Typically, the UST owner and operator determine ultimate liability between themselves by common law principles. To date, the Division has insufficient information to identify the UST operator. You are requested to submit any information you have concerning the responsibility for the daily operation of the subject UST system.

In accordance with G.S. 143-215.6A, failure to comply with the State's rules may result in the assessment of civil penalties against you up to \$10,000 per rule violation. Each day that a violation continues may be considered a separate violation. Failure to comply with the corrective action rules may also result in the Attorney General of the State requesting an injunction in Superior Court requiring the necessary measures. Also, any willful or knowing noncompliance which allows groundwater standards to continually be exceeded could result in criminal sanctions being sought under G.S. 143-215.6B.

Should you have any questions, please call Rob Krebs at 704/663-1699, ext. 241.

Sincerely,


Brenda J. Smith, P.G.
Regional Supervisor

Enclosures: 15A NCAC 2N .0203, .0603 -.0706
Suggested Analytical Methods for Groundwater Analyses
Suggested Analytical Methods for Soil Analyses

cc: Groundwater Section - Raleigh
Catawba County Health Department

RBK/sc

Postmark or Date	
TOTAL Postage & Fees	\$
Return Receipt Showing to Whom, Date, and Addressee's Address	
Return Receipt Showing to Whom & Date Delivered	
Restricted Delivery Fee	
Special Delivery Fee	
Certified Fee	
Postage	\$
Postmark or Date	


Receipt for Certified Mail
 No Insurance Coverage Provided
 Do not use for International Mail (See Reverse)

8/8/94
 P 848 363 498

Sent to
CHURCH'S BODY SHOP INC
 ATTN: TERRY CHURCH
 PO BOX 1528
 HICKORY NC 28603

Is your RETURN ADDRESS completed on the reverse side?

<p>SENDER:</p> <ul style="list-style-type: none"> • Complete items 1 and/or 2 for additional services. • Complete items 3, and 4a & b. • Print your name and address on the reverse of this form so that we can return this card to you. • Attach this form to the front of the mailpiece, or on the back if space does not permit. • Write "Return Receipt Requested" on the mailpiece below the article number. • The Return Receipt will show to whom the article was delivered and the date delivered. 		<p>I also wish to receive the following services (for an extra fee):</p> <p>1. <input type="checkbox"/> Addressee's Address</p> <p>2. <input type="checkbox"/> Restricted Delivery</p> <p>Consult postmaster for fee.</p>
<p>3. Article Addressed to:</p> <p>CHURCH'S BODY SHOP INC ATTN: TERRY CHURCH PO BOX 1528 HICKORY NC 28603</p> <p>(NORR-THE PERFECT IMAGE)</p>	<p>4a. Article Number P 848 363 498 (8/8/94)</p>	
<p>5. Signature (Addressee)</p> <p><i>Terry Church</i></p> <p>6. Signature (Agent)</p> <p><i>Deloris T. Callaway</i></p>	<p>4b. Service Type</p> <p><input type="checkbox"/> Registered <input type="checkbox"/> Insured</p> <p><input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD</p> <p><input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise</p>	
	<p>7. Date of Delivery 8-11</p>	
	<p>8. Addressee's Address (Only if requested and fee is paid)</p>	

PS Form 3811, December 1991 *U.S. GPO: 1992-323-402

DOMESTIC RETURN RECEIPT

Thank you for using Return Receipt Service.

- STICK POSTAGE STAMPS TO ARTICLE TO COVER FIRST CLASS POSTAGE, CERTIFIED MAIL FEE, AND CHARGES FOR ANY SELECTED OPTIONAL SERVICES (see front).**
1. If you want this receipt postmarked, stick the gummed stub to the right of the return address leaving the receipt attached and present the article at a post office service window or hand it to your rural carrier (no extra charge).
 2. If you do not want this receipt postmarked, stick the gummed stub to the right of the return address of the article, date, detach and retain the receipt, and mail the article.
 3. If you want a return receipt, write the certified mail number and your name and address on a return receipt card, Form 3811, and attach it to the front of the article by means of the gummed ends if space permits. Otherwise, affix to back of article. Endorse front of article **RETURN RECEIPT REQUESTED** adjacent to the number.
 4. If you want delivery restricted to the addressee, or to an authorized agent of the addressee, endorse **RESTRICTED DELIVERY** on the front of the article.
 5. Enter fees for the services requested in the appropriate spaces on the front of this receipt. If return receipt is requested, check the applicable blocks in item 1 of Form 3811.
 6. Save this receipt and present it if you make inquiry.

102595-93-B-0290

UNITED STATES POSTAL SERVICE

Official Business



PENALTY FOR PRIVATE USE TO AVOID PAYMENT OF POSTAGE, \$300

AUG 12 1994



DIVISION OF ENVIRONMENTAL MANAGEMENT
MOORESVILLE REGIONAL OFFICE

Print your name, address and ZIP Code here

DEHNK - GROUNDWATER SECTION (RBK)
919 N MAIN ST
MOORESVILLE NC 28115

NR
ANKS
IN
NC

Return Completed Form To: *ATTN: Annette PARKER*
The appropriate DEM Regional Office according to the county of the facility's location.
[SEE MAP ON REVERSE SIDE OF OWNER'S COPY (PINK) FOR REGIONAL OFFICE ADDRESS].

State Use Only
I.D. Number _____
Date Received _____

INSTRUCTIONS

Complete and return within (30) days following completion of site investigation.

I. Ownership of Tank(s)

Owner Name: *Church's Body Shop, Inc.*
Corporation, Individual, Public Agency, or Other Entity
Street Address: *P.O. Box 1528*
County: *Catawba*
City: *Hickory* State: *NC* Zip Code: *28603*
Telephone Number: *(704) 396-2185*
(Area Code)

II. Location of Tank(s)

Facility Name: *The Perfect Image*
(or Company)
Facility ID # (if available):
Street Address: *Old Lewis Road*
(or State Road)
County: *Catawba* City: *Hickory* Zip Code: *28601*
Telephone Number: *(704) 328-6552*
(Area Code)

III. Contact Person

Name: *Terry Church* Job Title: *Owner* Tel. No.: *704-396-2185*
Closure Contractor: *Certi Foam Services* Address: *P.O. Box 5524, W-5, NC 27113* Tel. No.: *910-661-9231*
Primary Consultant: *Andrew Raring* Address: *Same* Tel. No.: *910-661-9249*
Lab: *Blue Ridge Labs* Address: *P.O. Box 2998, Lewis NC 28645* Tel. No.: *704-728-0149*

IV. U.S.T. Information

V. Excavation Condition

VI. Additional Information Required

Tank No.	Size in Gallons	Tank Dimensions	Last Contents	Water in Excavation		Free Product		Notable Odor or Visible Soil Contamination	
				Yes	No	Yes	No	Yes	No
8	280	36" x 60"	gasoline		X		X		X

See reverse side of pink copy (owner's copy) for additional information required by N.C. - DEM in the written report and sketch.

NOTE: The site assessment portion of the tank closure must be conducted under the supervision of a Professional Engineer or Licensed Geologist. After Jan. 1, 1994, all closure site assessment reports must be signed and sealed by a P.E. or L.G.

VII. Check List (Check the activities completed)

PERMANENT CLOSURE (For Removing or Abandoning-in-place)

- Contact local fire marshal.
 - Notify DEM Regional Office before abandonment.
 - Drain & flush piping into tank.
 - Remove all product and residuals from tank.
 - Excavate down to tank.
 - Clean and inspect tank.
 - Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures.
 - Cap or plug all lines except the vent and fill lines.
 - Purge tank of all product & flammable vapors.
 - Cut one or more large holes in the tanks.
 - Backfill the area.
- Date Tank(s) Permanently closed: *July 11th & 12th 1994*
Date of Change-in-Service: _____

ABANDONMENT IN PLACE (8)

- Fill tank until material overflows tank opening.
- Plug or cap all openings.
- Disconnect and cap or remove vent line. *Nitrogen*
- Solid inert material used - specify: *Resin Foam*

REMOVAL

- Create vent hole.
 - Label tank.
 - Dispose of tank in approved manner.
- Final tank destination: _____

VIII. Certification (Read and Sign)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Print name and official title of owner or owner's authorized representative <i>Harvey Danner, Pres; Certi Foam Services</i>	Signature <i>Harvey Danner</i>	Date Signed <i>July 21st, 1994</i>
--	-----------------------------------	---------------------------------------

DATE RECEIVED _____	STATE USE ONLY	I.D. NUMBER _____
I. OWNERSHIP OF TANK(S)		II. LOCATION OF TANK(S)
Owner Name (Corporation, Individual, Public Agency, or Other Entity) <u>Church's Body Shop, Inc.</u> Street Address <u>P.O. Box 1528</u> <u>Catawba</u> County <u>Hickory NC 28603</u> City State Zip Code <u>704-396-2185</u> Area Code Phone Number		(If same as Section 1, mark box here <input type="checkbox"/>) <u>The Perfect Image</u> Facility Name or Company Site Identifier <u>Old Lenoir Road</u> Street Address or State Road <u>Catawba</u> County <u>Hickory 28601</u> City (nearest) Zip Code

Type of Owner (mark all that apply)

<input checked="" type="checkbox"/> Current	<input type="checkbox"/> State or Local Gov't	<input checked="" type="checkbox"/> Private or Corporate Ownership
<input type="checkbox"/> Former	<input type="checkbox"/> Federal Gov't (GSA facility I.D. no. _____)	<input checked="" type="checkbox"/> Uncertain

Facility I.D. # if assigned _____

Indicate number of regulated tanks at this location

Indicate number of all tanks at this location

Mark box here if tank(s) are located on land within an Indian reservation or on other Indian trust lands

III. CONTACT PERSON FOR TANK LOCATION

Terry Church Owner 704-396-2185
 Name Job Title Area Code Phone Number

IV. TYPE OF NOTIFICATION (Mark "X" for all that apply)

<input type="checkbox"/> EXISTING UST	<input type="checkbox"/> NEW UST	<input type="checkbox"/> LEAK DETECTION (LD) Certification
<input type="checkbox"/> UST UPGRADE	<input type="checkbox"/> Change of Ownership	<input checked="" type="checkbox"/> AMENDMENT of a previous notification for these USTs at this facility

"Existing" UST - an UST system installed on or before December 22, 1988.
 "New" UST - an UST system installed after December 22, 1988.
 "LD Certification" - notification of compliance with leak detection requirements.
 UST "Upgrade" - addition of corrosion protection and spill/overflow prevention equipment.

V. DESCRIPTION OF ALL USTs AT THIS FACILITY

Tank Identification No. e.g., A, B, C, or 1,2,3,	Tank No. <u>6</u>	Tank No. <u>8</u>	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
1. Date of Installation	<u>Unknown</u>	<u>Unknown</u>				
2. Total Capacity (Gallons)	<u>280</u>	<u>280</u>				
3. Materials of Construction choose all that apply	A. FRP (fiberglass reinf. plast.)		B. Steel (with dielectric coating)		C. Steel/FRP Composite	
	O. Other (specify) <u>8</u>		U. Unknown			
	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
	Tank Piping	Tank Piping	Tank Piping	Tank Piping	Tank Piping	Tank Piping
Use Codes listed above	<u>B</u>	<u>B</u>				

4. Certification of Installation (Refer to North Carolina Administrative Code, Title 15A, Subchapter 2N, Section .0301) [use all codes that apply]

A. The installer has been certified by the tank and piping manufacturers.	C. Installation inspected and certified by a registered professional engineer.	E. Manufacturer's installation work check-lists has been completed.
Tank No. <u>6</u>	Tank No. <u>8</u>	Tank No. _____
Use Installation Codes (A, B, or C)	<u>Unknown</u>	
Date Install. Completed	<u>Unknown</u>	

OATH: I certify that the information concerning installation provided in Part V. Item 4 (above) is true to the best of my belief and knowledge.

Installer:

 Print Name Job Title

 Company Name Company Address

 Signature Date

5. Piping System	P. Pressurized System				S. Suction System		G. Gravity Feed System	
	Tank No. <u>6</u>	Tank No. <u>8</u>	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
Use Piping system codes	<u>S</u>	<u>S</u>						

6. Leak Detection [LD] (use any code or combination of codes that apply) [Refer to 15A NCAC 2N .0504 & .0505]
- | | | |
|--|--|--|
| A. Periodic tank tightness testing "TTT" | F. Interstitial monitoring-double walled tank/piping | J. Manual tank gauging |
| B. Inventory Control* | G. Interstitial monitoring-secondary barrier | K. Statistical Inventory Reconciliation "SIR" |
| C. Automatic tank gauging "ATG" | H. Automatic line leak detectors "LLD" | O. Other method allowed by State Agency. Must specify. |
| D. Vapor monitoring | I. Line tightness testing "LTT" | N. None |
| E. Groundwater monitoring | | X. Exempt under 280.41(b)(2) (i)-(v) [piping only] |

* Options A, B, and C are not stand-alone methods and may only be used in one of the following combinations: A and B or C and B.

Use LD Codes	Tank No. <u>6</u>		Tank No. <u>8</u>		Tank No. _____		Tank No. _____		Tank No. _____		Tank No. _____	
	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
Use LD Codes	<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>								
Date LD initiated	<u>-</u>		<u>-</u>									

7. Upgrade (use any code or combination of codes that apply) [Refer to 15A NCAC 2N .0402]

Corrosion Protection

A. Sacrificial Anode	C. FRP Tank/Piping	E. Steel/FRP composite	N. None
B. Impressed Current	D. Dielectric coating	F. Internal lining	U. Unknown

Use Corrosion Protection Codes (above)	Tank No. <u>6</u>		Tank No. <u>8</u>		Tank No. _____		Tank No. _____		Tank No. _____		Tank No. _____	
	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
Use Corrosion Protection Codes (above)	<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>								
Date Installed	<u>-</u>		<u>-</u>									

Spill and Overfill

A. Catchment Basin	B. Automatic Shutoff Device	C. Overfill Alarm	D. Ball Float Valve	N. None
--------------------	-----------------------------	-------------------	---------------------	---------

Use Spill/Overfill Codes	Tank No. <u>6</u>		Tank No. <u>8</u>		Tank No. _____		Tank No. _____		Tank No. _____	
	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
Use Spill/Overfill Codes	<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>						
Date Installed	<u>-</u>		<u>-</u>							

8. Substances Last, Currently, or to be stored in Greatest Quantity by Volume (mark all that apply)

	Tank No. <u>6</u>	Tank No. <u>8</u>	Tank No. _____	Tank No. _____	Tank No. _____	Tank No. _____
a. Petroleum (Specify: Unleaded Reg., Unleaded Plus, Diesel, K-1, Used Oil, etc.)	<u>gasoline</u>	<u>gasoline</u>				
b. Hazardous Substance Please Indicate Name of Principal CERCLA Substance OR Chemical Abstract Service (CAS) No.						
c. Other (specify)						

VI. FINANCIAL RESPONSIBILITY

I have financial responsibility in accordance with 15A NCAC 2Q.
 Mark "x" here if financial responsibility compliance date is deferred by 15A NCAC 2Q Section .0202.

Method: Self Insured

Insurer: _____

Policy Number: _____

VII. CERTIFICATION (Read and Sign After Completing Section I Thru VI)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Harvey Decker, Pres. Certificate Services, Inc.
 Name and official title of owner or owner's authorized representative

Harvey Decker
 Signature

July 28th, 1994
 Date Signed

Notice of Intent: UST Permanent Closure or Change-In-Service

**FOR
TANKS
IN
NC**

Return Completed Form To:
The appropriate DEM Regional Office according to the county of the facility's location. [SEE REVERSE SIDE OF OWNER'S COPY (BLUE) FOR REGIONAL OFFICE ADDRESS].

State Use Only

I. D. Number

Date Received

JUN 15 1994

INSTRUCTIONS

Complete and return thirty (30) days prior to closure or change-in-service.

DIVISION OF ENVIRONMENTAL MANAGEMENT
MOORESVILLE REGIONAL OFFICE

I. OWNERSHIP OF TANK(S)

Tank Owner Name: Church's Body Shop, Inc.
(Corporation, Individual, Public Agency, or Other Entity)
Street Address: P.O. Box 1528
County: Catawba
City: Hickory State: NC Zip Code: 28603
Tele. No. (Area Code): 704-396-2185

II. LOCATION OF TANK(S)

Facility Name or Company: Same
Facility ID # (if available): none
Street Address or State Road: Old Lewis Road
County: Catawba City: Hickory Zip Code: 28603
Tele. No. (Area Code): ---

III. CONTACT PERSON

Name: Terry Church Job Title: Owner Telephone Number: (704) 396-2185

IV. TANK REMOVAL, CLOSURE IN PLACE, CHANGE-IN-SERVICE

1. Contact Local Fire Marshall.
2. Plan the entire closure event.
3. Conduct Site Soil Assessments.
4. If Removing Tanks or Closing in Place refer to API Publications. 2015 "Cleaning Petroleum Storage Tanks" & 1604 "Removal & Disposal of Used Underground Petroleum Storage Tanks".
5. Provide a sketch locating piping, tanks and soil sampling locations.
6. Fill out form GW/UST-2 "Site Investigation Report for Permanent Closure" and return within 30 days following the site investigation.
7. Keep records for 3 years.

V. WORK TO BE PERFORMED BY:

(Contractor) Name: Certifoam Services, Inc.
Address: PO Box 5529, Winston Salem, N.C. State: NC Zip Code: 27113
Contact: Harvey Danner, Pres. Phone: 910-661-9231

VI. TANK(S) SCHEDULED FOR CLOSURE OR CHANGE-IN-SERVICE

TANK ID#	TANK CAPACITY	LAST CONTENTS	PROPOSED ACTIVITY		
			CLOSURE		CHANGE-IN-SERVICE
			Removal	Abandonment In Place	New Contents Stored
<u>1</u>	<u>1000</u>	<u>Diesel</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<u>2</u>	<u>3000</u>	<u>Gasoline</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<u>3</u>	<u>3000</u>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<u>4</u>	<u>2000</u>	<u>"</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
<u>5</u>	<u>550</u>	<u>Waste Oil.</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	
			<input type="checkbox"/>	<input type="checkbox"/>	

VII. OWNER OR OWNER'S AUTHORIZED REPRESENTATIVE

Print name and official title
Harvey Danner, Pres.
Signature: [Signature]

*Scheduled Removal Date: July 11th 1994
Date Submitted: June 9th 1994

*If scheduled work date changes, notify your appropriate DEM Regional Office 48 hours prior to originally scheduled date.