

**SOLID WASTE MANAGEMENT FACILITY
FIRE OCCURRENCE NOTIFICATION**
NC DENR Division of Waste Management
Solid Waste Section



26-10

Notify the Section verbally within 24 hours and submit written notification within 15 days of the occurrence.
(If additional space is needed, use back of this form)

NAME OF FACILITY: Wilkes Rd T+P Facility PERMIT # "26-10"
DATE AND TIME OF FIRE: 11 / 17 / 2010 @ 5:45 (AM) / PM (circle one)
HOW WAS THE FIRE REPORTED AND BY WHOM: 9-1-1 dispatch notified Robert Howard, Director of SWM
LIST ACTIONS TAKEN: Fire department arrived, machines were extinguished, mess was cleaned up

WHAT WAS THE CAUSE OF THE FIRE: unknown; dust being blown around from storm last night may have settled on engine that had been running all day; smoldered throughout the night + finally caught fire affecting a powerscreen + tub grinder.

DESCRIBE AREA, TYPE, AND AMOUNT OF WASTE INVOLVED: Wilkes Rd T+P facility; in addition to machines, about 3cy of screened mulch caught fire around machine

WHAT COULD HAVE BEEN DONE TO PREVENT THIS FIRE: nothing really, it was an act of nature. Machines are blown off at end of day, debris is removed from around machines daily.

CURRENT STATUS OF FIRE: out at 6:30am; mulch that burned was placed in a roll-off box, flooded with water, then covered with dirt.

DESCRIBE PLAN OF ACTIONS TO PREVENT FUTURE INCIDENTS: continue current daily routine of cleaning machines and area

NAME: Robert J. Howard TITLE: Director, Solid Waste DATE: 11/17/10

THIS SECTION TO BE COMPLETED BY SOLID WASTE SECTION REGIONAL STAFF

DATE RECEIVED 11-17-10

List any factors not listed that might have contributed to the fire or that might prevent occurrence of future fires:

FOLLOW-UP REQUIRED:
 NO PHONE CALL SUBMITTAL MEETING RETURN VISIT BY: DA 11-17-10 (DATE)
 ACTIONS TAKEN OR REQUIRED:
Fire isolated to equipment, small amount of mulch under equipment. Extinguished back in operation.