

**I N T E R**

**O F F I C E**

Fac/Perm/Co ID # 3412	Date 7 1 22 1996	Doc ID# DIN 10009
--------------------------	---------------------	----------------------


# MEMO

**To:** Jim Bateson  
**From:** Matthew Gantt  
**Subject:** Inspection of Winston-Salem C&D Land  
**Date:** May 10, 1996

Post-It® Fax Note	7671	Date	5-10	# of pages	2
To	J. BATESON	From	M. GANTT		
Co./Dept	RALEIGH-SWS	Co.	WSRO		
Phone #	733-0692	Phone #	771-4600		
Fax #	733-4810	Fax #	771-4631		

An inspection of the above-referenced facility was made by Brent Rockett and I, along with Ron Bell and Mylinda Jacobsen of the City of Winston-Salem, on May 10, 1996. The following observations were made:

1. The area of soft soil south of sediment basin #1 was observed. The spring in this area identified by the City was not flowing at the time of inspection. Ron Bell said he thought this area was an old drainageway filled in over time with silt deposits from agricultural activity. As shown in the attached map, the spring is well within the footprint of proposed cell 1-A. Mr. Bell also said he did not anticipate any problems achieving a 4' separation in this area. I informed Mr. Bell he needed to contact Joe Reading with HDR about this situation and that I would inform you also so that we can reach a conclusion about this problem. This needs to be addressed in the Certification by HDR.



Jim Bateson  
Page 2  
May 10, 1996

2. Monitoring well MW-3 could not be found in the stockpile area. Apparently, the placement of stockpile material has covered this well. This also needs to be addressed by HDR.
3. The signage for the facility has not yet been provided. Mr. Bell said this would be done before the facility opened.
4. Sediment and erosion control for the site appeared to be adequate. The access road has recently been seeded with sparse vegetation emerging in some areas.
5. No scales or support facilities have been installed. Do scales need to be in place before the facility opens ?

I would like to discuss this with you Monday, May 13. By this time I believe HDR should have been contacted and they can begin working on getting us something to review.

If you have any questions, please contact me at your earliest convenience.