



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

NUNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Rutherford PERMIT NO.: SLAS-81-05 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 6/04/14

Date of Last Inspection: 8/27/13

FACILITY NAME AND ADDRESS:

Harris Septic Tank
 1356 Race Path Church Road
 Mooresboro, NC 28114

GPS COORDINATES: N: 35.28833° E: -81.75159° (Per Acme Mapper)

FACILITY CONTACT NAME AND PHONE NUMBER:

Thomas Harris
 Cell: (828) 452-0548

FACILITY CONTACT ADDRESS:

1356 Race Path Church Road
 Mooresboro, NC 28114

AUDIT PARTICIPANTS:

Bill Wagner, Environmental Senior Specialist – Solid Waste Section
 Jane Whisnant, Harris Septic Tank (828) 305-0784

STATUS OF PERMIT:

Current - Issued: July 22, 2011 Expires: June 22, 2016

PURPOSE OF SITE VISIT:

Semi-annual inspection

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

NONE.

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2



Figure 1: 81-05 Septage Land Application Site - Harris Septage
1356 Race Path Church Road, Mooresboro, Rutherford Co.

AREAS OF CONCERN:

None.

ADDITIONAL COMMENTS

1. The four septage land application fields are currently “inactive”.
1. The four septage fields have not been used since sometime in 2004.
2. All septage from the *Harris Septic Tank* business is taken to the Cliffside Waste Water Treatment Plant at 136 Hawkins Loop Road, Cliffside, NC.
3. The access road to the application fields was well maintained.
4. The limits of the waste application areas are not clearly marked with stakes.
5. It appears that the approved setbacks are being maintained. (i.e. distances from wells, homes, etc.)
6. There was no evidence of any application of septage on any of the four application fields.
7. There were no objectionable odors detected during the inspection.
8. The cover crop on all four fields is well established with no bare areas and. All four fields have recently been cut.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section



1. Looking (W) from the edge of Race Path Church Rd., at the entrance to the Offices of *Harris Septic Tank*.



2. Looking across land application field # B2.



3. Looking across land application field # A2.



4. Looking (S) down the (W) edge of land application field # A1.

Please contact me if you have any questions or concerns regarding this inspection report.


 Bill Wagner
 Environmental Senior Specialist
Regional Representative

Phone: 828-296-4705

Sent on: 6/06/14		Email		Hand Delivery	X	US Mail		Certified No. _____
------------------	--	-------	--	---------------	---	---------	--	---------------------

ec: Tony Gallagher, Solid Waste Section – Composting and Land Application Branch Head
 Jason Watkins, Solid Waste Section – Western District Supervisor
 Connie Wylie, Composting and Land Application Branch
 Liz Patterson, Composting and Land Application Branch