



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Alexander PERMIT NO.: SLAS-02-04 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: August 13, 2013

Date of Last Inspection: October 25, 2012

FACILITY NAME AND ADDRESS:

Taylorsville Precast Molds, Inc.
 Henry Road
 Taylorsville, NC 28681

GPS COORDINATES: N: 35.88222 W: 81.12165

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: David R. Mecimore
 Telephone: (828) 632-4608
 Email address:

FACILITY CONTACT ADDRESS:

128 Taylorsville Mfg. Road
 Taylorsville, North Carolina 28681

PARTICIPANTS:

Charles Gerstell, NCDENR-Solid Waste Section

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine Inspection

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Proper signage was provided at the entrance to the facility. A second sign was provided on the east side of the property adjacent to Henry Road.
2. The access road leading to the site was off all-weather construction.
3. Permit Condition #2 requires that the fescue be cut as hay and baled whenever it reaches approximately 12 inches in height, or roughly every 4 to 6 weeks beginning in June. However, cover was greater than 12-inches in height at the time of inspection preventing a thorough inspection.
 - During a telephone conversation on August 21, 2013, Mr. Mecimore stated that the field had not been harvested as a result of unusually wet conditions. He stated that they had received approximately 61-inches of rain for the year. He explained that the field would be cut as soon as conditions were dry enough to allow for harvesting of the fescue.
 - Mr. Mecimore also explained that they would no longer apply septage until after the fescue has been harvested.
4. The disposal boundaries were marked with white PVC pipes located at each corner of the application field. However, markers were obstructed by tall grass at the time of inspection. Vegetation around the markers needs to remain cut back to prevent the markers from being obstructed from view.
5. Inspection for conditions of rutting could not be made due to the height of fescue on site.
6. No evidence of runoff beyond the approved area was observed.
7. Multiple pieces of waste paper were observed adjacent to the fence of the field located on the opposite side of the access road west of the concrete detention tanks. One piece of paper was identified as a feminine product wrapper. All waste in this area must be picked up and properly disposed. During the phone conversation on August 21st, Mr. Mecimore stated that this waste would be removed.
8. No objectionable odors were observed during the inspection.
9. It appeared that all setbacks were being maintained.

Please contact me if you have any questions or concerns regarding this inspection report.

Charles T. Gerstell

Phone: (704) 235-2144

Charles T. Gerstell
 Environmental Senior Specialist
Regional Representative

Sent on: <u>8/22/13</u>		Email		Hand delivery	X	US Mail		Certified No. []
-------------------------	--	-------	--	---------------	----------	---------	--	-------------------

Copies: Jason Watkins, Western District Supervisor
 Tony Gallagher, Composting & Land Application Brach Head
 Elizabeth Patterson, Environmental Technician, Composting & Land Application Branch