



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Catawba PERMIT NO.: SLAS-18-02 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 01-27-12 **Date of Last Inspection:** _____

FACILITY NAME AND ADDRESS:

James C. Asbury
Asbury's Septic Tank Cleaning Service Inc.
1651 Conley Road
Morganton, NC 28655

GPS COORDINATES:

N: 35.61639

W: -81.49889

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *James C. Asbury*
Telephone: *828-584-1126*
Email address:
Fax: *828-584-7337*

FACILITY CONTACT ADDRESS:

PO Box 3758 – Morganton, NC 28680

PARTICIPANTS: *Chester Cobb and Tony Gallagher*

STATUS OF PERMIT: *Inactive*

EXPIRES: *01-01-12*

PURPOSE OF SITE VISIT: *Facility Closure*

STATUS OF PAST NOTED VIOLATIONS:

No vioalctions on the previous inspection.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

Inspection conducted to close out facility permit. Inspected two fields, one off of Maple Grove Ave. and the other field was off of Prysock Ave. Both fields were still established in fescue. Some weeds present in fields. No indications of any recent applications. Septage land application signage still present at the entrances to the sites. Signage can be taken down. No issues noticed with the two fields.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283

Chester R. Cobb
Chester R. Cobb
Regional Representative

Sent on: 8-8-12		Email		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. []
-----------------	--	-------	--	---------------	-------------------------------------	---------	--	-------------------