



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Gaston PERMIT NO.: SLAS 36-04 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

Date of Site Inspection: 12/17/2013

Date of Last Inspection: 10/15/2013

FACILITY NAME AND ADDRESS:

Stanley Environmental Solutions Inc.
 131 Mariposa Road
 Stanley, NC 28164

GPS COORDINATES: N: 35.36067 W: -81.16873

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Jim Lanier
 Telephone: (704) 263-8186
 Email address: jim@stanleyenviro.com
 Fax: N/A

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie, Jim Lanier

STATUS OF PERMIT:

Active- permit expired/under review

PURPOSE OF SITE VISIT:

Repermit

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Inspected disposal fields with Jim Lanier. Field markers appear adequate in regards to site map, however **please fix markers at slight curve on field 2 (southeast side) and also at the far north corner of field 1 (current marker is within the trees)**. Discussed these two areas with Mr. Lanier.
2. The approved setbacks appear to be met, however no setbacks were measured at this time.
3. The fescue cropstand appears sufficient for land application. Recent rains & site was very wet so entire fields were not driven on during this visit.
4. The required signs are posted and the access road is adequate.
5. No odors noted except from compost area.
6. No sign of land application outside permitted boundaries & no signs of heavy application.
7. When the treatment facility is relocated across the access road on field 2, then field 2 will need to be re-GPS'd for the reduced disposal area.
8. Thank you for your time.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------