



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Halifax PERMIT NO.: SLAS-42-08 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 11/15/2011 **Date of Last Inspection:**

FACILITY NAME AND ADDRESS:

*Peter J. Minks and Lark Renee Phillips
 Chantilly Septic Tank Service
 25140 NC Hwy 125
 Scotland Neck, NC 27874*

GPS COORDINATES:

N: 36.35933

W: -77.64027

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Peter J. Minks Jr.*
Telephone: *252-536-3996*
Email address: *larked@yadoo.com*
Fax:

FACILITY CONTACT ADDRESS:

Same as above.

PARTICIPANTS: *Chester Cobb, Peter Minks, and Lark Phillips*

STATUS OF PERMIT: *New*

EXPIRES: *1/6/2013*

PURPOSE OF SITE VISIT: *Initial*

STATUS OF PAST NOTED VIOLATIONS:

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage needs to be replace at the corner of Field 3. Signage present along the path at the entrance from SR 1600.
2. Access road off of Hwy 903 was in good shape.
3. All markers were present.
4. all discharges appeared to be within the permitted boundaries of the site.
5. No spot dumps noticed. Need to watch applications. Do not what the septage to be so thick that it mats the grass down.
6. The small grain need to be planted. Broadleaf weed control needed in all the fields. The Buckhorn Plaintiff is about to take over sections of the fields.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed.
9. No change noticed with any of the setbacks.
10. Records not checked.
11. I collected soil samples from the three fields. Field 4 is considered inactive therefore no sample taken from this field. Received check for the samples to be analyzed by NCDA.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Chester R. Cobb

Regional Representative

Phone: (919) 707-8283

Sent on: <i>8/6/12</i>		Email		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. []
------------------------	--	-------	--	---------------	-------------------------------------	---------	--	-------------------