



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Lincoln PERMIT NO.: SLAS-55-01 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 2/17/14

Date of Last Inspection: 8/28/13

FACILITY NAME AND ADDRESS:

Dennis Hoyle Services
 7337 Reeps Grove Church Rd.
 Vale, NC 28168

GPS COORDINATES: N: 35.5330° E: -81.42381°

FACILITY CONTACT NAME AND PHONE NUMBER:

Dennis Hoyle
 Office: (704) 276-2080
 Cell: (980) 429-0438

FACILITY CONTACT ADDRESS:

P.O. Box 84
 Vale, NC 28168

AUDIT PARTICIPANTS:

Bill Wagner, Environmental Senior Specialist – Solid Waste Section

STATUS OF PERMIT:

Current – Issued March 31, 2011 Expires March 2, 2016

PURPOSE OF SITE VISIT:

Comprehensive Site Inspection

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

None.

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3



Figure 1: Septage Land Application Site (SLAS) 55-01

COMMENTS

1. The access road to the application fields was well maintained.
2. Proper signage was displayed at the entrance to the site.
3. Approved setbacks are being maintained. (i.e. distances from wells, homes, property lines etc.)
4. Stakes used to mark the limits of the waste application areas were in place. (Photo #2)
5. There was no evidence of any application of septage outside of the permitted application areas.
6. There were no objectionable odors detected during the inspection.
7. Septage appears to have been properly applied in an even manner with no evidence of any ponding or over application of waste.
8. The cover crop was well established with no bare areas.
9. The cover crop on both fields has been cut recently. (Photos #2 & #3)
10. The nutrient management plan stipulates that both fields are to be cut "*whenever it reaches 12 inches in height or just before seedhead [sic] emergence*".
11. No ponding of water or of septage was observed.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section



1. Looking (S) at the entrance to Field #1.



2. Two of the "limits of waste" markers at the (N) end of Field #1.



3. Looking (SE) across Field #1 at the entrance gate to Field #2.



4. Looking (S) from near the entrance gate, down the length of field #2.

Please contact me if you have any questions or concerns regarding this inspection report.

Bill Wagner
 Environmental Senior Specialist
 Regional Representative

Phone: 828-296-4705

Sent on: 2/18/14		Email		Hand Delivery	X	US Mail	Certified No. _____
------------------	--	-------	--	---------------	---	---------	---------------------

ec: Tony Gallagher, Compost & Land Application Branch Head
 Jason Watkins, Western District Supervisor – Solid Waste Section
 Liz Patterson, Compost & Land Application Branch