



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Randolph PERMIT NO.: SLAS 76-05 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 8/01/2013

Date of Last Inspection: 2/28/2013

FACILITY NAME AND ADDRESS:

Cheek Plumbing & Backhoe
 7748 Lanes Mill Road
 Bennett, NC 27208

GPS COORDINATES: N: 35.6250 W: -79.57194

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Randy Cheek
 Telephone: (336) 879-3764
 Email address: N/A
 Fax: (336) 879-5308

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

- Weed control needed** on field 3 & the back side of field 2. Did not receive written evaluation from agent/agronomist as requested on the audit of 2/28/2013. The cropstand on the front section of field 2 does look improved since the visit on 2/28/2013.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Recent rains, fields very wet – did not drive over entire site. Did not see any recent application.
2. The access road is adequate and the required signs are posted.
3. It appears that the approved setbacks are being met & the field markers appear adequate.
4. No odors noted.
5. **Please refer to the enclosed checklist (& take any needed actions) to ensure the site is in compliance for the once a year meeting which will be scheduled this fall. Soil samples will be taken at that time.**

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------