



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Robeson PERMIT NO.: SLAS 78-04 FILE TYPE: COMPLIANCE
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		
CDFL	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		

Date of Site Inspection: 4/17/2014

Date of Last Inspection: 10/29/2013

FACILITY NAME AND ADDRESS:

Brian's Waste Recycling, Inc.
P.O. Box 70
Lumberton, NC 28359

GPS COORDINATES: N: 34.70555 E: -79.03725

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Phillip Wallwork
Telephone: (910) 738-5311
Email address: brianswr5@aol.com
Fax: (910) 738-5563

FACILITY CONTACT ADDRESS:

1730 Rennert Road
Lumberton, NC 28360

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Expired on June 11, 2012/submittal under review

PURPOSE OF SITE VISIT:

Repermit

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Field markers appear accurate & are clearly visible.
2. The approved setbacks are being met. No sign of land application outside the permitted boundaries.
3. The required signs are posted (new sign present) & the access road is adequate.
4. No sign of heavy application or recent application and no odors noted.
5. The cropstand appears adequate at this time. The regional agronomist for your area is now Ms. Georgia Love (910) 690-0270 if you wish to contact her for a site evaluation & advice on weed control, improving the cropstand etc.

Please contact me if you have any questions or concerns regarding this inspection report.

Connie S. Wylie

Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------