



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Wilson</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		<b>PERMIT NO.: SLAS-98-07</b>
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		<b>FILE TYPE: COMPLIANCE</b>

**Date of Site Inspection:** 4/4/2012    **Date of Last Inspection:** 11/3/2011

**FACILITY NAME AND ADDRESS:**

*Myrtle Creech*  
*Creech's Septic Tank & Grease Trap Cleaning*  
*8973 Kirby Road*  
*Kenly, NC 27542*

**GPS COORDINATES:**

**N:** 35.59566

**W:** -78.07491

**FACILITY CONTACT NAME AND PHONE NUMBER:**

**Name:** *Myrtle Creech*  
**Telephone:** *252-239-0016*  
**Email address:** *tcreech23@gmail.com*  
**Fax:** *252-239-6514*

**FACILITY CONTACT ADDRESS:**

*PO Box 460 - Lucama, NC 27851*

**PARTICIPANTS:**    *Chester Cobb and Donnie Creech*

**STATUS OF PERMIT:** *Active*

**EXPIRES:**    *2/1/2016*

**PURPOSE OF SITE VISIT:** *Routine*

**STATUS OF PAST NOTED VIOLATIONS:**

No violations noted on the previous inspection.

**OBSERVED VIOLATIONS:**

NONE

*The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.*

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The required signage present at entrance to site.
2. Path to site was in excellent shape.
3. All field boundary markers were present.
4. No discharges noticed outside of the permitted boundaries.
5. No spot dumps or thick applications noticed.
6. Crops being managed as described in the nutrient management plan.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed today.
9. No change with any of the setbacks.
10. Records not checked.
11. No issues noticed with the site today.

Please contact me if you have any questions or concerns regarding this inspection report.



\_\_\_\_\_  
Chester R. Cobb

***Regional Representative***

Phone: (919) 707-8283.

Sent on: 8-6-12		Email		Hand delivery	X	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	---	---------	--	-------------------