



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY: Wilson</b> <b>PERMIT NO.: SLAS-98-11</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDF		

**Date of Site Inspection:** 4/4/2012    **Date of Last Inspection:**

**FACILITY NAME AND ADDRESS:**

*Allen Roberson  
 Roberson Septic Service  
 6049 US 301 N.  
 Elm City, NC 27822*

**GPS COORDINATES:**

**N:** 35.69186

**W:** -77.79693

**FACILITY CONTACT NAME AND PHONE NUMBER:**

**Name:** *Allen Roberson*  
**Telephone:** *252-236-5725*  
**Email address:** *allen@robersonsepticsevice.com*  
**Fax:** *252-236-3813*

**FACILITY CONTACT ADDRESS:**

*Same as above*

**PARTICIPANTS:**    *Chester Cobb and Allen Roberson*

**STATUS OF PERMIT:** *Proposed*

**EXPIRES:**    *6/25/2013*

**PURPOSE OF SITE VISIT:** *Initial*

**STATUS OF PAST NOTED VIOLATIONS:**

No violations noted on the previous visit.

**OBSERVED VIOLATIONS:**

NONE

*The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.*

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Septage Land Application signage had been moved back up the path prior to access to the first field. Signage close to the abandoned homesstead.
2. Access road was in good shape.
3. Markers had been installed where the orange flags had been placed on 1-4-12. The northeast corner marker for the first field will have to be moved because it is within 500 ft of the well.
4. Site has not been permitted yet. No septage discharges noticed.
9. Will have to move the northeast corner marker of the first field so that it will be 500 ft from the well. Orange flag placed where marker will need to be moved to.
11. Landowner said that they were thinking about doing grain sorghum and wheat instead of bermudagrass. The nutrient management plan will need to be rewritten to crop change. At a later date, I talked to Allen about adding another sign to a side entrance to the main access road from a residence. A sign will need to be placed there or the access means will need to be removed.

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb

***Regional Representative***

Phone: (919) 707-8283.

Sent on: 8-6-12		Email		Hand delivery	X	US Mail		Certified No. [ ]
-----------------	--	-------	--	---------------	---	---------	--	-------------------