



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wilson PERMIT NO.: SLAS-98-11 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 5/31/2012 **Date of Last Inspection:**

FACILITY NAME AND ADDRESS:

*Allen Roberson
 Roberson Septic Service
 6049 US 301 N.
 Elm City, NC 27822*

GPS COORDINATES:

N: 35.69186

W: -77.79693

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Allen Roberson*
Telephone: *252-236-5725*
Email address: *allen@robersonsepticsservice.com*
Fax: *252-236-3813*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb*

STATUS OF PERMIT: *Proposed*

EXPIRES: *6/25/2013*

PURPOSE OF SITE VISIT: *Pre-operational*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous visit.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The appropriate signage was up. A sign had been placed by the side entrance from the residence to the main access road.
2. Access road was in good shape. A few potholes noticed.
3. Markers up.
4. Site has not been permitted yet. No septage discharges noticed.
9. Allen said that he had moved the northeast corner marker for the first field to where I had placed the flag. All setbacks should be met now.
11. Site is ready to be permitted. I am waiting on updates to the nutrient management plan before I can do the permit. Permit was issued on 6-27-12.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283.

Chester R. Cobb

Regional Representative

Sent on: 8-6-12		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	---	---------	--	-------------------